CESCOM 20 - Projected Maintenance Due

Owner: **EXECUTIVE CESSNA TRANSPORTATION INC.**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0382**
Unit: Reg No: **N525LJ**
Airworthiness: **16-May-2012**
Print Date: **05-Nov-2026 11:14AM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/ Landings	Date	Average	Projected	Hours	Events/ Landings	Days	Months
AIRCRAFT	**2361**	**1372**	**28-Oct-2026**	**0**	**0.16**	**34.02**	**33**	**207**	**6**
ENG 1	**2361**	**1372**	**28-Oct-2026**	**0**	**0.16**	**34.02**	**33**	**207**	**6**
ENG 2	**2361**	**1372**	**28-Oct-2026**	**0**	**0.16**	**34.02**	**33**	**207**	**6**
AIR COND	**762.5**		**28-Oct-2026**	**.02**	**0.33**	**68.03**		**207**	**6**

***** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.***

Program Types

AIRCRAFT **SERIAL/REGNO:** 525B-0382 / N525LJ **MODEL:** 525B - CJ3 **MANUFACTURER:** TEXTRON AVIATION INC.

UTILIZATION: LUMP
OPERATING REGULATION: N/A
REGION OF OPERATION: N/A
OPTIONAL EQUIPMENT: DIGITAL CLOCK BATTERY

ENGINE NO. 1 **SERIAL/PART:** 141805 / 67000-200 **MODEL:** FJ44-3A/-3A-24 **MANUFACTURER:** WILLIAMS INTERNATIONAL

UTILIZATION: N/A
OPERATING REGULATION: N/A
REGION OF OPERATION: N/A
OPTIONAL EQUIPMENT: N/A

ENGINE NO. 2 **SERIAL/PART:** 141797 / 67000-200 **MODEL:** FJ44-3A/-3A-24 **MANUFACTURER:** WILLIAMS INTERNATIONAL

UTILIZATION: N/A
OPERATING REGULATION: N/A
REGION OF OPERATION: N/A
OPTIONAL EQUIPMENT: N/A

These program types are defined in the OEM manual and can differ from your other settings. These selections will impact the active OEM interval defined on the aircraft status.

As an example,

1. Your aircraft might be EASA registered but you choose to follow the OEM recommended interval for Transport Canada. In that case the operating regulation would be TCCA and can be set to EASA if OEM did not specify intervals for EASA operation.
2. Region of Operation is driven from the OEM manual and the selection between Airframe, Engine and APU can differ since the OEM manual can have requirements dependent on different regions of operation.

CESCOM 20 - Projected Maintenance Due

Owner: **EXECUTIVE CESSNA TRANSPORTATION INC.**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0382**
Unit: Reg No: **N525LJ**
Airworthiness: **16-May-2012**
Print Date: **05-Nov-2026 11:14AM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/ Landings	Date	Average	Projected	Hours	Events/ Landings	Days	Months
AIRCRAFT	**2361**	**1372**	**28-Oct-2026**	**0**	**0.16**	**34.02**	**33**	**207**	**6**
ENG 1	**2361**	**1372**	**28-Oct-2026**	**0**	**0.16**	**34.02**	**33**	**207**	**6**
ENG 2	**2361**	**1372**	**28-Oct-2026**	**0**	**0.16**	**34.02**	**33**	**207**	**6**
AIR COND	**762.5**		**28-Oct-2026**	**.02**	**0.33**	**68.03**		**207**	**6**

***** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.***

New Requirements/Action Items

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
E083-260901	WILLIAMS INTERNATIONAL FJ44-3A/-3A-24 LINE MAINTENANCE MANUAL (LMM) 68585 REV 71				MTH						
E1					MSC			-			New Req
E083-260901	WILLIAMS INTERNATIONAL FJ44-3A/-3A-24 LINE MAINTENANCE MANUAL (LMM) 68585 REV 71				MTH						
E2					MSC			-			New Req
FAA 2026-13-02	AIRPLANE FLIGHT MANUAL (AFM) REVISION				MTH						
PARA (H)					MSC			BF/F			New Req
				MANDATORY							

Overdue Maintenance Tasks

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
B351002	RESTORATION (HYDROSTATIC TEST) OXYGEN CYLINDER AND REGULATOR ASSEMBLY										
		KCRG		176276-50	MTH	08-Sep-2021		60		30-Sep-2026	-1 m 5 d
				475603004							
											Over Due
256002	ELT BEACON BATTERY PACK			452-0133	MTH	26-Jan-2022			0	31-Oct-2026	-5 d
		KCRG		391907-030	HRS	2210.8			0		
					LDG	1266			0		
					MSC			DUE			
											Over Due

Scheduled Maintenance Tasks

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
26-20-00-961	LEFT ENGINE FIRE EXTINGUISHER BOTTLES RESTORATION				MTH	30-Nov-2021		60		30-Nov-2026	25 d
26-20-00-961	RIGHT ENGINE FIRE EXTINGUISHER BOTTLES RESTORATION										
RIGHT					MTH	30-Nov-2021		60		30-Nov-2026	25 d
350006	OXYGEN CYLINDER	*CF		176276-50	MTH	18-Nov-2011		180	0	30-Nov-2026	25 d
	DOT E-10945			475603004							
D262001	LEFT ENGINE FIRE EXTINGUISHER BOTTLE RESTORATION (HYDROSTATIC TEST)										
LEFT		KCRG		30401102-2	MTH	30-Nov-2021		60		30-Nov-2026	25 d
				66800B1							
D262001	RIGHT ENGINE FIRE EXTINGUISHER BOTTLE RESTORATION (HYDROSTATIC TEST)										
RIGHT		KCRG		30401102-2	MTH	30-Nov-2021		60		30-Nov-2026	25 d
				55742B1							
25-60-03-220	ELT TRANSMITTER DETAILED INSPECTION (INTERVAL CFR 91.207)										
		KMCO		453-5060	MTH	23-Jan-2026		12		23-Jan-2027	2 m 18 d
				12292	HRS	2337.7					
					LDG	1355					
25-60-03-710	OPERATIONAL CHECK ELT TRANSMITTER EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM (INTERVAL CFR 91.207)										
		KMCO		453-5060	MTH	23-Jan-2026		12		23-Jan-2027	2 m 18 d
				12292	HRS	2337.7					
					LDG	1355					
312001A	REPLACE LEFT DIGITAL CLOCK BATTERY				MTH	31-Mar-2026	-64	12		31-Jan-2027	2 m 26 d
LEFT		KCRG		M877A5V	HRS	2338.8					
				21023	LDG	1356					
215018	REPLACE COMPRESSOR DRIVE MOTOR BRUSHES				MTH	16-May-2012					
					ACH	0		800		800	37.5
32-32-05-720	EMERGENCY PNEUMATIC STORAGE BOTTLE RESTORATION FUNCTIONAL CHECK (HYDROSTATIC TEST)										
					MTH	13-Feb-2024		36		28-Feb-2027	3 m 23 d

NOTE: Item codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference).

CESCOM 20 - Projected Maintenance Due

Owner: **EXECUTIVE CESSNA TRANSPORTATION INC.**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0382**
Unit: Reg No: **N525LJ**
Airworthiness: **16-May-2012**
Print Date: **05-Nov-2026 11:14AM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/ Landings	Date	Average	Projected	Hours	Events/ Landings	Days	Months
AIRCRAFT	**2361**	**1372**	**28-Oct-2026**	**0**	**0.16**	**34.02**	**33**	**207**	**6**
ENG 1	**2361**	**1372**	**28-Oct-2026**	**0**	**0.16**	**34.02**	**33**	**207**	**6**
ENG 2	**2361**	**1372**	**28-Oct-2026**	**0**	**0.16**	**34.02**	**33**	**207**	**6**
AIR COND	**762.5**		**28-Oct-2026**	**.02**	**0.33**	**68.03**		**207**	**6**

***** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.***

Scheduled Maintenance Tasks

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
B323101	HYDROSTATIC TEST EMERGENCY PNEUMATIC STORAGE BOTTLE										
		KCRG		40005320-2	MTH	13-Feb-2024		36		28-Feb-2027	3 m 23 d
				7649							
24-33-00-210	CAPACITY CHECK BATTERY (LEAD ACID)				MTH	31-Mar-2026		12		31-Mar-2027	4 m 26 d
		KCRG		RG-380E/44LA5	HRS	2338.8					
				41277880	LDG	1356					
25-62-00-220	DETAILED INSPECTION FIRST AID KIT				MTH	31-Mar-2026		12		31-Mar-2027	4 m 26 d
		KCRG			HRS	2338.8					
					LDG	1356					
26-20-10-720	CABIN PORTABLE FIRE EXTINGUISHER - FUNCTIONAL CHECK										
CABIN		KCRG		C352TS	MTH	31-Mar-2026		12		31-Mar-2027	4 m 26 d
				I-01810986	HRS	2338.8					
					LDG	1356					
26-20-10-720	COCKPIT PORTABLE FIRE EXTINGUISHER - FUNCTIONAL CHECK										
COCKPIT		KCRG		C352TS	MTH	31-Mar-2026		12		31-Mar-2027	4 m 26 d
				I-01810982	HRS	2338.8					
					LDG	1356					
5-12-05	INSPECTION DOCUMENT 5				MTH	31-Mar-2026		12		31-Mar-2027	4 m 26 d
		KCRG			HRS	2338.8					
					LDG	1356					
5-12-12	INSPECTION DOCUMENT 12				MTH	05-Mar-2025		24		31-Mar-2027	4 m 26 d
		KCRG			HRS	2311		600		2911	550
					LDG	1337					
B342100	CAPACITY TEST STANDBY GYRO POWER SUPPLY PS-855 (LEAD ACID)										
		KCRG		501-1712-01	MTH	31-Mar-2026		12		31-Mar-2027	4 m 26 d
				81576	HRS	2338.8					
					LDG	1356					
28-00-02-220	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATEMENT)										
		KCRG			MTH	28-Oct-2026		6		30-Apr-2027	5 m 25 d
					HRS	2361					
					LDG	1372					
34-21-00-720	PS-855 (LEAD ACID) STANDBY GYRO BATTERY PACK PERIODIC TEST										
		KCRG		501-1712-01	MTH	28-Oct-2026		6		30-Apr-2027	5 m 25 d
				81576	HRS	2361					
					LDG	1372					
5-12-40	INSPECTION DOCUMENT 40				MTH	28-Oct-2026		6		30-Apr-2027	5 m 25 d
		KCRG			HRS	2361					
					LDG	1372					
324204	BRAKE HYDRAULIC PACK ASSEMBLY FILTER ELEMENT DISCARD (REPLACE)										
		KMCO		PN	MTH	28-May-2024		36	0	28-May-2027	6 m 23 d
				SN-UNKNOWN	HRS	2279.7		1200	0	3479.7	1118.7
					LDG	1314			0		
324205	BRAKE RESERVOIR AIR FILTER AND BRAKE RESERVOIR SUPPLY LINE FILTER DISCARD (REPLACE)										
		KMCO		PN	MTH	28-May-2024		36	0	28-May-2027	6 m 23 d
				SN-UNKNOWN	HRS	2279.7		1200	0	3479.7	1118.7
					LDG	1314			0		
5-12-07	INSPECTION DOCUMENT 7 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)										
		KMCO			MTH	28-May-2024		36		31-May-2027	6 m 26 d
					HRS	2279.7					
					LDG	1314					
5-12-22	INSPECTION DOCUMENT 22				MTH	28-May-2024		36		31-May-2027	6 m 26 d
		KMCO			HRS	2279.7		1200		3479.7	1118.7
					LDG	1314					

NOTE: Item codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference).

CESCOM 20 - Projected Maintenance Due

Owner: **EXECUTIVE CESSNA TRANSPORTATION INC.**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0382**
Unit: Reg No: **N525LJ**
Airworthiness: **16-May-2012**
Print Date: **05-Nov-2026 11:14AM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/ Landings	Date	Average	Projected	Hours	Events/ Landings	Days	Months
AIRCRAFT	**2361**	**1372**	**28-Oct-2026**	**0**	**0.16**	**34.02**	**33**	**207**	**6**
ENG 1	**2361**	**1372**	**28-Oct-2026**	**0**	**0.16**	**34.02**	**33**	**207**	**6**
ENG 2	**2361**	**1372**	**28-Oct-2026**	**0**	**0.16**	**34.02**	**33**	**207**	**6**
AIR COND	**762.5**		**28-Oct-2026**	**.02**	**0.33**	**68.03**		**207**	**6**

***** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.***

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SB 525B-36-04	PNEUMATIC - BLEED AIR SYSTEM CLAMP INSPECTION, REMOVAL AND REPLACEMENT				MTH			12 MTH		26-Jun-2027	7 m 21 d
				MANDATORY	HRS			150 HRS		2513.53	152.53
SL 525B-25-12	EQUIPMENT/FURNISHINGS - SMOKE GOGGLES INSPECTION/REPLACEMENT				MTH			12 MTH		15-Sep-2027	10 m 10 d
				MANDATORY	HRS			300 HRS		2661.65	300.65
SB FJ44-79-013	OIL - OIL FILLER CAP ASSEMBLY - REPLACE				MTH						
R05					HRS					3500	1139
E1				RECOMMENDED	MSC			-			
SB FJ44-79-013	OIL - OIL FILLER CAP ASSEMBLY - REPLACE				MTH						
R05					HRS					3500	1139
E2				RECOMMENDED	MSC			-			
SB WI-73-1040 R03	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE										
E1					MTH						
					HRS					4749.7	2388.7
					MSC			DUE			
SB FJ44-72-109	ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE				HRS					5000	2639
E1				RECOMMENDED	MSC			DUE			
SB FJ44-72-109	ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE				HRS					5000	2639
E2				RECOMMENDED	MSC			DUE			
SB FJ44-72-110	ENGINE - DAMPENER BRACKET ASSEMBLY - REPLACE				HRS					5000	2639
E1					MSC			DUE			
				MANDATORY							
SB FJ44-72-110	ENGINE - DAMPENER BRACKET ASSEMBLY - REPLACE				HRS					5000	2639
E2					MSC			DUE			
				MANDATORY							
SB FJ44-72-133	REPLACE 1ST LP TURBINE NOZZLE				HRS					5000	2639
R02				RECOMMENDED	MSC			CSI			
E1											
SB FJ44-72-133	REPLACE 1ST LP TURBINE NOZZLE				HRS					5000	2639
R02				RECOMMENDED	MSC			CSI			
E2											
SB FJ44-72-140	GEARBOX HOUSING ASSEMBLY - INSPECTION				MTH						
R01					HRS					5000	2639
E1				RECOMMENDED	MSC			-			
SB FJ44-72-140	GEARBOX HOUSING ASSEMBLY - INSPECTION				MTH						
R01					HRS					5000	2639
E2				RECOMMENDED	MSC			-			
SB FJ44-79-011	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE				MTH						
R06					HRS					5000	2639
E1				MANDATORY	MSC			-			
SB FJ44-79-011	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE				MTH						
R06					HRS					5000	2639
E2				MANDATORY	MSC			-			
SB FJ44-79-012	OIL - LUBE OIL COOLER - REWORK OR REPLACE				MTH						
R01					HRS					5000	2639
E1				RECOMMENDED	MSC			DUE			
SB FJ44-79-012	OIL - LUBE OIL COOLER - REWORK OR REPLACE				MTH						
R01					HRS					5000	2639
E2				RECOMMENDED	MSC			DUE			
SB WI-73-1009 R05	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE										
E1					HRS					5000	2639
				RECOMMENDED	MSC			CSI			
SB WI-73-1009 R05	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE										
E2					HRS					5000	2639
				RECOMMENDED	MSC			CSI			

NOTE: Item codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference).

CESCOM 20 - Projected Maintenance Due

Owner: **EXECUTIVE CESSNA TRANSPORTATION INC.**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0382**
Unit: Reg No: **N525LJ**
Airworthiness: **16-May-2012**
Print Date: **05-Nov-2026 11:14AM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/ Landings	Date	Average	Projected	Hours	Events/ Landings	Days	Months
AIRCRAFT	**2361**	**1372**	**28-Oct-2026**	**0**	**0.16**	**34.02**	**33**	**207**	**6**
ENG 1	**2361**	**1372**	**28-Oct-2026**	**0**	**0.16**	**34.02**	**33**	**207**	**6**
ENG 2	**2361**	**1372**	**28-Oct-2026**	**0**	**0.16**	**34.02**	**33**	**207**	**6**
AIR COND	**762.5**		**28-Oct-2026**	**.02**	**0.33**	**68.03**		**207**	**6**

***** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.***

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SB WI-75-1001 R02	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE				MTH						
E1					HRS					5000	2639
				RECOMMENDED	MSC			-			
SB WI-75-1001 R02	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE				MTH						
E2					HRS					5000	2639
				RECOMMENDED	MSC			-			
SB WI-73-1040 R03	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE										
E2					MTH						
					HRS					5552.9	3191.9
					MSC			DUE			
SB WI-72-1034 R04	HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK				MTH						
E1					LDG			8000		8000	6628
				MANDATORY				ENC			
SB WI-72-1034 R04	HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK				MTH						
E2					LDG			8000		8000	6628
				MANDATORY				ENC			
SB 525B-24-12	ELECTRICAL POWER - JUMPER INSTALLATION IN THE COMPRESSOR ASSEMBLY										
					MTH						
				RECOMMENDED	MSC			-			
SB 525B-27-07	FLIGHT CONTROLS - ELEVATOR TRIM WHEEL INSPECTION										
					MTH						
				RECOMMENDED	MSC			-			
SL 525B-27-07 R01	FLIGHT CONTROLS - SPEED BRAKE ASSEMBLY FASTENER INSPECTION										
					MTH						
				RECOMMENDED	MSC			-			