



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
IIII1	REFURBISH INTERIOR	KCHA	MTH HRS LDG	24-Dec-2019 3537.4 2946		O/C			
PPPP1	PAINT AIRCRAFT	KCHA	MTH HRS LDG	24-Dec-2019 3537.4 2946		O/C			
E062-221212 E1	LIGHT MAINTENANCE MANUAL - FJ44-1A - REVISION 66 - DEC 12/2022		MTH			-			
E062-221212 E2	LIGHT MAINTENANCE MANUAL - FJ44-1A - REVISION 66 - DEC 12/2022		MTH			-			
E062-230330 E1	REVIEW REVIEW FJ44-1A LMM REV 67		MTH			-			
E062-230330 E2	REVIEW REVIEW FJ44-1A LMM REV 67		MTH			-			
053465	ICA - COLUMBIA AVIONICS AND AIRCRAFT SERVICES INSTRUCTIONS FOR CONTINUED AIRWORTHINESS DOCUMENT 30142991 REVISION 1 OR LATER. (STC SA01958WI)	KFCM	MTH HRS LDG	14-May-2025 4138.2 3483		12		31-May-2026	11 m 21 d
053466	ICA - COLUMBIA AVIONICS AND AIRCRAFT SERVICES INSTRUCTIONS FOR CONTINUED AIRWORTHINESS GARMIN GFC600 AUTOPILOT DOCUMENT 30143011 REVISION 1 OR LATER. (STC SA01958WI)	KFCM	MTH HRS LDG	14-May-2025 4138.2 3483		12		31-May-2026	11 m 21 d
053467	ICA - GARMIN GI 275 INSTRUCTIONS FOR CONTINUED AIRWORTHINESS CONTAINED IN GI 275 MAINTENANCE MANUAL 190-02246-11 REVISION 8 OR LATER. (STC SA02658SE)	KFCM	MTH HRS LDG	14-May-2025 4138.2 3483		12		31-May-2026	11 m 21 d
053468	ICA - GARMIN GFC 600 INSTRUCTIONS FOR CONTINUED AIRWORTHINESS, CONTAINED IN DOCUMENT 190-01938-00 REVISION 15 OR NEWER. (STC SA01844WI)	KFCM	MTH HRS LDG	14-May-2025 4138.2 3483		12		31-May-2026	11 m 21 d
055603A LEFT	INSPECT CKPT SIDE WINDOW INSP-300 HRS.	KEAU	MTH HRS LDG	09-Dec-2024 4065.8 3437		24 300		31-Dec-2026 4365.8	18 m 21 d 226.1
055603A RIGHT	INSPECT CKPT SIDE WINDOW INSP-300 HRS.	KEAU	MTH HRS LDG	09-Dec-2024 4065.8 3437		24 300		31-Dec-2026 4365.8	18 m 21 d 226.1
055715	INSPECTION ATLAS WINGLET SYSTEM - TAG 1101-0101	KEAU	MTH HRS LDG	24-Apr-2024 3975.9 3380		36		30-Apr-2027	22 m 20 d
055717	INSPECTION ACU RECALIBRATION	KSZT	MTH HRS LDG	11-May-2021 3664.5 3139		72		31-May-2027	23 m 21 d
055718	TACS RETURN SPRING REPLACEMENT	KSZT	MTH HRS LDG	11-May-2021 3664.5 3139		1000		4664.5	524.8
5-12-01 0512001B	INSPECTION DOCUMENT 01	KFCM	MTH HRS LDG	14-May-2025 4138.2 3483		300		4438.2	298.5
5-12-02 0512002	INSPECTION DOCUMENT 02	KFCM	MTH HRS LDG	14-May-2025 4138.2 3483		12		31-May-2026	11 m 21 d
B262201 COCKPIT 0512016	FUNCTIONAL (WEIGHT) CHECK PORTABLE FIRE EXTINGUISHER	KFCM	C352CS B-00099692 MTH HRS LDG	14-May-2025 4138.2 3483		12		31-May-2026	11 m 21 d

Weight Check Date: 02-May-2025

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
5-12-03 0512003	INSPECTION DOCUMENT 03	KCHA		MTH 08-May-2013 HRS 2997.9 LDG 2401		24			
5-12-04	INSPECTION DOCUMENT 04 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KEAU		MTH 05-Jun-2023 HRS LDG		36			
A323101 0512004 : GEAR	RESTORATION (HYDROSTATIC TEST) EMERGENCY GEAR BOTTLE	KEAU	9912368-2 3881	MTH 05-Jun-2023		36		30-Jun-2026	12 m 20 d
Hydro Check Date: 05-Jun-2023									
5-12-05	INSPECTION DOCUMENT 05 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KEAU		MTH 06-Jan-2025 HRS 4091.8 LDG 3455		60			
B262002 LEFT 0512005 : L	RESTORATION (HYDROSTATIC TEST) FIRE EXTINGUISHER BOTTLE	KEAU	30400031-1 44969B1	MTH 06-Jan-2025 HRS 4091.8 LDG 3455		60		30-Nov-2029	53 m 20 d
Hydro Check Date: 30-Nov-2024									
B262002 RIGHT 0512005 : R	RESTORATION (HYDROSTATIC TEST) FIRE EXTINGUISHER BOTTLE	KEAU	30400031-1 31679B1	MTH 06-Jan-2025 HRS 4091.8 LDG 3455		60		30-Nov-2029	53 m 20 d
Hydro Check Date: 30-Nov-2024									
5-12-06	INSPECTION DOCUMENT 06 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			MTH 01-Oct-2010 HRS 2768 LDG 2190		72			
A262201 COCKPIT 0512006	DETAILED INSPECTION PORTABLE FIRE EXTINGUISHER	UNK	C352CS B-00099692	MTH 25-Jan-2021		72		31-Jan-2027	19 m 21 d
Test Date: 25-Jan-2021									
5-12-07	INSPECTION DOCUMENT 07 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			MTH 01-Oct-2010 HRS LDG		144			
B262202 COCKPIT 0512007	RESTORATION (HYDROSTATIC TEST) PORTABLE FIRE EXTINGUISHER	KCHA	C352CS B-00099692	MTH 01-Jan-2016		144		31-Jan-2028	31 m 21 d
Hydro Check Date: 01-Jan-2016									
5-12-08 0512008	INSPECTION DOCUMENT 08	KEAU		MTH 24-Apr-2024 HRS 3975.9 LDG 3380		24 300		30-Apr-2026 4275.9	10 m 20 d 136.2
5-12-09	INSPECTION DOCUMENT 09 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KFCM		MTH 14-May-2025 HRS 4138.2 LDG 3483		4 200			
A243301 0512009	LEAD ACID BATTERY FUNCTIONAL CHECK (CAPACITY CHECK) NOTE: THE INSPECTION SCHEDULE MAY BE ADJUSTED AFTER THE USEFUL BATTERY LIFE IS ESTABLISHED, BASED ON OPERATIONS. TASK 24-33-00-720	KFCM	S3597-4 41219353	MTH 14-May-2025 HRS 4138.2 LDG 3483		4 200		30-Sep-2025 4338.2	3 m 20 d 198.5
5-12-10 0512010	INSPECTION DOCUMENT 10	KEAU		MTH 27-Feb-2023 HRS 3858 LDG 3263		36 1200		28-Feb-2026 5058	8 m 18 d 918.3
5-12-11 0512011	INSPECTION DOCUMENT 11	KEAU		MTH 07-Jun-2023 HRS 3912.8 LDG 3323		36 1200		30-Jun-2026 5112.8	12 m 20 d 973.1



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains	
5-12-12 0512012	INSPECTION DOCUMENT 12 (14 CFR 91.207)	KFCM		MTH HRS LDG	14-May-2025 4138.2 3483		12		31-May-2026	11 m 21 d	
5-12-13	INSPECTION DOCUMENT 13 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	7FL6		MTH HRS LDG	08-Jan-2024 3957.5 3358		24				
B341011 LEFT 0512013 : L	LEFT PITOT-STATIC SYSTEMS FUNCTIONAL CHECK (AIRPLANES -0003, -0360 AND ON AND AIRPLANES -0001 THRU -0359 INCORPORATING SB525-34-41)	7FL6		MTH	08-Jan-2024		24		31-Jan-2026	7 m 21 d	
Calibration Date: 08-Jan-2024											
B341011 RIGHT 0512013 : R	RIGHT PITOT-STATIC SYSTEMS FUNCTIONAL CHECK (AIRPLANES -0003, -0360 AND ON AND AIRPLANES -0001 THRU -0359 INCORPORATING SB525-34-41)	7FL6		MTH	08-Jan-2024		24		31-Jan-2026	7 m 21 d	
Calibration Date: 08-Jan-2024											
B345401 NO. 1 0512013 : 1	NO. 1 TRANSPONDER SYSTEM 14 CFR PART 91.413 CALIBRATION CHECK (EXCEPT PHILIPPINE REGISTERED AIRPLANES)	7FL6		011-03303-00 3EH020064	MTH		08-Jan-2024		24	31-Jan-2026	7 m 21 d
Calibration Date: 08-Jan-2024											
B345401 NO. 2 0512013 : 2	NO. 2 TRANSPONDER SYSTEM 14 CFR PART 91.413 CALIBRATION CHECK (EXCEPT PHILIPPINE REGISTERED AIRPLANES)	7FL6		011-03303-00 3EH022573	MTH		08-Jan-2024		24	31-Jan-2026	7 m 21 d
Calibration Date: 08-Jan-2024											
5-12-14	INSPECTION DOCUMENT 14 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KCHA		MTH HRS LDG	01-Aug-2018 3485.2 2898		T/C				
A324103 LEFT 0512014 : L	SPECIAL DETAIL INSPECT MAIN LANDING GEAR WHEEL (NDI)	KCHA		3-1527-2 0648	MTH HRS LDG		01-Aug-2018 3485.2 2898		T/C		
A324103 NOSE 0512014 : NOSE	SPECIAL DETAIL INSPECT LANDING GEAR WHEEL ASSY (NDI)	KCHA		3-1418 4285	MTH HRS LDG		01-Aug-2018 3485.2 2898		T/C		
A324103 RIGHT 0512014 : R	SPECIAL DETAIL INSPECT MAIN LANDING GEAR WHEEL (NDI)	KCHA		3-1527-2 0612	MTH HRS LDG		01-Aug-2018 3485.2 2898		T/C		
5-12-21 0512021	INSPECTION DOCUMENT 21	KEAU		MTH HRS LDG	06-Jan-2025 4091.8 3455		24 600		31-Jan-2027 4691.8	19 m 21 d 552.1	
5-12-22	INSPECTION DOCUMENT 22 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KCHA		MTH HRS LDG	23-Mar-2015 3217.1 2616		300				
5-12-29	INSPECTION DOCUMENT 29			MTH HRS	01-Sep-1998 0		7200		7200	3060.3	
5-12-33 0512033	INSPECTION DOCUMENT 33	KFCM		MTH HRS LDG	14-May-2025 4138.2 3483		12 300		31-May-2026 4438.2	11 m 21 d 298.5	
5-12-34 0512034	INSPECTION DOCUMENT 34 (NOT CURRENTLY USED)	CHA		MTH ACH	27-Jun-2006 1175		N/R				
5-12-35 0512035	INSPECTION DOCUMENT 35 (NOT CURRENTLY USED)	CHA		MTH ACH	27-Jun-2006 1175		N/R				



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
5-12-36	INSPECTION DOCUMENT 36	KEAU	MTH	07-Jun-2023		6			
			HRS	3912.8					
			LDG	3323					
5-12-MA 05120MA	INSPECTION DOCUMENT MA	KEAU	MTH	09-Dec-2024					
			HRS	4065.8		300		4365.8	226.1
			LDG	3437					
5-12-MC 05120MC	INSPECTION DOCUMENT MC	KCHA	MTH	15-Aug-2016					
			HRS	3361.5		1200		4561.5	421.8
			LDG	2766					
			ACH	1984.7					
5-12-MD 05120MD	INSPECTION DOCUMENT MD	*CF	MTH	01-Sep-1998					
			LDG	0		5000		5000	1514
5-12-MF 05120MF	INSPECTION DOCUMENT MF	*CF	MTH	01-Sep-1998					
			HRS	0		6000		6000	1860.3
5-12-MG 05120MG	INSPECTION DOCUMENT MG	*CF	MTH	01-Sep-1998					
			HRS	0		6000		6000	1860.3
5-12-MH 05120MH	INSPECTION DOCUMENT MH	*CF	MTH	01-Sep-1998					
			HRS	0		6000		6000	1860.3
5-12-MI 05120MI	INSPECTION DOCUMENT MI	*CF	MTH	01-Sep-1998					
			HRS	0		7200		7200	3060.3
5-12-MJ 05120MJ	INSPECTION DOCUMENT MJ	*CF	MTH	01-Sep-1998					
			HRS	0		7200		7200	3060.3
5-12-MK 05120MK	INSPECTION DOCUMENT MK	*CF	MTH	01-Sep-1998					
			HRS	0		7900		7900	3760.3
5-12-ML 05120ML	INSPECTION DOCUMENT ML	*CF	MTH	01-Sep-1998					
			HRS	0		9600		9600	5460.3
5-12-MO 05120MO	INSPECTION DOCUMENT MO	*CF	MTH	01-Sep-1998					
			HRS	0		15200		15200	11060.3
5-12-MQ	INSPECTION DOCUMENT MQ		MTH						
			HRS			14000		14000	9860.3
A551004 045503	HORIZONTAL STABILIZER FRONT UPPER SPAR CAP AT SS4.78 INSPECTION TASK 55-10-00-250	*CF	MTH	01-Sep-1998					
			HRS	0		14000		14000	9860.3
5-12-MR	INSPECTION DOCUMENT MR		MTH						
			HRS			13200		13200	9060.3
A570006 045701	LOWER MAIN SPAR SPLICE AT WS 93.00 (EDDY CURRENT) SPECIAL DETAILED INSPECTION TASK 57-00-00-250	*CF	MTH	01-Sep-1998					
			HRS	0		13200		13200	9060.3
5-12-MS	INSPECTION DOCUMENT MS		MTH						
			HRS			15000		15000	10860.3
A570007 045702	LOWER REAR SPAR SPLICE AT WS 93.00 (EDDY CURRENT) SPECIAL DETAILED INSPECTION TASK 57-00-00-251	*CF	MTH	01-Sep-1998					
			HRS	0		15000		15000	10860.3
5-12-MT	INSPECTION DOCUMENT MT		MTH						
			HRS			19200		19200	15060.3
A570008 045703	MAIN SPAR CARRY-THROUGH LOWER CAP (RWS 42.0 TO LWS 42.0) (EDDY CURRENT) SPECIAL DETAILED INSPECTION TASK 57-00-00-252	*CF	MTH	01-Sep-1998					
			HRS	0		19200		19200	15060.3
5-12-MU	INSPECTION DOCUMENT MU		MTH						
			HRS			19200		19200	15060.3
A570009 045704	REAR SPAR CARRY-THROUGH LOWER CAP (RWS 42.0 TO LWS 42.0) (EDDY CURRENT) SPECIAL DETAILED INSPECTION TASK 57-00-00-253	*CF	MTH	01-Sep-1998					
			HRS	0		19200		19200	15060.3
5-12-MV	INSPECTION DOCUMENT MV		MTH						
			HRS			22800		22800	18660.3
A570010 045705	MAIN SPAR OUTBOARD LOWER CAP (WS 120.0 TO WS 152.00) (EDDY CURRENT) SPECIAL DETAILED INSPECTION TASK 57-00-00-254	*CF	MTH	01-Sep-1998					
			HRS	0		22800		22800	18660.3



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
05-50-00-870-803-01 E1	POLISH FAN ROTOR		MTH	01-Sep-1998		A/R			
05-50-00-870-803-01 E2	POLISH FAN ROTOR		MTH	01-Sep-1998		A/R			
052001 E1	FJ44 CHECK 1	KEAU	MTH HRS LDG	27-Feb-2023 3858 3263		300		4158	18.3
052001 E2	FJ44 CHECK 1	KEAU	MTH HRS LDG	27-Feb-2023 3858 3263		300		4158	18.3
052002 E1	FJ44 CHECK 2	UNK	MTH HRS LDG	09-May-2019 3537.4 2946		600		4137.4	-2.3
									<b>Over Due</b>
052002 E2	FJ44 CHECK 2	UNK	MTH HRS LDG	07-May-2019 3537.4 2946		600		4137.4	-2.3
									<b>Over Due</b>
052003 E1	FJ44 CHECK 3		MTH HRS LDG	02-Nov-2003 1539.9 1047	-2.4	12000		13537.5	9397.8
052003 E2	FJ44 CHECK 3		MTH HRS LDG	02-Nov-2003 1539.9 1047	-2.4	12000		13537.5	9397.8
052004 E1	FJ44 CHECK 4	UNK	MTH HRS LDG	09-May-2019 3537.4 2946		12000		15537.4	11397.7
052004 E2	FJ44 CHECK 4	UNK	MTH HRS LDG	07-May-2019 3537.4 2946		12000		15537.4	11397.7
052005 E1	FJ44 CHECK 5		MTH HRS	01-Sep-1998 0	-6462.5	12000		5537.5	1397.8
052005 E2	FJ44 CHECK 5		MTH HRS	01-Sep-1998 0	-6462.5	12000		5537.5	1397.8
052006 E1	FJ44 CHECK 6		MTH HRS	01-Sep-1998 0	-4462.5	12000		7537.5	3397.8
052006 E2	FJ44 CHECK 6		MTH HRS	01-Sep-1998 0	-4462.5	12000		7537.5	3397.8
052007 E1	FJ44 CHECK 7		MTH HRS	01-Sep-1998 0	-2462.5	12000		9537.5	5397.8
052007 E2	FJ44 CHECK 7		MTH HRS	01-Sep-1998 0	-2462.5	12000		9537.5	5397.8
052008 E1	FJ44 CHECK 8		MTH HRS	01-Sep-1998 0	-462.5	12000		11537.5	7397.8
052008 E2	FJ44 CHECK 8		MTH HRS	01-Sep-1998 0	-462.5	12000		11537.5	7397.8
052009 E1	FJ44 CHECK 9		MTH HRS	01-Sep-1998 0		14000		14000	9860.3
052009 E2	FJ44 CHECK 9		MTH HRS	01-Sep-1998 0		14000		14000	9860.3
052010 E1	FJ44 CHECK 10		MTH HRS	01-Sep-1998 0		16000		16000	11860.3
052010 E2	FJ44 CHECK 10		MTH HRS	01-Sep-1998 0		16000		16000	11860.3
052011 E1	FJ44 CHECK 11		MTH	01-Sep-1998		-			
052011 E2	FJ44 CHECK 11		MTH	01-Sep-1998		-			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
052012 E1	FJ44 CHECK 12			MTH 01-Sep-1998 HRS 0		20000		20000	15860.3
052012 E2	FJ44 CHECK 12			MTH 01-Sep-1998 HRS 0		20000		20000	15860.3
052013 E1	FJ44 CHECK 13			MTH 01-Sep-1998		-			
052013 E2	FJ44 CHECK 13			MTH 01-Sep-1998		-			
052014 E1	FJ44 CHECK 14			MTH 01-Sep-1998 HRS 0		24000		24000	19860.3
052014 E2	FJ44 CHECK 14			MTH 01-Sep-1998 HRS 0		24000		24000	19860.3
262002A LEFT NO. 1 262002 : L1	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)		13083-5 ESD23L965-001	MTH 06-Jan-2025 HRS 4091.8 LDG 3455		72		31-Jan-2031	67 m 21 d
262002C LEFT NO. 2 262002 : L2	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)		13083-5 ESD23L965-001	MTH 06-Jan-2025 HRS 4091.8 LDG 3455		72		31-Jan-2031	67 m 21 d
262002E RIGHT NO. 1 262002 : R1	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)	KEAU	13083-5 ESD23L965-001	MTH 06-Jan-2025 HRS 4091.8 LDG 3455		72		31-Jan-2031	67 m 21 d
262002G RIGHT NO. 2 262002 : R2	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)	KEAU	13083-5 ESD23L965-001	MTH 06-Jan-2025 HRS 4091.8 LDG 3455		72		31-Jan-2031	67 m 21 d
B335003 LEFT	LEFT EMERGENCY LIGHTING BATTERY PACK RESTORATION	KEAU	CBS28-1 007490	MTH 14-May-2025 HRS 4138.2 LDG 3483		48	2	31-Mar-2029	45 m 21 d
341057 LEFT 0512013B : L-ADC	CALIBRATION TEST ADC/ALT UNIT (FAR 91.411)	KFCM	011-02337-01 1U6015356	MTH 14-May-2025 HRS 4138.2 LDG 3483		A/R			
Calibration Date: 14-May-2025									
341058 RIGHT 0512013B : R-ADC	CALIBRATION TEST ADC/ALT UNIT (FAR 91.411)	KFCM	011-02337-01 1U6015360	MTH 14-May-2025 HRS 4138.2 LDG 3483		A/R			
Calibration Date: 14-May-2025									
341068 LEFT 0512013 : L-ALT	CALIBRATION TEST ENCODING ALTIMETER (FAR 91.411)	7FL6	PN NOT INSTALLED	MTH		A/R			
347001	CHECK RVSM HEIGHT MONITORING	DAB		MTH 07-Jan-2025 HRS 4091.8 LDG 3455		1000		5091.8	952.1
350002 0512004 : OXY	RESTORATION (HYDROSTATIC TEST) OXYGEN BOTTLE	KCRG	176274-50 0565-4951	MTH 17-Feb-2021		60		28-Feb-2026	8 m 18 d
Hydro Check Date: 17-Feb-2021									
710010 E1	COMPRESSOR CLEANING			MTH 01-Sep-1998		A/R			
710010 E2	COMPRESSOR CLEANING			MTH 01-Sep-1998		A/R			
731025 E1	FUEL FILTER REPLACEMENT	UNK		MTH 09-May-2019 HRS 3537.4 LDG 2946		1200		4737.4	597.7



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
731025	FUEL FILTER REPLACEMENT				MTH	07-May-2019				
E2		UNK			HRS	3537.4	1200		4737.4	597.7
					LDG	2946				



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
211002	B/A FLOW CONTROL VALVE 9912420-3	*CF		1H124-8 7AP39	MTH 01-Sep-1998		O/C			
211003	HEAT PRESSURE EXCHANGER	*CF		10840A 381	MTH 01-Sep-1998		O/C			
211004	RAM AIR MODULATING VALVE	KCHA		27241287-15 5AH7	MTH 25-Jun-2014 HRS 3111.6 LDG 2525		O/C			
211005	EMERGENCY PRESS SHUTOFF VALVE 9912422-1	*CF		2601-7 276	MTH 01-Sep-1998		O/C			
212001	UNDERFLOOR INLET AIR BLOWER	*CF		0113-12 314	MTH 01-Sep-1998		O/C			
212003	TEMP PRESS COMPRESSION SWITCH	*CF		1173T42-3 2276	MTH 01-Sep-1998		O/C			
212011 AFT	TEMP UNDERFLOOR SENSOR 9912085-3	*CF		27221274 5AP193	MTH 01-Sep-1998		O/C			
212202	OVERHEAD AIR VALVE SOLENOID	*CF		D113204 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
212203	ACTUATOR	*CF		D-68070-A-1 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
212302	BLOWER - WINDSHIELD AIR MOTOR	*CF		7003-200 370	MTH 01-Sep-1998		O/C			
212401	AVIONICS COOLING BLOWER	*CF		071-04037-0003 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
212403	AVIONICS COOLING BLOWER	*CF		19A827 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
212404 NOSE	AVIONICS COOLING FAN	*CF		032105 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
213001	PRESS MASTER OUTFLOW VALVE	KCHA		9912409-18 5004	MTH 20-Sep-2018 HRS 3490.9 LDG 2902		O/C	0 0 0		
213002	PRESS SECONDARY OUTFLOW VALVE	KCHA		9912409-3 1114	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C	0 0		
213003	PRESSURIZATION CONTROLLER 9912409-6	CHA		52770-112 360	MTH 15-Sep-2006 HRS 2283		O/C	282		
213005	DIFFERENTIAL PRESS INDICATOR	*CF		C668511-0105 20750	MTH 01-Sep-1998		O/C			
215001	FORWARD EVAPORATOR	*CF		1134820-1 254	MTH 01-Sep-1998		O/C			
215002	AFT EVAPORATOR	*CF		1134820-2 277	MTH 01-Sep-1998		O/C			
215003 AFT	EVAPORATOR MOTOR	KEAU		1250210-1 SN-UNKNOWN	MTH 06-Jun-2024 HRS 3986.1 LDG 3387		O/C			
215003 FORWARD	EVAPORATOR MOTOR	*CF		1250210-1 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
215004	AIR CONDITIONER COMPRESSOR	KCRG		1134160 10679	MTH 18-Feb-2020 HRS 3567.1 LDG 2967		O/C			
215005	AIR CONDITIONER CONDENSER	KCRG		1134180-1 N/A	MTH 18-Feb-2020 HRS 3567.1 LDG 2967		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
215006	COMPRESSOR DRIVE MOTOR KCRG			1134104-5 3805	MTH 18-Feb-2020 HRS 3567.1 LDG 2967		O/C			
215007	RECEIVER DRYER ASSEMBLY KCRG			1134140-3 N/A	MTH 18-Feb-2020 HRS 3567.1 LDG 2967		O/C			
215008	BINARY SWITCH	GSO		1250232-7 SN-UNKNOWN	MTH 17-Jul-2001 ACH 490		O/C	0		
215009	A/C FLIGHT HOUR METER *CF			1250703-3 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
215011	AIR CONDITIONER DRIVE BELT R134A	KCRG		232L100 N/A	MTH 18-Feb-2020 HRS 3567.1 LDG 2967		O/C			
215012	COMPRESSOR DRIVE MOTOR BRUSHES KCRG			1251171 N/A	MTH 18-Feb-2020 HRS 3567.1 LDG 2967 ACH 2107.9		500	0	2607.9	367.1
215013 AFT	EXPANSION VALVE *CF			1250218 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
215013 FORWARD	EXPANSION VALVE *CF			1250218 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
216002	TEMPERATURE CONTROLLER *CF			27231272-25 3AP22	MTH 01-Sep-1998		O/C			
216003	TEMP CNTL SYS SENSOR 9912085-3 *CF			27221274 5AP194	MTH 01-Sep-1998		O/C			
221002	AUTOPILOT COMPUTER CONTROL			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
221003 AILERON	SERVO GSA80	KFCM		011-00877-20 19Z17274	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C	0 0 0		
221004 RUDDER	SERVO GSA80	KFCM		011-00877-20 19Z017287	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C	0 0 0		
221005 ELEVATOR	SERVO GSA80	KFCM		011-00877-20 19Z017309	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C	0 0 0		
221009	GMC 605 AUTOPILOT CONTROLLER -- KFCM			011-02967-02 38H202382	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C	0 0 0		
221010	GSM 86 PITCH TRIM SERVO GEARBOX -- KFCM			011-01904-01 1GJ007865	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C	0 0 0		
221012	GSM 86 ROLL SERVO GEARBOX -- KFCM			011-01904-00 1GK040519	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C	0 0 0		
221017	GSM 86 PITCH SERVO GEARBOX -- KFCM			011-01904-00 1GK040440	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C	0 0 0		



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
221019	GSM 86 YAW SERVO GEARBOX -- KFCM			011-01904-00 1GK0392851	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C	0 0 0		
230002	GLOVE BOX WITH DUEL USB PORT KCHA			JA 70-012 6079	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			
230098	USB ADAPTER #3 --			PN SN-UNKNOWN			O/C			
232001 NO. 1	COMM RADIO SYSTEM CONTROL KCHA			PN NOT INSTALLED	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			
232001 NO. 2	COMM RADIO SYSTEM CONTROL KCHA			PN NOT INSTALLED	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			
232004	FLITEPHONE TRANSCEIVER KCHA			PN NOT INSTALLED	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			
232008 BOTTOM	ANTENNA - COMM 1 *CF			17-50-01 1259	MTH 01-Sep-1998		O/C			
232008 TOP	ANTENNA - COMM 2 GSO			18-50-01 547	MTH 18-Jul-2001 HRS 903		O/C	0		
235001 LEFT	AUDIO AMPLIFIER KCHA			PN NOT INSTALLED	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			
235001 RIGHT	AUDIO AMPLIFIER KCHA			PN NOT INSTALLED	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			
242001 NO. 1	SECOND AC POWER INVERTER			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
242001 NO. 2	SECOND AC POWER INVERTER			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
243002 LEFT	GENERATOR CONTROL UNIT CHA			51525-001F 97220	MTH 03-Aug-2010 HRS 2758.8 LDG 2180		O/C	1774		
243002 RIGHT	GENERATOR CONTROL UNIT CHA			51525-001F P1409	MTH 02-Sep-2010 HRS 2759.6 LDG 2182		O/C			
243003	MAIN BATTERY KEAU			S3597-4 41219353	MTH 07-Jun-2022 HRS 3812 LDG 3234		O/C	0 0		
243004	BATTERY TEMPERATURE MONITOR- *CF			1529-1-1 2803	MTH 01-Sep-1998		O/C			
243005	OVERVOLTAGE MONITOR- *CF			1645-1-3 1744	MTH 01-Sep-1998		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
243006 LEFT	AMMETER	*CF		C662501-0105 D98457	MTH 01-Sep-1998		O/C			
243006 RIGHT	AMMETER	*CF		C662501-0105 E98275	MTH 01-Sep-1998		O/C			
243008	BATTERY DISCONNECT RELAY	*CF		A931F CM14745	MTH 01-Sep-1998		O/C			
243009	GCU 485 EFIS CONTROL PANEL -- KFCM			011-03582-00 3QR600151	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C	0 0 0		
243011	VOLTMETER	*CF		C662502-0101 E98094	MTH 01-Sep-1998		O/C			
245001 LEFT	START PCB ASSY	KCHA		6318324-2 N/A	MTH 30-Jun-2016 HRS 3337.6 LDG 2741 ACH 1958.6		O/C	0 0		
245001 RIGHT	START PCB ASSY	*CF		6318324-1 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
245002 LEFT	ASSEMBLY-FUEL CONTROL PCB	*CF		6318321-3 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
245002 RIGHT	ASSEMBLY-FUEL CONTROL PCB	CHA		6318321-4 SN-UNKNOWN	MTH 02-Sep-2010 HRS 2759.6 LDG 2182		O/C	0		
245003 LEFT	ASSEMBLY-IGNITOR PCB	*CF		6318322-1 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
245003 RIGHT	ASSEMBLY-IGNITOR PCB	*CF		6318322-1 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
245004 LEFT	ANTI ICE PCB ASSY	CHA		6318323-3 SN-UNKNOWN	MTH 24-Mar-2010 HRS 2734 LDG 2154		O/C	0		
245004 RIGHT	ANTI ICE PCB ASSY	*CF		6318323-3 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
245005	ATTENUATOR PCB ASSY	*CF		6318355-2 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
245006	ENVIRONMENTAL PCB ASSY	*CF		6318356-1 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
245007	MISCELLANEOUS PCB ASSY	GSO		6318357-2 SN-UNKNOWN	MTH 28-Sep-2001 HRS 951		O/C	0		
245008	TRIM CONTROL PCB ASSY			6518351-10 0629	MTH 21-Apr-2004 HRS 1705		O/C	0		
245009	DIMMING PCB ASSY	*CF		6518353-2 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
245010	GEAR LOGIC PCB ASSY	*CF		6518354-3 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
245011	FUEL FLOW XMITTER PCB ASSY	*CF		85-230-1 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
256001	ELT TRANSMITTER	UNK		3000-10 344250	MTH 09-Aug-2021 HRS 3683 LDG 3164		O/C	2089		
256004	ELT ANTENNA	FXE		10-209-2 997	MTH 07-Jan-2004 HRS 1594		O/C	0		



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
256005	ELT BEACON BATTERY PACK 2020BATTERY	KFCM		2020 NSN	MTH 14-May-2025 HRS 4138.2 LDG 3483		24	0	30-Apr-2027	22 m 20 d
Manufacture Date: 22-Apr-2025										
256006 NO. 1	LIFE VEST XF-35	KCHA		PO1074-207 19080920189	MTH 22-Nov-2019 HRS 3537.4 LDG 2946		120	0	14-Aug-2029	50 m 4 d
256006 NO. 2	LIFE VEST XF-35	KCHA		PO1074-207 19080920190	MTH 22-Nov-2019 HRS 3537.4 LDG 2946		120	0	14-Aug-2029	50 m 4 d
256006 NO. 3	LIFE VEST XF-35	KCHA		PO1074-207 19080920188	MTH 22-Nov-2019 HRS 3537.4 LDG 2946		120	0	14-Aug-2029	50 m 4 d
256006 NO. 4	LIFE VEST XF-35	KCHA		PO1074-207 19080920183	MTH 22-Nov-2019 HRS 3537.4 LDG 2946		120	0	14-Aug-2029	50 m 4 d
256006 NO. 5	LIFE VEST XF-35	KCHA		PO1074-207 19080920187	MTH 22-Nov-2019 HRS 3537.4 LDG 2946		120	0	14-Aug-2029	50 m 4 d
256006 NO. 6	LIFE VEST XF-35	KCHA		PO1074-207 19080920185	MTH 22-Nov-2019 HRS 3537.4 LDG 2946		120	0	14-Aug-2029	50 m 4 d
256006 NO. 7	LIFE VEST XF-35	KCHA		PO1074-207 19080920191	MTH 22-Nov-2019 HRS 3537.4 LDG 2946		120	0	14-Aug-2029	50 m 4 d
261002 LEFT	FIRE DETECT SENSOR 9912416-1	*CF		30012121004/4559 202333	MTH 01-Sep-1998		O/C			
261002 RIGHT	FIRE DETECT SENSOR 9912416-1	*CF		30012121004/4559 202344	MTH 01-Sep-1998		O/C			
262001 LEFT	FIRE EXTINGUISHER BOTTLE 9912048-4			30400031-1 44969B1	MTH 06-Jan-2025 HRS 4091.8 LDG 3455		O/C	0 0 0		
262001 RIGHT	FIRE EXTINGUISHER BOTTLE 9912048-4	KEAU		30400031-1 31679B1	MTH 06-Jan-2025 HRS 4091.8 LDG 3455		O/C	0 0 0		
262002 LEFT NO. 1	FIRE EXTINGUISHER CARTRIDGE			13083-5 ESD23L965-001	MTH 06-Jan-2025 HRS 4091.8 LDG 3455		72		30-Nov-2029	53 m 20 d
Manufacture Date: 01-Nov-2023										
262002 LEFT NO. 2	FIRE EXTINGUISHER CARTRIDGE			13083-5 ESD23L965-001	MTH 06-Jan-2025 HRS 4091.8 LDG 3455		72		30-Nov-2029	53 m 20 d
Manufacture Date: 01-Nov-2023										
262002 RIGHT NO. 1	FIRE EXTINGUISHER CARTRIDGE	KEAU		13083-5 ESD23L965-001	MTH 06-Jan-2025 HRS 4091.8 LDG 3455		72		30-Nov-2029	53 m 20 d
Manufacture Date: 01-Nov-2023										
262002 RIGHT NO. 2	FIRE EXTINGUISHER CARTRIDGE	KEAU		13083-5 ESD23L965-001	MTH 06-Jan-2025 HRS 4091.8 LDG 3455		72		30-Nov-2029	53 m 20 d
Manufacture Date: 01-Nov-2023										
262003 COCKPIT	PORTABLE FIRE EXTINGUISHER	KCHA		C352CS B-00099692	MTH 30-Mar-2016 HRS 3310.5 LDG 2715		O/C	0 0 0		
273001 LEFT	SHAKER CONTROL	*CF		201 4018	MTH 01-Sep-1998		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
273002	ELEVATOR ELECTRIC TRIM SERVO GSA81	KFCM		011-00878-20 1A1036630	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C	0 0 0		
273003	SERVO MOUNT ASSY	*CF		44575-3415 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
273005	RUDDER TRIM TAB ACTUATOR	*CF		6361215-21 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
273007 LEFT	ELEVATOR ASSEMBLY	KCHA		6334000-19 0272	MTH 25-Feb-2021 HRS 3645.5 LDG 3123		O/C			
273008 RIGHT	ELEVATOR	KCHA		6334000-20 0259	MTH 25-Feb-2021 HRS 3645.5 LDG 3123		O/C			
275001	SHUTOFF VALVE	*CF		4083 237	MTH 01-Sep-1998		O/C			
275002 LEFT	FLAP HYD ACTUATOR	*CF		1542000-3 9912365-4 562	MTH 01-Sep-1998		O/C			
275002 RIGHT	FLAP HYD ACTUATOR	*CF		1542000-3 9912365-4 569	MTH 01-Sep-1998		O/C			
276001 LEFT	SPEEDBRAKE ACTUATOR	*CF		1542100-3 9912375-3 573	MTH 01-Sep-1998		O/C			
276001 RIGHT	SPEEDBRAKE ACTUATOR	*CF		1542100-3 9912375-3 580	MTH 01-Sep-1998		O/C			
281001 LEFT	FUEL SURGE VALVE	*CF		35C10C 9912016-1 974	MTH 01-Sep-1998		O/C			
281001 RIGHT	FUEL SURGE VALVE	*CF		35C10C 9912016-1 995	MTH 01-Sep-1998		O/C			
282001 LEFT	ELECTRIC FUEL PUMP	*CF		1C7-13 9912017-4 10AM75	MTH 01-Sep-1998		O/C			
282001 RIGHT	ELECTRIC FUEL PUMP	*CF		1C7-13 9912017-4 5AP35	MTH 01-Sep-1998		O/C			
282002 LEFT	FUEL TRANSFER PUMP	*CF		RG45880 9912190-3 B673	MTH 01-Sep-1998		O/C			
282002 RIGHT	FUEL TRANSFER PUMP	*CF		RG45880 9912190-3 B678	MTH 01-Sep-1998		O/C			
282004 LEFT	FUEL MOTOR ACTUATED VALVE	*CF		EM9014-3 9912014-3 571	MTH 01-Sep-1998		O/C			
282004 RIGHT	FUEL MOTOR ACTUATED VALVE	*CF		EM9014-3 9912014-3 587	MTH 01-Sep-1998		O/C			
282005 LEFT	FUEL TRANSFER EJECTOR	*CF		RG45310 9912190-2 B7513	MTH 01-Sep-1998		O/C			
282005 RIGHT	FUEL TRANSFER EJECTOR	*CF		RG45310 9912190-2 B7444	MTH 01-Sep-1998		O/C			
282006	TRANSFER VALVE	*CF		ZSV57 9914103-6 804091035	MTH 01-Sep-1998		O/C			
284001 LEFT	#5 FUEL TRANSMITTER	*CF		10307T01Y00 9912412-5 B732	MTH 01-Sep-1998		O/C			
284001 RIGHT	#5 FUEL TRANSMITTER	*CF		10307T01Y00 9912412-5 B736	MTH 01-Sep-1998		O/C			
284002 LEFT	FUEL QUANTITY TRANSMITTER	*CF		10309T03Y00 9912412-8 B899	MTH 01-Sep-1998		O/C			
284002 RIGHT	FUEL QUANTITY TRANSMITTER	*CF		10309T03Y00 9912412-8 B898	MTH 01-Sep-1998		O/C			
284003	FUEL QUANTITY SIGNAL CONDITIONER	*CF		10310B01Y02 9912412-7 B352	MTH 01-Sep-1998		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
284004 LEFT	#3 FUEL TRANSMITTER 9912412-3	*CF		10305T01Y00 B725	MTH 01-Sep-1998		O/C			
284004 RIGHT	#3 FUEL TRANSMITTER 9912412-3	*CF		10305T01Y00 B723	MTH 01-Sep-1998		O/C			
284005 LEFT	#4 FUEL TRANSMITTER 9912412-4	*CF		10306T01Y00 B720	MTH 01-Sep-1998		O/C			
284005 RIGHT	#4 FUEL TRANSMITTER 9912412-4	*CF		10306T01Y00 B714	MTH 01-Sep-1998		O/C			
284006 LEFT	#2 FUEL TRANSMITTER 9912412-2	*CF		10304T01Y00 B764	MTH 01-Sep-1998		O/C			
284006 RIGHT	#2 FUEL TRANSMITTER 9912412-2	*CF		10304T01Y00 B766	MTH 01-Sep-1998		O/C			
284007 LEFT	#1 FUEL TRANSMITTER 9912412-1	*CF		10303T01Y00 B735	MTH 01-Sep-1998		O/C			
284007 RIGHT	#1 FUEL TRANSMITTER 9912412-1	*CF		10303T01Y00 B734	MTH 01-Sep-1998		O/C			
284008 LEFT	FUEL LOW LEVEL SWITCH 9912412-1	*CF		GIF5400-40 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
284008 RIGHT	FUEL LOW LEVEL SWITCH KCHA			GIF5400-40 N/A	MTH 24-Aug-2017 HRS 3403.3 LDG 2815 ACH 2023.8		O/C	0 0		
284009	FUEL QUANTITY/FUEL FLOW INDICATOR 9912399-10	*CF		10274N03M00 B595	MTH 01-Sep-1998		O/C			
291002 LEFT	HYDRAULIC PUMP ASSY 9912392-3	*CF		MC14549-5 880	MTH 01-Sep-1998		O/C			
291002 RIGHT	HYDRAULIC PUMP ASSY 9912392-3	*CF		MC14549-5 893	MTH 01-Sep-1998		O/C			
291003	HYDRAULIC CHECK VALVE 9912392-3	*CF		CV02-193 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
291005	HYDRAULIC RESERVOIR ASSEMBLY 9912392-3	*CF		6317001-52 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
291007	PRESSURE SWITCH 9912373-2	*CF		GPP1250-36 9816298	MTH 01-Sep-1998		O/C			
291008	HYDRAULIC MANIFOLD ASSEMBLY 9912423-24	*CF		8184-8 312	MTH 01-Sep-1998		O/C			
291009	HYDRAULIC RELIEF VALVE 9912423-24	*CF		1785-1 286	MTH 01-Sep-1998		O/C			
291010 LEFT	HYDRAULIC SHUTOFF VALVE ASSY 9912400-3	*CF		AV24B1388-1 T23036	MTH 01-Sep-1998		O/C			
291010 RIGHT	HYDRAULIC SHUTOFF VALVE ASSY 9912400-3	*CF		AV24B1388-1 T23030	MTH 01-Sep-1998		O/C			
291011 LEFT	FLOW SWITCH/CHECK HYD VALVE 9912393-2	*CF		MC19232-2 618	MTH 01-Sep-1998		O/C			
291011 RIGHT	FLOW SWITCH/CHECK HYD VALVE 9912393-2	*CF		MC19232-2 620	MTH 01-Sep-1998		O/C			
291011	SYSTEM RELIEF VALVE KCHA			9912423-46 1472A	MTH 06-Jun-2014 HRS 3106.3 LDG 2519		O/C	0 0 0		
291012	SPEED BRAKE DUMP VALVE SOLENOID 9912423-7	*CF		4082-2 303A	MTH 01-Sep-1998		O/C			
291013	LOADING VALVE SOLENOID 9912423-39	GSO		4134-4 566	MTH 07-Mar-2003 HRS 1377		O/C	0		
291014	GEAR VALVE SOLENOID 9912423-25	*CF		4051-1 306	MTH 01-Sep-1998		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
291015	GEAR PORTION CHECK VALVE 9912423-13	*CF		9504 302	MTH 01-Sep-1998		O/C			
291016 LEFT	SPEED BRAKE PORTION VALVE 9912423-14	*CF		9505 616	MTH 01-Sep-1998		O/C			
291016 RIGHT	SPEED BRAKE PORTION VALVE 9912423-14	*CF		9505 615	MTH 01-Sep-1998		O/C			
291017	SPEED BRAKE PORTION VALVE 9912423-15	*CF		2577 304	MTH 01-Sep-1998		O/C			
291018	PNEUMATIC DUMP VALVE 9912423-17	*CF		9503-1 313	MTH 01-Sep-1998		O/C			
291019 LEFT	ATTENUATOR VALVE SOLENOID 9912423-19	*CF		4107-1 305	MTH 01-Sep-1998		O/C			
291019 RIGHT	ATTENUATOR VALVE SOLENOID 9912423-20	*CF		4107-2 301	MTH 01-Sep-1998		O/C			
291020 NO. 1	SPEEDBRAKE VALVE SOLENOID 9912423-6	*CF		4052-1 303	MTH 01-Sep-1998		O/C			
291021 NO. 1	FLAP VALVE SOLENOID 9912423-8	*CF		4052-2 309	MTH 01-Sep-1998		O/C			
291022	ELECTRO/HYDRAULIC SERVO VALVE *CF			37-509 302	MTH 01-Sep-1998		O/C			
301001	SHUTOFF ISOLATION VALVE 9912403-2	*CF		2602-36 110	MTH 01-Sep-1998		O/C			
301002 LEFT	PNEUMATIC DEICE SWITCH *CF			1106P55-1 577	MTH 01-Sep-1998		O/C			
301002 RIGHT	PNEUMATIC DEICE SWITCH *CF			1106P55-1 637	MTH 01-Sep-1998		O/C			
301003 LEFT	SHUTOFF PRESS REGULATOR VALVE 9912402-9	*CF		1H127-4 5AP70	MTH 01-Sep-1998		O/C			
301003 RIGHT	SHUTOFF PRESS REGULATOR VALVE 9912402-9	*CF		1H127-4 5AP71	MTH 01-Sep-1998		O/C			
301004 LEFT	TEMPERATURE DEICE SWITCH SWF			1173T42-4 2555	MTH 03-Dec-2004 HRS 1864		O/C	0		
301004 RIGHT	TEMPERATURE DEICE SWITCH *CF			1173T42-4 598	MTH 01-Sep-1998		O/C			
301010 LEFT	HORIZONTAL STABILIZER BOOT MYCV2R0			29S4D5244-11	MTH 08-Oct-2004 HRS 1818		O/C	0		
301010 RIGHT	HORIZONTAL STABILIZER BOOT CAE			29S4D5244-12 MZPB030	MTH 19-Oct-2007 HRS 2481		O/C	0		
301011	DEICE TAIL TIMER 9912440-1	*CF		937-1-1 394	MTH 01-Sep-1998		O/C			
302001 LEFT	SOLENOID VALVE 9912402-10	CHA		1H127-5 5AP52	MTH 24-Feb-2009 HRS 2642		O/C	2642		
302001 RIGHT	SOLENOID VALVE 9912402-10	CHA		1H127-5 1AN17	MTH 24-Feb-2009 HRS 2642		O/C	0		
302003 LEFT	INLET MONITOR SWITCH *CF			21548-2-19-6 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
302003 RIGHT	INLET MONITOR SWITCH *CF			21548-2-19-6 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
303002 LEFT	HEATED PITOT TUBE *CF			PH502 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
303002 RIGHT	HEATED PITOT TUBE *CF			PH502 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
304001	B/A TEMP MONITOR- *CF			1169-1 2658	MTH 01-Sep-1998		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
304002	HEAT EXCHANGER 9912041-3	*CF		10653A 996	MTH 01-Sep-1998		O/C			
304003	WINDSHIELD S/O VALVE 9912402-9	*CF		1H127-4 5AP73	MTH 01-Sep-1998		O/C			
304004 LEFT	PITOT STATIC CURRENT SENSOR *CF			76250-1 3445	MTH 01-Sep-1998		O/C			
304004 RIGHT	PITOT STATIC CURRENT SENSOR *CF			76250-1 3217	MTH 01-Sep-1998		O/C			
304006	TEMP BLEED AIR CONTROLLER 9912085-5	*CF		27231272-20 2AP13	MTH 01-Sep-1998		O/C			
304007	TEMP CONTROL BLEED AIR VALVE 9912085-1	*CF		27241287 5APH257	MTH 01-Sep-1998		O/C			
304009 LEFT	SOLENOID DEICE VALVE *CF			3D2353-06 N14654	MTH 01-Sep-1998		O/C			
304009 RIGHT	SOLENOID DEICE VALVE *CF			3D2353-06 N14653	MTH 01-Sep-1998		O/C			
304010	ALCOHOL PUMP ASSEMBLY *CF			476411 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
304011	TEMPERATURE SENSOR 9912085-3	*CF		27221274 5AP111	MTH 01-Sep-1998		O/C			
304012 LEFT	WINDSHIELD BLEED AIR VALVE *CF			1403-20 1152	MTH 01-Sep-1998		O/C			
304012 RIGHT	WINDSHIELD BLEED AIR VALVE *CF			1403-20 1149	MTH 01-Sep-1998		O/C			
304013	PRESSURE WINDSHIELD SWITCH *CF			1115P25 29972	MTH 01-Sep-1998		O/C			
304014 AFT	TEMPERATURE EVAPORATOR SENSOR 9912085-3	*CF		27221274 4AP167	MTH 01-Sep-1998		O/C			
312001 LEFT	DIGITAL CLOCK			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
313001	FLIGHT HOUR METER 85071	*CF		C664503-0104 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
315001	CABIN ALTITUDE PRESSURE SWITCH KCHA			9910095-6 1823574	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C	0 0		
315002	MASTER WARN ANNUNCIATOR ASSY CHA			9912438-9 438000388	MTH 22-Dec-2010 HRS 2773.2 LDG 2197		O/C			
321001 LEFT MAIN LANDING GEAR	AND ATTACHING HARDWARE ASSEMBLY *CF			6341003-7 112	MTH 01-Sep-1998		O/C			
321001 NOSE LANDING GEAR	STRUT AND ATTACHING HARDWARE ASSEMBLY *CF			6342000-21 SN-UNKNOWN	MTH 01-Sep-1998 LDG 0		22500	0	22500	19014
321001 RIGHT MAIN LANDING GEAR <i>321002 : R</i>	AND ATTACHING HARDWARE ASSEMBLY *CF			6341003-8 112	MTH 01-Sep-1998		O/C			
321003 LEFT MAIN GEAR	TRUNNION ASSEMBLY *CF			6341007-3 SN-UNKNOWN	MTH 01-Sep-1998 LDG 0		12480	0	12480	8994
321004 RIGHT MAIN GEAR	TRUNNION ASSEMBLY *CF			6341007-4 SN-UNKNOWN	MTH 01-Sep-1998 LDG 0		12480	0	12480	8994
321005 LEFT	TRAILING LINK AND AXLE ASSEMBLY *CF			6341002-7 SN-UNKNOWN	MTH 01-Sep-1998 LDG 0		28300	0	28300	24814



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
321006 RIGHT	TRAILING LINK AND AXLE ASSEMBLY *CF			6341002-8 SN-UNKNOWN	MTH 01-Sep-1998 LDG 0		28300	0	28300	24814
321007	SHIMMY DAMPER ASSEMBLY GSO			6343001-5 3095	MTH 28-Sep-2001 HRS 951 LDG 651		O/C	0		
321008 LEFT	OLEO ASSEMBLY CHA			6341130-3 0257	MTH 16-Dec-2008 HRS 2624 LDG 2026		28300	1247	29079	25593
321008 RIGHT	OLEO ASSEMBLY *CF			6341130-3 SN-UNKNOWN	MTH 01-Sep-1998 LDG 0		28300	0	28300	24814
321009 321004	FORK AND PISTON ASSEMBLY *CF			6342000-3 SN-UNKNOWN	MTH 01-Sep-1998 LDG 0		12500	0	12500	9014
323000 NOSE LANDING GEAR 323001	ACTUATOR ASSEMBLY 9912370-3 *CF			1541900-3 286	MTH 01-Sep-1998 LDG 0		22500	0	22500	19014
323001 LEFT MAIN LANDING GEAR	ACTUATOR ASSEMBLY 9912397-7 *CF			1541800-11 630	MTH 01-Sep-1998 LDG 0		12000	0	12000	8514
323002 RIGHT MAIN LANDING GEAR	ACTUATOR ASSEMBLY 9912397-7 *CF			1541800-11 629	MTH 01-Sep-1998 LDG 0		12000	0	12000	8514
323003	NG UPLOCK ACTUATOR *CF			6327504-5 WMP282	MTH 01-Sep-1998		O/C			
323005 LEFT	MLG UPLOCK ACTUATOR *CF			6327504-4 WMP584	MTH 01-Sep-1998		O/C			
323005 RIGHT	MLG UPLOCK ACTUATOR *CF			6327504-4 WMP571	MTH 01-Sep-1998		O/C			
323006	HYD SHUTTLE VALVE *CF			95784 500	MTH 01-Sep-1998		O/C			
324001 LEFT	MAIN LANDING GEAR WHEEL 9912398-7 KCHA			3-1527-2 0648	MTH 01-Aug-2018 HRS 3485.2 LDG 2898		O/C	0 0 0		
324001 RIGHT	MAIN LANDING GEAR WHEEL 9912398-7 UNK			3-1527-2 0612	MTH 09-Jan-2025 HRS 4095.4		O/C	77 610.2		
324002 NOSE	LANDING GEAR WHEEL ASSY 9914069-2 *CF			3-1418 4285	MTH 01-Sep-1998		O/C			
324005 LEFT	MLG TIRE KEAU			277K08-1 21370283	MTH 27-Feb-2023 HRS 3858 LDG 3263		O/C	0 0		
324005 RIGHT	MLG TIRE UNK			PN-UNKNOWN SN-UNKNOWN	MTH 09-Jan-2025 HRS 4095.4		O/C	0 0		
324007 NOSE	LANDING GEAR TIRE KCHA			030-611-0 9026S00402	MTH 06-Dec-2019 HRS 3537.4 LDG 2946		O/C	0 0		
324008 LEFT 324007 : L	SHUTTLE VALVE *CF			195-191-1 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
324008 RIGHT	SHUTTLE VALVE *CF			195-191-1 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
324016 LEFT MAIN LANDING GEAR	BRAKE ASSY 9912398-8 KCHA			2-1559-3 0812	MTH 06-Dec-2019 HRS 3537.4 LDG 2946		O/C	0 0		



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
324016 RIGHT MAIN LANDING GEAR	BRAKE ASSY 9912398-8	KCHA		2-1559-3 0525	MTH 06-Dec-2019 HRS 3537.4 LDG 2946		O/C	0 0		
324101	POWER BRAKE AND ANTISKID VALVE 9912374-4	*CF		38-747 414	MTH 01-Sep-1998		O/C			
324102 LEFT	ANTISKID TRANSDUCER ASSEMBLY 9912305-2	*CF		40-955 3765	MTH 01-Sep-1998		O/C			
324102 RIGHT	ANTISKID TRANSDUCER ASSEMBLY 9912305-2	*CF		40-955 4178	MTH 01-Sep-1998		O/C			
324103	BRAKE CONTROL BOX 9912305-6	*CF		42-707-1 1079	MTH 01-Sep-1998		O/C			
324104 LEFT	BRAKE CYLINDER ASSEMBLY 9912366-1	*CF		95805 713	MTH 01-Sep-1998		O/C			
324104 RIGHT	BRAKE CYLINDER ASSEMBLY 9912366-1	*CF		95805 760	MTH 01-Sep-1998		O/C			
324104A LEFT	BRAKE CYLINDER ASSEMBLY 9912366-2	MCO		95805-1 0665	MTH 02-May-2007 HRS 2391 LDG 1746		O/C	0		
324104A RIGHT	BRAKE CYLINDER ASSEMBLY 9912366-2	*CF		95805-1 688	MTH 01-Sep-1998		O/C			
324105	PARKING BRAKE VALVE 9912388-1	*CF		95853 344A	MTH 01-Sep-1998		O/C			
324106	HYDRAULIC PUMP MOTOR *CF			MP50B1 1031	MTH 01-Sep-1998		O/C			
324107	ANTISKID ACCUMULATOR *CF			57C57663 293	MTH 01-Sep-1998		O/C			
324108	HYDRAULIC PRESSURE SWITCH 9912373-1	*CF		GPP1250-29 9810303	MTH 01-Sep-1998		O/C			
324109	BRAKE PRESSURE PUMP ASSY 9912364-2	*CF		640929 1153	MTH 01-Sep-1998		O/C			
324110	EMERGENCY BRAKE VALVE ASSY 9912387-1	*CF		878208-01 299	MTH 01-Sep-1998		O/C			
324111 LEFT	MLG UP & LOCK SWITCH *CF			65-430087 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
324111 RIGHT	MLG UP & LOCK SWITCH *CF			65-430087 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
324111	NLG UP & LOCK SWITCH *CF			65-430087 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
324112	PRESSURE ANTISKID SWITCH 9912374-6	*CF		38-747502 418	MTH 01-Sep-1998		O/C			
325001	NOSE LANDING GEAR ASSEMBLY *CF			6342000-22 126	MTH 01-Sep-1998		O/C			
325002	NOSE STEERING BUNGEE ASSEMBLY *CF			5565624-19 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
326001 LEFT	M/G DOWN&LOCK SWITCH *CF			1EN118-6 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
326001 RIGHT	M/G DOWN&LOCK SWITCH *CF			1EN118-6 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
326002	N/G DOWN&LOCK SWITCH *CF			1EN118-6 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
326006	EMERGENCY GEAR BOTTLE KCHA			9912368-2 3881	MTH 17-Jun-2020 HRS 3594.7 LDG 2989		288	0	01-Mar-2027	20 m 19 d
Manufacture Date: 17-Jun-2020										
326007	EMERGENCY GEAR GAUGE *CF			18225901 65238A	MTH 01-Sep-1998		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
330001 CENTER	PANEL LIGHTS DIMMER *CF			273-1 5432	MTH 01-Sep-1998		O/C			
330001 LEFT	PANEL LIGHTS DIMMER *CF			273-1 5407	MTH 01-Sep-1998		O/C			
330001 RIGHT	PANEL LIGHTS DIMMER *CF			273-1 5437	MTH 01-Sep-1998		O/C			
330002	ELECTRICAL PANEL INVERTER *CF			EM2044-1 2509A	MTH 01-Sep-1998		O/C			
332001 L1	INDIRECT LIGHTING INVERTER *CF			6900113-3 2350	MTH 01-Sep-1998		O/C			
332002 L2	INDIRECT LIGHTING INVERTER *CF			6900113-3 2342	MTH 01-Sep-1998		O/C			
332003 L3	INDIRECT LIGHTING INVERTER *CF			6900113-3 2337	MTH 01-Sep-1998		O/C			
332004 L4	INDIRECT LIGHTING INVERTER *CF			6900113-3 2339	MTH 01-Sep-1998		O/C			
332005 R1	INDIRECT LIGHTING INVERTER *CF			6900113-3 235	MTH 01-Sep-1998		O/C			
332006 R2	INDIRECT LIGHTING INVERTER *CF			6900113-3 2330	MTH 01-Sep-1998		O/C			
332007 R3	INDIRECT LIGHTING INVERTER *CF			6900113-3 2349	MTH 01-Sep-1998		O/C			
332008 R4	INDIRECT LIGHTING INVERTER *CF			6900113-3 2343	MTH 01-Sep-1998		O/C			
334001	GROUND RECOGNITION LIGHT *CF			90033-13 2067468	MTH 01-Sep-1998		O/C			
334003 LEFT	ANTI COLLISION POWER SUPPLY KSZT			N/A N/A	MTH 11-May-2021 HRS 3664.5 LDG 3139		O/C	0 0		
334003 RIGHT	ANTI COLLISION POWER SUPPLY KSZT			N/A N/A	MTH 11-May-2021 HRS 3664.5 LDG 3139		O/C	0 0		
334004 LEFT	HOUSING ASSY-LANDING LIGHT LAMP *CF			50033011-1 563	MTH 01-Sep-1998		O/C			
334004 RIGHT	HOUSING ASSY-LANDING LIGHT LAMP *CF			50033011-1 571	MTH 01-Sep-1998		O/C			
334005 LEFT	ANTI COLLISION LIGHT ASSY KSZT			01-0790738-L0 235	MTH 11-May-2021 HRS 3664.5 LDG 3139		O/C	0 0		
334005 RIGHT	ANTI COLLISION LIGHT ASSY KSZT			01-0790738-R0 233	MTH 11-May-2021 HRS 3664.5 LDG 3139		O/C	0 0		
334006 LEFT	EMERGENCY EXIT BATTERY PACK KFCM			CBS28-1 007490	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C	2 0		
334012 EMPENNAGE	LED NAV/BEACON LIGHT KSZT			01-0771774V02 821678-0003	MTH 11-May-2021 HRS 3664.5 LDG 3139		O/C	0 0		
340003	FIS MODULE KAC-503	FXE		071-00168-0311 1028	MTH 17-Jan-2002 HRS 1022		O/C		0	



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
340004	DATA RECEIVER	KCHA		PN NOT INSTALLED	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			
340011 NO. 1	NO. 1 GDU 1060	KFCM		011-03308-72 7FW000934	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C	0 0 0		
340011 NO. 2	NO. 2 GDU 1060	KFCM		011-03308-72 7FW000941	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C	0 0 0		
340014	GDL 69A SATELLITE DATA LINK TRANCEIVER LINK	KCHA		011-03177-10 3NV004008	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			
340019 LEFT	GTP 59 OUTSIDE AIR TEMP PROBE	KFCM		011-00978-00 8DE001982	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C	0 0 0		
340019 RIGHT	GTP 59 OUTSIDE AIR TEMP PROBE	KFCM		011-00978-00 8DE002013	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C	0 0 0		
340038	GI275 ELECTRONIC FLIGHT INSTRUMENT --	KFCM		011-04489-30 5MZ123728	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C	0 0 0		
340042	AIR DATA MODULE --	KFCM		011-04426-00 575000911	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C	0 0 0		
340105	#1 GARMIN GMU-44B MAGNETOMETER	KFCM		011-04201-00 4WT019408	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C	0 0 0		
340106	#2 GARMIN GMU-44B MAGNETOMETER	KFCM		011-04201-00 4WT019015	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C	0 0 0		
341001 LEFT	AIRSPEED INDICATOR			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
341001 RIGHT	AIRSPEED INDICATOR			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
341001	AOA COMPUTER	*CF		C12406-2 382	MTH 01-Sep-1998		O/C			
341002	AOA CONTROLLER	*CF		C12421-1 476	MTH 01-Sep-1998		O/C			
341008	AOA INDICATOR	*CF		C12405-1 388	MTH 01-Sep-1998		O/C			
341009	AOA SENSOR	KCHA		C-12417-2 159	MTH 29-Dec-2011 HRS 2860.1 LDG 2262		O/C	0 0 0		
341010 AFT	RADIO ALTIMETER ANTENNA	*CF		S67-2002 13200	MTH 01-Sep-1998		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
341010 FORWARD	RADIO ALTIMETER ANTENNA *CF			S67-2002 13188	MTH 01-Sep-1998		O/C			
341019 LEFT	ENCODING ALTIMETER			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
341020 LEFT	ADC/ALT UNIT	KFCM		011-02337-01 1U6015356	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C	0 0 0		
341020 RIGHT	ADC/ALT UNIT	KFCM		011-02337-01 1U6015360	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C	0 0 0		
341020	REMOTE COURSE CONTROLLER			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
341029	MARKER BEACON INDICATOR			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
341030	OAT INDICATOR			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
341033 341003	AOA INDEXER	*CF		C12463-3 257	MTH 01-Sep-1998		O/C			
342002	AIR DATA SENSOR AZ-429	*CF		7017970-901 98050401	MTH 01-Sep-1998		O/C			
342003 #1	GRS 79 AHRS COMPUTER -- KFCM			011-03732-00 45T011046	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C	0 0 0		
342003 #2	GRS 79 AHRS COMPUTER -- KFCM			011-03732-00 45T011080	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C	0 0 0		
342004 RIGHT	ATTITUDE DIRECTOR INDICATOR			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
342006	SLAVING ACCESSORY			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
342021 LEFT	VERTICAL SPEED INDICATOR			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
342021 RIGHT	VERTICAL SPEED INDICATOR			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
342042 LEFT	FLIGHT DIRECTOR MODE SELECTOR			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
342043 LEFT	VERTICAL GYRO			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
342043 RIGHT	VERTICAL GYRO			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
342044 LEFT	FLIGHT GUIDANCE COMPUTER			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
342045	ACCELEROMETER			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
342046	HORIZONTAL SITUATION INDICATOR			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
342048	YAW RATE GYRO			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
342049 LEFT	DIRECTIONAL GYRO			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
342049 RIGHT	DIRECTIONAL GYRO			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
342050 RIGHT	FLUX DETECTOR			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
342050	FLUX DETECTOR			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
342052	DUAL REMOTE COMPENSATOR			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
342063	STANDBY JET GYRO			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
342064	STANDBY GYRO POWER SUPPLY			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
342066 LEFT BOTTOM	EHSI INDICATOR			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
342066 LEFT TOP	EADI INDICATOR			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
342067	MFD DISPLAY	KCHA		PN NOT INSTALLED	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			
342068	CONTROL DISPLAY			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
342069	MULTI-HAZARD AWARENESS SYSTEM KMH-820	KCHA		066-01175-2102 8006	MTH 06-Jan-2012 HRS 2860.1 LDG 2273		O/C			
342070 BOTTOM	TAS DIRECTIONAL ANTENNA KA 815	KCHA		071-01599-0100 24632	MTH 06-Jan-2012 HRS 2860.1 LDG 2273		O/C	0 0 0		
342070 TOP	TAS DIRECTIONAL ANTENNA KA-815	SAT		071-01599-0100 08859	MTH 22-Aug-2002 HRS 1220		O/C	0		
342070	KCM805 CONFIGURATION MODULE KCM-805	SMF		071-00112-0200 1077	MTH 25-Feb-2005 HRS 1922		O/C	0		
342074	TAWS ANNUNCIATOR --	KCHA		PN NOT INSTALLED	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			
343401	GAD 43E ADAPTER --	KFCM		011-02349-00 1V7054749	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C	0 0 0		
344000	GWX 75 WEATHER RADAR --	KFCM		011-03997-00 4RR005968	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C	0 0 0		
344001	ANTENNA GLIDESLOPE COUPLER *CF			82-70-01 812	MTH 01-Sep-1998		O/C			
344004	ARRAY RADAR ANTENNA			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
344005	RADAR TRANSCEIVER			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
344007	FMS CONFIGURATION MODULE			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
344021	RADIO MAGNETIC INDICATOR			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
344022	RADIO ALTIMETER RECEIVER/TRANSMITTER KRA-405B	ICT		066-01153-0101 2081	MTH 24-Nov-1999 HRS 427		O/C	0		
344023 NO. 1	DUAL NAVIGATION CONVERTER			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
344024	RADIO ALTIMETER INDICATOR			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
345000 NO. 1	GMA-35 AUDIO CONTROL PANEL PANEL KCHA			011-02299-40 1T6202831	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			
345001 FORWARD	DME #1 ANTENNA *CF			56-80-01 7637	MTH 01-Sep-1998		O/C			
345002 NO. 1	DME RECEIVER/TRANSMITTER KN-63 *CF			066-01070-0001 13997	MTH 01-Sep-1998		O/C			
345003 LEFT	DME INDICATOR			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
345004 NO. 1	TRANSPONDER ANTENNA KA-60 *CF			071-01174-0000 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
345004 NO. 2	TRANSPONDER ANTENNA KA-60 *CF			071-01174-0000 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
345005	MARKER BEACON ANTENNA *CF			31-10-01 2847	MTH 01-Sep-1998		O/C			
345006	GLIDESLOPE ANTENNA *CF			44-70-01 A5731	MTH 01-Sep-1998		O/C			
345009 #2	DIPLEXER KCHA			CI-507 611873	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			
345009	DIPLEXER KCHA			CI-507 611872	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			
345011 NO. 1	ADF RECEIVER KCHA			PN NOT INSTALLED	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			
345012 NO. 1	ADF ANTENNA KCHA			PN NOT INSTALLED	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			
345020 BOTTOM	VHF NAV 2 RECEIVER KCHA			PN NOT INSTALLED	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			
345020 TOP	VHF NAV 1 RECEIVER KCHA			PN NOT INSTALLED	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			
345022 LEFT	NAVIGATION ANTENNA C598505-0303 *CF			22-37-101 2121	MTH 01-Sep-1998		O/C			
345022 RIGHT	NAVIGATION ANTENNA C598505-0303 *CF			22-37-101 2102	MTH 01-Sep-1998		O/C			
345034 NO. 1	TRANSPONDER KCHA			011-03303-00 3EH020064	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			
345034 NO. 2	TRANSPONDER KCHA			011-03303-00 3EH022573	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
345038X	GNS-X CDU	KCHA	7	PN NOT INSTALLED	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			
345039 RIGHT	GPS 2 ANTENNA GA 37	KCHA		013-00245-00 19182	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			
345039	GPS 1 ANTENNA GA-35	KCHA		013-00235-00 146207	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			
345040	NAV DATA BASE GPS KLN-90	*CF		071-01523-0003 36851	MTH 01-Sep-1998		O/C			
345044	CONFIGURATION MODULE *CF			17680-01 9549	MTH 01-Sep-1998		O/C			
345051	ARGUS 7000 --	KCHA		PN NOT INSTALLED	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			
345055	JETTECH GPS CONVERTER KCHA			1201-4000-01 1910148	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			
345061 NO. 1	GTN-750 GARMIN			010-02002-03 5FR001751	MTH 12-Jun-2020		O/C			
345061 NO. 2	GTN-750 GARMIN			010-02002-03 5FR001791	MTH 12-Jun-2020		O/C			
346001 NO. 1	GPS RECEIVER	KCHA		PN NOT INSTALLED	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			
346005	STORMSCOPE DISPLAY KCHA			PN NOT INSTALLED	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			
346007	STORMSCOPE ANTENNA KCHA			PN NOT INSTALLED	MTH 24-Dec-2019 HRS 3537.4 LDG 2946		O/C			
346009	COMPUTER-AIR DATA --			PN NOT INSTALLED	MTH 14-May-2025 HRS 4138.2 LDG 3483		O/C			
350006	OXYGEN BOTTLE DOT-E 8162	KCRG		176274-50 0565-4951	MTH 02-Mar-2021 HRS 3646.7 LDG 3124		180	122 0 0	31-Jan-2026	7 m 21 d
Manufacture Date: 01-Jan-2011										
350007	OXYGEN PRESSURE GAGE MD-97	*CF		C668512-0101 D98263	MTH 01-Sep-1998		O/C			
351002 COPILOT	COPILOT CREW OXYGEN MASK RESTORATION KEAU			MC10-16-101 101411	MTH 08-Mar-2023 HRS 3860.2 LDG 3266		72	0	31-Mar-2029	45 m 21 d
351002 PILOT	PILOT CREW OXYGEN MASK RESTORATION 9914067-41	7FL6		MC10-16-101 116570	MTH 09-Jan-2024 HRS 3957.5 LDG 3358		72	0	31-Jan-2030	55 m 21 d
351004 LEFT	ALTITUDE PRESSURE SWITCH 9912057-5	*CF		P24031 1860	MTH 01-Sep-1998		O/C			
351008	OXYGEN 3 POSITION VALVE 9912057-21	*CF		110081-06 459	MTH 01-Sep-1998		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
361001 LEFT	TEMPERATURE SENSOR *CF			27431501-05 5AP55	MTH 01-Sep-1998		O/C			
361001 RIGHT	TEMPERATURE SENSOR *CF			27431501-05 5AP53	MTH 01-Sep-1998		O/C			
361002 LEFT	B/A PRECOOLER ASSEMBLY 9914402-6	KCHA		8161-5 T0470	MTH 24-Aug-2017 HRS 3403.3 LDG 2815 ACH 2023.8		3200	0 0	6603.3	2463.6
361002 RIGHT	B/A PRECOOLER ASSEMBLY 9914402-6	KCHA		8161-5 T0477	MTH 24-Aug-2017 HRS 3403.3 LDG 2815 ACH 2023.8		3200	0 0	6603.3	2463.6
361004 LEFT	PNEUMATIC SHUTOFF VALVE ASSY 9912421-1	*CF		4713-2 560	MTH 01-Sep-1998		O/C			
361004 RIGHT	PNEUMATIC SHUTOFF VALVE ASSY 9912421-1	*CF		4713-2 562	MTH 01-Sep-1998		O/C			
361006	PRESSURE BLEED AIR REGULATOR 9912043-4	GSO		1H75-16 5AN26	MTH 27-Apr-2005 HRS 1968		O/C	0		
361007 LEFT	OVER TEMP BLEED AIR SWITCH 9914149-2	*CF		1173T181-2 1567	MTH 01-Sep-1998		O/C			
361007 RIGHT	OVER TEMP BLEED AIR SWITCH 9914149-2	*CF		1173T181-2 1594	MTH 01-Sep-1998		O/C			
361007	DOOR SEAL CONTROL VALVE KCHA			MJV3 N/A	MTH 08-May-2013 HRS 2997.9 LDG 2401		O/C	0 0 0		
361008 LEFT	PRECOOLER DOOR VALVE *CF			5060-00-01 861	MTH 01-Sep-1998		O/C			
361008 RIGHT	PRECOOLER DOOR VALVE *CF			5060-00-01 867	MTH 01-Sep-1998		O/C			
361009 LEFT	CHECK VALVE *CF			1989-00-5 597	MTH 01-Sep-1998		O/C			
361009 RIGHT	CHECK VALVE *CF			1989-00-5 600	MTH 01-Sep-1998		O/C			
361010 LEFT	CHECK VALVE *CF			1553-00-18 1635	MTH 01-Sep-1998		O/C			
361010 RIGHT	CHECK VALVE *CF			1553-00-18 1640	MTH 01-Sep-1998		O/C			
361011 LEFT	PRECOOLER ACTUATOR *CF			6312213-5 12AN120	MTH 01-Sep-1998		O/C			
361012 RIGHT	PRECOOLER ACTUATOR *CF			6312213-6 3AP8	MTH 01-Sep-1998		O/C			
383001	FLUSHING TOILET ASSEMBLY GSO			17000-426 11020377	MTH 08-Oct-2004 HRS 1818		O/C	0		
521000	CABIN ENTRY DOOR			PN SN-UNKNOWN	MTH 01-Sep-1998		O/C	0		
522001	DOOR INFLATABLE SEAL KEAU			9912075-4 3891	MTH 07-Jun-2023 HRS 3912.8 LDG 3323		O/C	0 0		
522002	SECONDARY SEAL *CF			R441253 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
522003	ESCAPE HATCH SEAL *CF			R441236 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
522004	PRESSURE SWITCH KGSO			P18M-30 6380	MTH 31-Oct-2020 HRS 3624.2 LDG 3009		O/C	0 0 0		



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
522005	EMERGENCY ESCAPE HATCH			PN SN-UNKNOWN	MTH 01-Sep-1998		H/T H/T	0		
531000 LEFT	TRUNNION SUPPORT FITTING *CF			5513056-5 SN-UNKNOWN	MTH 01-Sep-1998 LDG 0		22500	0	22500	19014
531000 RIGHT	TRUNNION SUPPORT FITTING *CF			5513056-6 SN-UNKNOWN	MTH 01-Sep-1998 LDG 0		22500	0	22500	19014
531001	ACTUATOR SUPPORT FITTING *CF			6511105-1 SN-UNKNOWN	MTH 01-Sep-1998 LDG 0		22500	0	22500	19014
531201	RADOME ASSEMBLY *CF			6313101-47 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
541001 LEFT ENGINE	INLET *CF			6352100-56 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
541001 RIGHT ENGINE	INLET *CF			6352100-56 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
561001 LEFT	WINDSHIELD ASSY, (LH) 9912064-15 *CF			E149000-101 4687	MTH 01-Sep-1998		O/C			
561001 RIGHT	WINDSHIELD ASSY, (RH) 9912064-16 *CF			E149000-102 4656	MTH 01-Sep-1998		O/C			
561002 L1	CABIN DOOR WINDOW *CF			161100-03 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
561002 L2	CABIN WINDOW *CF			161100-03 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
561002 L3	CABIN WINDOW 9912207-8 *CF			161100-03 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
561002 L4	CABIN WINDOW 9912207-8 *CF			161100-03 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
561002 R1	CABIN WINDOW 9912207-8 *CF			161100-03 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
561002 R2	CABIN WINDOW 9912207-8 *CF			161100-03 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
561002 R3	CABIN WINDOW 9912207-8 *CF			161100-03 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
561002 R4	CABIN WINDOW 9912207-8 *CF			161100-03 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
561003 PILOT	SIDE WINDOW GSO			6311065-27 01671100	MTH 28-Sep-2001 HRS 951		O/C	0		
561004 COPILOT	SIDE WINDOW *CF			6311065-16 5199802	MTH 01-Sep-1998		O/C			
571000 LEFT AFT	TRUNNION ATTACH FITTING *CF			6322070-17 SN-UNKNOWN	MTH 01-Sep-1998 LDG 0		28300	0	28300	24814
571000 RIGHT AFT	TRUNNION ATTACH FITTING *CF			6322070-16 SN-UNKNOWN	MTH 01-Sep-1998 LDG 0		28300	0	28300	24814
571001 LEFT FORWARD	TRUNNION ATTACH FITTING *CF			6322060-15 SN-UNKNOWN	MTH 01-Sep-1998 LDG 0		28300	0	28300	24814
571001 RIGHT FORWARD	TRUNNION ATTACH FITTING *CF			6322060-16 SN-UNKNOWN	MTH 01-Sep-1998 LDG 0		28300	0	28300	24814
571002 LEFT	SIDE BRACE FITTING *CF			6322080-13 SN-UNKNOWN	MTH 01-Sep-1998 LDG 0		28300	0	28300	24814
571002 RIGHT	SIDE BRACE FITTING *CF			6322080-14 SN-UNKNOWN	MTH 01-Sep-1998 LDG 0		28300	0	28300	24814
573010	LRU ANNUNCIATOR ASSEMBLY -- KSZT			100-39-0200_R-G 1119	MTH 11-May-2021 HRS 3664.5 LDG 3139		O/C	0 0		
573011	ADS TCU ASSEMBLY - LEFT -- KSZT			100-57-0300-04_R-F 1285	MTH 11-May-2021 HRS 3664.5 LDG 3139		A/R	0 0		



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
573012	ADS TCU ASSEMBLY - RIGHT -- KEAU			100-57-0300-04 1449	MTH 03-Jul-2024 HRS 3991.1 LDG 3392		A/R	0 0		
573013	WING EXTENSION - LEFT -- KSZT			100-57-1100-01_R-R 134	MTH 11-May-2021 HRS 3664.5 LDG 3139		O/C	0		
573014	WING EXTENSION - RIGHT -- KSZT			100-57-1100-02_R-R 134	MTH 11-May-2021 HRS 3664.5 LDG 3139		O/C	0		
573015	TACS ASSEMBLY - LEFT -- KSZT			101-57-1400-01_R-M 86	MTH 11-May-2021 HRS 3664.5 LDG 3139		O/C	0 0		
573016	TACS ASSEMBLY - RIGHT -- KSZT			101-57-1400-02_R-M 87	MTH 11-May-2021 HRS 3664.5 LDG 3139		O/C	0 0		
573017	ACU ASSEMBLY -- KSZT			100-39-0100_R-C 1081	MTH 11-May-2021 HRS 3664.5 LDG 3139		O/C	0 0		
573018	WINGLET ASSEMBLY - LEFT -- KSZT			101-57-1700-01_R-M 1700-01-0025	MTH 11-May-2021 HRS 3664.5 LDG 3139		O/C	0 0		
573019	WINGLET ASSEMBLY - RIGHT -- KSZT			101-57-1700-02_R-M 1700-02-0027	MTH 11-May-2021 HRS 3664.5 LDG 3139		O/C	0 0		
712001 LEFT ENGINE AFT	ISOLATOR MOUNT	LNK		9912410-2 LK4191	MTH 15-May-2019 HRS 3537.4 LDG 2946		CSI	0 0 0	7537.5	3397.8
712001 LEFT ENGINE FORWARD BOTTOM	ISOLATOR MOUNT	LNK		9912410-3 6048	MTH 15-May-2019 HRS 3537.4 LDG 2946		CSI	0 0 0	7537.5	3397.8
712001 LEFT ENGINE FORWARD TOP	ISOLATOR MOUNT	LNK		9912410-3 6047	MTH 15-May-2019 HRS 3537.4 LDG 2946		CSI	0 0 0	7537.5	3397.8
712001 RIGHT ENGINE AFT	ISOLATOR MOUNT	LNK		9912410-2 LK4179	MTH 15-May-2019 HRS 3537.4 LDG 2946		CSI	0 0 0	7537.5	3397.8
712001 RIGHT ENGINE FORWARD BOTTOM	ISOLATOR MOUNT	LNK		9912410-3 6046	MTH 15-May-2019 HRS 3537.4 LDG 2946		CSI	0 0 0	7537.5	3397.8
712001 RIGHT ENGINE FORWARD TOP	ISOLATOR MOUNT	LNK		9912410-3 6045	MTH 15-May-2019 HRS 3537.4 LDG 2946		CSI	0 0 0	7537.5	3397.8
71EN1 NO. 1 710001 : E1**L	ENGINE	GSO		45700-104 1553	MTH 02-Nov-2003 HRS 1539		E/C	1539		



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE	GSO		45700-104 1554	MTH 02-Nov-2003 HRS 1539		E/C	1539		
720007 E1	1ST LP TURBINE NOZZLE	GSO		57375 GD947B	MTH 02-Nov-2003 HRS 1539		O/C	1539		
720007 E2	1ST LP TURBINE NOZZLE	UNK		115539 AU20353	MTH 07-May-2019 HRS 3537.4 LDG 2946		O/C	0 0 4		
723001 E1	FAN ROTOR	GSO		59070 AU00251	MTH 02-Nov-2003 HRS 1539 LDG 1047		16500	1047	16500	13014
723001 E2	FAN ROTOR	GSO		59070 AU00288	MTH 02-Nov-2003 HRS 1539 LDG 1047		16500	1047	16500	13014
723010 E1	HP COMPRESSOR ROTOR	UNK		123505 LC1461	MTH 09-May-2019 HRS 3537.4 LDG 2951		10000	3736.1 3650	9301	5815
723010 E2	HP COMPRESSOR ROTOR	UNK		123506 LC2581	MTH 07-May-2019 HRS 3537.4 LDG 2951		10000	4244.4 3792	9159	5673
723015 E1	IP COMPRESSOR ROTOR	GSO		66032 HW14985	MTH 02-Nov-2003 HRS 1539 LDG 1047		10000	132	10915	7429
723015 E2	IP COMPRESSOR ROTOR	GSO		66032 HW15021	MTH 02-Nov-2003 HRS 1539 LDG 1047		10000	132	10915	7429
723019 E2	INTERSTAGE HOUSING ASSEMBLY	UNK		50930 RC1527	MTH 07-May-2019 HRS 3537.4 LDG 2946		O/C	4267.5 3820		
723022 E1	DIFFUSER CASE ASSEMBLY	GSO		59906 AU00791	MTH 02-Nov-2003 HRS 1539		O/C	1539		
723022 E2	DIFFUSER CASE ASSEMBLY	GSO		59906 AU00795	MTH 02-Nov-2003 HRS 1539		O/C	1539		
723061 E1	HIGH PRESSURE SHAFT 200	GSO		55667 GG795	MTH 02-Nov-2003 HRS 1539		O/C	1539		
723061 E2	HIGH PRESSURE SHAFT 200	GSO		55667 GG825	MTH 02-Nov-2003 HRS 1539		O/C	1539		
723092 E1	COMPLETE LP SHAFT ASSEMBLY 40	GSO		50865 RXISM9738	MTH 02-Nov-2003 HRS 1539		O/C	1539		
723092 E2	COMPLETE LP SHAFT ASSEMBLY 40	GSO		50865 RXISM9739	MTH 02-Nov-2003 HRS 1539		O/C	1539		
723149 E1	HP COMPRESSOR COVER ASSY	GSO		50778 -	MTH 02-Nov-2003 HRS 1539		O/C	1539		
723149 E2	HP COMPRESSOR COVER ASSY	GSO		50778 -	MTH 02-Nov-2003 HRS 1539		O/C	1539		
724035 E1	HP TURBINE ROTOR ASSEMBLY	UNK		74149 RRL0753	MTH 09-May-2019 HRS 3537.4 LDG 2946		O/C	3537.4 2951		



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
724035 E2	HP TURBINE ROTOR ASSEMBLY	UNK		74149 RRL0754	MTH 07-May-2019 HRS 3537.4 LDG 2946		O/C	3537.4 2950		
724040 E1	REAR FUEL SLINGER SEAL ASSEMBLY	UNK		115471 AU21157	MTH 09-May-2019 HRS 3537.4 LDG 2946		O/C			
724040 E2	REAR FUEL SLINGER SEAL ASSEMBLY	UNK		115471 AU20818	MTH 07-May-2019 HRS 3537.4 LDG 2946		O/C	1168 815		
725010 E1	HP TURBINE DISK	GSO		59494 RRL7FDKJ	MTH 02-Nov-2003 HRS 1539 LDG 1047		8000 8000	1525 1047	8014 8000	3874.3 4514
725010 E2	HP TURBINE DISK	GSO		59494 RL7FDZL	MTH 02-Nov-2003 HRS 1539 LDG 1047		8000 8000	1525 1047	8014 8000	3874.3 4514
725016 E1	NOZZLE, 2ND LP TURBINE HOUSING ASSEMBLY	UNK		56310 AU01096	MTH 09-May-2019 HRS 3537.4 LDG 2946		O/C	2991.9 2282		
725016 E2	NOZZLE, 2ND LP TURBINE HOUSING ASSEMBLY	UNK		56310 AU01576	MTH 07-May-2019 HRS 3537.4 LDG 2946		O/C	1824.3 1713		
725020 E1	1ST LP TURBINE DISK 411	GSO		50255 RRL7FEXL	MTH 02-Nov-2003 HRS 1539 LDG 1047		14700	1047	14700	11214
725020 E2	1ST LP TURBINE DISK 411	GSO		50255 RRL7FEXS	MTH 02-Nov-2003 HRS 1539 LDG 1047		14700	1047	14700	11214
725030 E1	2ND LP TURBINE DISK 551	GSO		50792 RRL7FEVA	MTH 02-Nov-2003 HRS 1539 LDG 1047		13500	1047	13500	10014
725030 E2	2ND LP TURBINE DISK 551	GSO		50792 RRL7FEUX	MTH 02-Nov-2003 HRS 1539 LDG 1047		13500	1047	13500	10014
726011 E1	ACCESSORY DRIVE GEARBOX ASSEMBLY	KCHA		115283 WL01502	MTH 15-Aug-2016 HRS 3361.5 LDG 2766		O/C	0 6569		
726011 E2	ACCESSORY DRIVE GEARBOX ASSEMBLY	KCHA		115283 WL01935	MTH 15-Aug-2016 HRS 3361.5 LDG 2766		O/C	0 2477		
730001 LEFT ENGINE	FUEL PRESSURE SWITCH 9912033-2 *CF			1103P0448 3475	MTH 01-Sep-1998		O/C			
730001 RIGHT ENGINE	FUEL PRESSURE SWITCH 9912033-2 *CF			1103P0448 34617	MTH 01-Sep-1998		O/C			
732002	SYNCHRONIZER CONTROLLER *CF			213693 12077348	MTH 01-Sep-1998		O/C			
732003	ENGINE SYNCHRONIZER ACTUATOR *CF			5485-066 12023766	MTH 01-Sep-1998		O/C			
733001 LEFT ENGINE	FUEL FLOW TRANSMITTER 9912417-1 *CF			1573-4 621	MTH 01-Sep-1998		O/C			
733001 RIGHT ENGINE	FUEL FLOW TRANSMITTER 9912417-1 *CF			1573-4 620	MTH 01-Sep-1998		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
730002 E1	FUEL NOZZLE ASSEMBLY 115	UNK		50817 BCC-00007129	MTH 09-May-2019 HRS 3537.4 LDG 2946		O/C	0 0 5		
730002 E2	FUEL NOZZLE ASSEMBLY 115	GSO		50817 BCCITM04964	MTH 02-Nov-2003 HRS 1539		O/C	1539		
731001 E1	FUEL PUMP 640	GSO		54904 YYK0857	MTH 02-Nov-2003 HRS 1539		6000	1539	6000	1860.3
731001 E2	FUEL PUMP 640	GSO		54904 YYK0860	MTH 02-Nov-2003 HRS 1539		6000	1539	6000	1860.3
732090 E1	START NOZZLE CONTROL VALVE 625	UNK		50803 RF12160631	MTH 09-May-2019 HRS 3537.4 LDG 2946		6000	0 6804.5 4552	9537.4	5397.7
732090 E2	START NOZZLE CONTROL VALVE 625	UNK		50803 RF2336464	MTH 07-May-2019 HRS 3537.4 LDG 2946		6000	0 9993.1 6667	9537.4	5397.7
732301 E1	ELEC FUEL FILTER INDICATOR UNK	UNK		57847 GE2864	MTH 09-May-2019 HRS 3537.4 LDG 2946		O/C			
732301 E2	ELEC FUEL FILTER INDICATOR GSO	GSO		57847 GE0266	MTH 02-Nov-2003 HRS 1539		O/C	1539		
732401 E1	FUEL CONTROL (HMU) UNIT 630	GSO		55629 11485558	MTH 02-Nov-2003 HRS 1539		6000	1057	6482	2342.3
732401 E2	FUEL CONTROL (HMU) UNIT 630	GSO		55629 2335074	MTH 02-Nov-2003 HRS 1539		6000	1057	6482	2342.3
741010 E1 INBOARD	IGNITION EXCITER GSO	GSO		56635 CK9800243	MTH 02-Nov-2003 HRS 1539		O/C	1539		
741010 E2 INBOARD	IGNITION EXCITER GSO	GSO		56635 CK9800185	MTH 02-Nov-2003 HRS 1539		O/C	1539		
741020 E1 OUTBOARD	IGNITION EXCITER GSO	GSO		CH92007-1 CK0000601	MTH 08-Oct-2004 HRS 1818		O/C	0		
741020 E2 OUTBOARD	IGNITION EXCITER GSO	GSO		56635 CK9800191	MTH 02-Nov-2003 HRS 1539		O/C	1539		
742001 E1	SHORT IGNITOR LEAD GSO	GSO		50852 SN-UNKNOWN	MTH 02-Nov-2003 HRS 1539		O/C	1539		
742001 E2	SHORT IGNITOR LEAD GSO	GSO		50852 SN-UNKNOWN	MTH 02-Nov-2003 HRS 1539		O/C	1539		
742002 E1	LONG IGNITOR LEAD GSO	GSO		50853 SN-UNKNOWN	MTH 02-Nov-2003 HRS 1539		O/C	1539		
742002 E2	LONG IGNITOR LEAD GSO	GSO		50853 SN-UNKNOWN	MTH 02-Nov-2003 HRS 1539		O/C	1539		
742201 E1 INBOARD	IGNITOR KEAU	KEAU		68032 CK-190577	MTH 27-Feb-2023 HRS 3858 LDG 3263		O/C			
742201 E1 OUTBOARD	IGNITOR KEAU	KEAU		68032 CK-1905612	MTH 27-Feb-2023 HRS 3858 LDG 3263		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
742201 E2 INBOARD	IGNITOR	UNK		68032 CK-1802518	MTH 07-May-2019 HRS 3537.4 LDG 2946		O/C	0 0 4		
742201 E2 OUTBOARD	IGNITOR	UNK		68032 CK-1802517	MTH 07-May-2019 HRS 3537.4 LDG 2946		O/C	0 0 4		
761000 LH	AFT THROTTLE CONTROL ASSEMBLY	KCHA		7-45016-30 J1624-5	MTH 24-Jan-2012 HRS 2869.3 LDG 2277		O/C	0 0 0		
771003 STANDBY	N1 INDICATOR 9912399-8	GSO		10272N05M00 9710560	MTH 13-Dec-2000 HRS 741		O/C	107		
771005 E1	N1 DUAL MAGNETIC SPEED SENSOR 740	GSO		50867 YYV179	MTH 02-Nov-2003 HRS 1539		O/C	1539		
771005 E2	N1 DUAL MAGNETIC SPEED SENSOR 740	GSO		50867 YYV176	MTH 02-Nov-2003 HRS 1539		O/C	1539		
771015 E1	N2 DUAL MAGNETIC SPEED SENSOR 750	GSO		50866 YYV360	MTH 02-Nov-2003 HRS 1539		O/C	1539		
771015 E2	N2 DUAL MAGNETIC SPEED SENSOR 750	GSO		50866 YYV363	MTH 02-Nov-2003 HRS 1539		O/C	1539		
772001 E1 NO. 1	ITT PROBE 680	GSO		55631-S YYF001983	MTH 02-Nov-2003 HRS 1539		O/C	1539		
772001 E1 NO. 2	ITT PROBE 680	GSO		55633-L YYF001516	MTH 02-Nov-2003 HRS 1539		O/C	1539		
772001 E1 NO. 3	ITT PROBE 680	GSO		62142 YYF002517	MTH 02-Nov-2003 HRS 1539		O/C	0		
772001 E1 NO. 4	ITT PROBE 710	GSO		55631-S YYF001985	MTH 02-Nov-2003 HRS 1539		O/C	1539		
772001 E1 NO. 5	ITT PROBE 711	GSO		55633-L YYF001517	MTH 02-Nov-2003 HRS 1539		O/C	1539		
772001 E1 NO. 6	ITT PROBE 712	GSO		55631-S YYF001986	MTH 02-Nov-2003 HRS 1539		O/C	1539		
772001 E2 NO. 1	ITT PROBE 682	GSO		62142 YYF002518	MTH 02-Nov-2003 HRS 1539		O/C	0		
772001 E2 NO. 2	ITT PROBE 682	GSO		62142 YYF002520	MTH 02-Nov-2003 HRS 1539		O/C	0		
772001 E2 NO. 3	ITT PROBE 682	GSO		55631-S YYF001988	MTH 02-Nov-2003 HRS 1539		O/C	1539		
772001 E2 NO. 4	ITT PROBE 710	GSO		55631-S YYF001989	MTH 02-Nov-2003 HRS 1539		O/C	1539		
772001 E2 NO. 5	ITT PROBE 711	GSO		55633-L YYF001519	MTH 02-Nov-2003 HRS 1539		O/C	1539		



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
772001 E2 NO. 6	ITT PROBE 712	GSO		55631-S YYF001970	MTH 02-Nov-2003 HRS 1539		O/C	1539		
772002 E1	ITT HARNESS	UNK		75378 EMX004292	MTH 09-May-2019 HRS 3537.4 LDG 2946		O/C	0 0 5		
772002 E2	ITT HARNESS	UNK		75378 EMX004275	MTH 07-May-2019 HRS 3537.4 LDG 2946		O/C	0 0 4		
781001 LEFT	EXHAUST NOZZLE	*CF		6352350-20 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
781001 RIGHT	EXHAUST NOZZLE	*CF		6352350-20 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
783001 LEFT	T/A SWITCH	*CF		602EN602-6 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
783001 RIGHT	T/A SWITCH	*CF		602EN602-6 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
783002 LEFT	T/A PADDLE ASSY	KCHA		6354051-79 N/A	MTH 24-Aug-2017 HRS 3403.3 LDG 2815		O/C	0 0 0		
783002 RIGHT	T/A PADDLE ASSY	GSO		6354051-79-1 SN-UNKNOWN	MTH 27-Apr-2005 HRS 1968		O/C	0		
783003 LEFT	ATTENUATOR ACTUATOR	*CF		6317105-10 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
783003 RIGHT	ATTENUATOR ACTUATOR	*CF		6317105-10 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
783005 LEFT	THRUST ATTENUATOR BELLCRANK	*CF		6354051-59 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
783005 RIGHT	THRUST ATTENUATOR BELLCRANK	*CF		6354051-60 SN-UNKNOWN	MTH 01-Sep-1998		O/C			
793001	OIL TEMPERATURE/PRESSURE N2 SENSOR	KCHA		9912399-9 9807605	MTH 30-Mar-2016 HRS 3310.5 LDG 2715		O/C	5 0 0		
793002 LEFT ENGINE	OIL TEMPERATURE TRANSMITTER	*CF		MS28034-3 95308	MTH 01-Sep-1998		O/C			
793002 RIGHT ENGINE	OIL TEMPERATURE TRANSMITTER	*CF		MS28034-3 95314	MTH 01-Sep-1998		O/C			
793004 LEFT ENGINE	OIL PRESSURE TRANSMITTER	*CF		APTE-281A-1000- 100G 57736205	MTH 01-Sep-1998		O/C			
793004 RIGHT ENGINE	OIL PRESSURE TRANSMITTER	CHA		APTE-281A-1000- 100G 62685272	MTH 18-Aug-2007 HRS 2471		O/C	0		
793006 LEFT ENGINE	OIL PRESSURE SWITCH	*CF		S1103P89-3 625	MTH 01-Sep-1998		O/C			
793006 RIGHT ENGINE	OIL PRESSURE SWITCH	ICT		S1103P89-3 2098	MTH 22-Sep-1998 HRS 39		O/C	0		
792201 E1	LUBE OIL COOLER	GSO		59866 PP0086	MTH 02-Nov-2003 HRS 1539		O/C	1539		
792201 E2	LUBE OIL COOLER	GSO		59866 PP0088	MTH 02-Nov-2003 HRS 1539		O/C	1539		



## CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

### Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
792401 E1	LUBE AND SCAVENGE PUMP UNK	56666 WL01217	MTH HRS LDG	09-May-2019 3537.4 2946			6000	0 3477.5 2951	9537.4	5397.7
792401 E2	LUBE AND SCAVENGE PUMP UNK	56666 WL01245	MTH HRS LDG	07-May-2019 3537.4 2946			6000	0 7008.1 3903	9537.4	5397.7
801101 LEFT ENGINE	STARTER/GENERATOR 9912125-2 KCHA	300SGL129Q 1480XL2	MTH HRS LDG ACH	07-Oct-2016 3367.5 2775 1995.9			1000	0 0 0	4367.5	227.8
801101 RIGHT ENGINE	STARTER/GENERATOR 9912125-2 KCHA	300SGL129Q 4237XL2	MTH HRS LDG	09-Nov-2017 3423.6 2832			1000	0 0 0	4423.6	283.9



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC)			INFORMATIONAL			-			
	<b>MOC :</b>									
SL CIL-99-03 R01	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED			-			
	<b>MOC :</b>									
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED MTH			-			
	<b>MOC :</b>									
SL 525-99-02 R05	CESCOM PRICES (THIS SL CANCELS SL525-99-02 R4 AND PREVIOUS)			INFORMATIONAL			-			
	<b>MOC :</b>									
SL 525-99-05	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL			A/R			
	<b>MOC :</b>									
SL 525-99-06	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			A/R			
	<b>MOC :</b>									
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
	<b>MOC :</b>									
SL 525-03-01 R01	SUPPLEMENTAL TYPE CERTIFICATE (THIS SL IS REPLACED BY CIL-03-01, DATED JUNE 3, 2013)			INFORMATIONAL			-			
	<b>MOC :</b>									
SL 525-99-10	MISCELLANEOUS - TRANSMITTAL OF ROCKWELL COLLINS OPERATORS BULLETIN (OPSB) 0166-17 - THE FMS MAY TURN IN THE WRONG DIRECTION AFTER SEQUENCING A "CLIMB TO" ALTITUDE THAT WAS MANUALLY EDITED OR TEMPERATURE COMPENSATED			INFORMATIONAL			-			
	<b>MOC :</b>									
SL 525-05-03 05SL-03	NEW 525 TASK BASED INSPECTION PROGRAM	CHA		MANDATORY	MTH 26-Jan-2007 HRS 2356		A/R			Complete
	<b>MOC :</b> COMPLIED WITH									
SL 525-05-05	PRECOOLER LIFE LIMIT	KCHA		INFORMATIONAL	MTH 24-Aug-2017 HRS 3403.3 LDG 2815		-			Complete
	<b>MOC :</b> COMPLIED WITH - C/W BY REPLACEMENT OF THE LEFT AND RIGHT PRECOOLER ASSEMBLIES. SEE LOG ENTRY THIS DATE.									
SB FJ44-05-002 R04 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	<b>MOC :</b>									
SB FJ44-05-002 R04 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	<b>MOC :</b>									
SB FJ44-05-002 R05-CN E1	SUPERSEDED - UNSERVICEABLE PARTS - NOTIFICATION (THIS SERVICE DOCUMENT HAS BEEN SUPERSEDED BY WIPSID-05-1000)			CANCELLED			-			
	<b>MOC :</b>									
SB FJ44-05-002 R05-CN E2	SUPERSEDED - UNSERVICEABLE PARTS - NOTIFICATION (THIS SERVICE DOCUMENT HAS BEEN SUPERSEDED BY WIPSID-05-1000)			CANCELLED			-			
	<b>MOC :</b>									
SB FJ44-05-002 R05 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-05-002 R05 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
<b>MOC :</b>										
SB FJ44-05-002 E1	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R01)			INFORMATIONAL			-			
<b>MOC :</b>										
SB FJ44-05-002 E2	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R01)			INFORMATIONAL			-			
<b>MOC :</b>										
PSID WI-05-1000 R04 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
<b>MOC :</b>										
PSID WI-05-1000 R04 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
<b>MOC :</b>										
PSID WI-05-1000 R05 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
<b>MOC :</b>										
PSID WI-05-1000 R05 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
<b>MOC :</b>										
PSID WI-05-1000 R06 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
<b>MOC :</b>										
PSID WI-05-1000 R06 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
<b>MOC :</b>										
PSID WI-05-1003 R01 E1	TIME LIMITS/MAINTENANCE CHECKS - FORMS						-			
<b>MOC :</b>										
PSID WI-05-1003 R01 E2	TIME LIMITS/MAINTENANCE CHECKS - FORMS						-			
<b>MOC :</b>										
PSID WI-05-1003 R03 E1	TIME LIMITS/MAINTENANCE CHECKS - FORMS						-			
<b>MOC :</b>										
PSID WI-05-1003 R03 E2	TIME LIMITS/MAINTENANCE CHECKS - FORMS						-			
<b>MOC :</b>										
PSID WI-05-1003 E1	TIME LIMITS/MAINTENANCE CHECKS - FORMS						-			
<b>MOC :</b>										
PSID WI-05-1003 E2	TIME LIMITS/MAINTENANCE CHECKS - FORMS						-			
<b>MOC :</b>										
SL WI-05-1009-CN E1	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL WI-05-1009-CN E2	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	<b>MOC :</b>									
SL WI-05-1009 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL						-			
	<b>MOC :</b>									
SL WI-05-1009 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL						-			
	<b>MOC :</b>									
SL WI-05-1020 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL						-			
	<b>MOC :</b>									
SL WI-05-1020 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL						-			
	<b>MOC :</b>									
SL WI-05-1021-CN E1	CANCELED-TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	<b>MOC :</b>									
SL WI-05-1021-CN E2	CANCELED-TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	<b>MOC :</b>									
SL WI-05-1021 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL						-			
	<b>MOC :</b>									
SL WI-05-1021 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL						-			
	<b>MOC :</b>									
SL WI-05-1022 E1	TIME LIMITS/MAINTENANCE CHECKS - UNSERVICEABLE PARTS - REVISION TO LINE MAINTENANCE MANUAL						-			
	<b>MOC :</b>									
SL WI-05-1022 E2	TIME LIMITS/MAINTENANCE CHECKS - UNSERVICEABLE PARTS - REVISION TO LINE MAINTENANCE MANUAL						-			
	<b>MOC :</b>									
SL WI-05-1092-CN E1	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	<b>MOC :</b>									
SL WI-05-1092-CN E2	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	<b>MOC :</b>									
SL WI-05-1092 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL						-			
	<b>MOC :</b>									
SL WI-05-1092 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL						-			
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl	Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL WI-05-1149 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL									
	<b>MOC :</b>									
SL WI-05-1149 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL									
	<b>MOC :</b>									
SL WI-05-1173-CN E1	CANCELLED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL									
	CANCELLED									
	<b>MOC :</b>									
SL WI-05-1173-CN E2	CANCELLED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL									
	CANCELLED									
	<b>MOC :</b>									
SL WI-05-1194-CN E1	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL									
	CANCELLED									
	<b>MOC :</b>									
SL WI-05-1194-CN E2	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL									
	CANCELLED									
	<b>MOC :</b>									
SL WI-05-1198 R01 E1	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL									
	<b>MOC :</b>									
SL WI-05-1198 R01 E2	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL									
	<b>MOC :</b>									
SL WI-05-1198 E1	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL									
	<b>MOC :</b>									
SL WI-05-1198 E2	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL									
	<b>MOC :</b>									
SB 525-11-09 11SB-09	FUEL PLACARD RELOCATION		OPTIONAL	MTH						
	<b>MOC :</b>									
SL CIL-99-01 R01	USE OF CORROSION INHIBITING COMPOUNDS									
	INFORMATIONAL									
	<b>MOC :</b>									
SL CIL-99-01 R02	USE OF CORROSION INHIBITING COMPOUNDS									
	INFORMATIONAL									
	<b>MOC :</b>									
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS									
	INFORMATIONAL									
	<b>MOC :</b>									
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS									
	RECOMMENDED									
	<b>MOC :</b>									
SL CIL-20-01 R02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL									
	INFORMATIONAL									
	<b>MOC :</b>									
SL CIL-20-01 R03- CN	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL									
	CANCELLED									
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL INFORMATIONAL				-			
	<b>MOC :</b>							
SL 525-20-01 R18	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL INFORMATIONAL				A/R			
	<b>MOC :</b>							
SL 525-20-05 20SL-05	ELECTRICAL CONNECTOR REPLACEMENT GSO	RECOMMENDED	MTH 28-Sep-2001 HRS 951		-			Complete
	<b>MOC :</b> COMPLIED WITH							
SL 525-20-06	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL INFORMATIONAL				-			
	<b>MOC :</b>							
SB 525-21-13 R01 21SB-13 : 525R1	EVAPORATOR WATER COLLECTION & DRAINAGE OPTIONAL		MTH		-			
	<b>MOC :</b>							
SB 525-21-15 21SB-15	BINARY PRESSURE SWITCH REPLACE GSO	RECOMMENDED	MTH 18-Jul-2001 HRS 903		-			Complete
	<b>MOC :</b> COMPLIED WITH							
SB 525-21-17 R02	FORWARD EVAPORATOR RELAY INSTALLATION OPTIONAL				A/R			
	<b>MOC :</b>							
SB 525-21-17 R03	FORWARD EVAPORATOR REPLAY INSTALLATION OPTIONAL				-			
	<b>MOC :</b>							
SB 525-21-17 21SB-17	FORWARD EVAPORATOR RELAY INSTALLATION OPTIONAL		MTH		A/R			
	<b>MOC :</b>							
SB 525-21-19 21SB-19	TEMPERATURE SENSOR RELOCATION OPTIONAL		MTH		A/R			
	<b>MOC :</b>							
SB 525-21-20 R01	AIR CONDITIONING - BAROMETRIC PRESSURE SWITCH INSTALLATION OPTIONAL				-			
	<b>MOC :</b>							
SB 525-21-20	BAROMETRIC PRESSURE SWITCH INSTALLATION OPTIONAL				-			
	<b>MOC :</b>							
ASL 525-21-01 21SLA01	AIR CONDITIONER GROUND CABLE INSPECTION GSO	MANDATORY	MTH 28-Sep-2001 HRS 951		A/R			Complete
	<b>MOC :</b> COMPLIED WITH							
SL CIL-21-01	COMPRESSOR MOTOR BRUSH LIFE LIMIT INFORMATIONAL				-			
	<b>MOC :</b>							
SB 525-23-08 23SB-08	ALLIEDSIGNAL 8.33 KHZ COMMUNICATION RADIO INSTALLATION OPTIONAL		MTH		-			
	<b>MOC :</b>							
SB 525-23-12 23SB-12	HONEYWELL KY-196A/KY-196B DUAL VHF COMMUNICATION SYSTEM UPGRADE GSO	RECOMMENDED	MTH 02-Nov-2003 HRS 1539		-			Complete
	<b>MOC :</b> COMPLIED WITH							
SB 525-23-13 23SB-13	GARMIN RADIO REPLACEMENT OPTIONAL		MTH		-			
	<b>MOC :</b>							



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 525-23-05 23SL-05	TRANSMITTAL OF ALLIED SIGNAL BENDIX/KING SERVICE BULLETIN KY196A-9 - KY196A VHF COMM TRANSCEIVER	GSO		RECOMMENDED	MTH 18-Jan-2000 HRS 460		-			Complete
<b>MOC : COMPLIED WITH</b>										
SL 525-23-06 23SL-06	TRANSMITTAL OF ALLIED SIGNAL BENDIX/KING SERVICE BULLETIN KY196B-2 - KY196B VHF COMM TRANSCEIVER	GSO		RECOMMENDED	MTH 18-Jan-2000 HRS 460		-			Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE BY COMPONENT SERIAL NUMBER.</b>										
SL 525-23-11	COMMUNICATIONS - ATG 5000 SOFTWARE UPGRADE OPTIONAL						-			
<b>MOC :</b>										
SL 525-23-12	COMMUNICATIONS - ATG 5000 SOFTWARE UPDATE TO VERSION 2.8 OPTIONAL						-			
<b>MOC :</b>										
SB 525-24-07 R02 24SB-07 : 525R2	44 AMP HOUR BATTERY INSTALLATION	GSO		OPTIONAL	MTH 18-Jan-2000 HRS 460		-			Complete
<b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH AT FACTORY OR IS A FACTORY OPTION.</b>										
SB 525-24-17 R01 24SB-17 : 525R1	EXTERNAL POWER REVERSE POLARITY PROTECTION			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 525-24-19 R02 24SB-19 : 525R2	CONCORDE LEAD ACID BATTERY INSTALLATION	MCO		OPTIONAL	MTH 09-Feb-2006 HRS 2143		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 525-24-22 24SB-22	TAILCONE ELECTRICAL GROUND STUD IMPROVEMENT			RECOMMENDED	MTH 21-Apr-2004 HRS 1705		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 525-24-23 24SB-23	AFT CABIN WIRE BUNDLE PROTECTION			RECOMMENDED	MTH 21-Apr-2004 HRS 1705		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 525-24-25 24SB-25	NICKEL-CADMIUM BATTERY INSTALLATION			OPTIONAL	MTH		-			
<b>MOC :</b>										
COM MC 525-007 R01	GENERATOR CONTROL UNIT TROUBLESHOOTING GUIDELINES			INFORMATIONAL	MTH		-			
<b>MOC :</b>										
COM MC 525-007	GENERATOR CONTROL UNIT TROUBLESHOOTING GUIDELINES						-			
<b>MOC :</b>										
SL 525-24-03 24SL-03	IGNITER CONTROL PRINTED/CIRCUIT BOARD INSPECTION	GSO		RECOMMENDED	MTH 13-Feb-2002 HRS 1074		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL 525-24-10	ELECTRICAL POWER - BATTERY TEMPERATURE INDICATOR GAGE BLANKING PLATE INSTALLATION			OPTIONAL			-			
<b>MOC :</b>										
SB 525-25-22 R01 25SB-22 : 525R1	GLARESHIELD LEATHER STRAP INSTALLATION			OPTIONAL	MTH 27-Jul-2005 HRS 2036		-			Complete
<b>MOC : COMPLIED WITH</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 525-25-23 R01	THREE FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT) WITH NAVIGATION INTERFACE INSTALLATION			OPTIONAL			A/R			
	<b>MOC :</b>									
SB 525-25-23 25SB-23	THREE FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT) WITH NAVIGATION INTERFACE INSTALLATION			OPTIONAL			A/R			
	<b>MOC :</b>									
SB 525-25-25 25SB-25	TOILET TRAY AND PAD INSTALLATION			SUPERSEDED	MTH		A/R			
	<b>MOC :</b>									
	- SERVICE BULLETIN CANCELLED 08-22-2007.									
SB 525-25-26 25SB-26	PASSENGER SEAT GEAR AND BACKREST LATCH PIN REPLACEMENT			OPTIONAL	MTH		-			
	<b>MOC :</b>									
SB 525-25-34	EQUIPMENT/FURNISHINGS - OPTION FOR LARGER HEADSET HOOK			OPTIONAL			-			
	<b>MOC :</b>									
SB CIB-25-01	EQUIPMENT/FURNISHINGS - PASSENGER SEAT QUICK RELEASE PIN INSTALLATION			OPTIONAL			-			
	<b>MOC :</b>									
SL 525-25-03 25SL-03	LEFT HAND TOILET SEAT BELT INSPECTION/INSTALLATION	GSO		RECOMMENDED	MTH 18-Jan-2000 HRS 460		A/R			Complete
	<b>MOC :</b>									
	COMPLIED WITH									
SL 525-25-05 25SL-05	INSPECTION OF THE BACKREST LATCH PLATES	CHA		MANDATORY	MTH 01-Oct-2010 HRS 2768 LDG 2190		A/R			Complete
	<b>MOC :</b>									
	COMPLIED WITH									
SB 525-26-01 26SB-01	FIRE BOTTLE IDENTIFICATION SLEEVE INSTALLATION			MANDATORY	MTH 18-May-2005 HRS 1983		A/R			Complete
	<b>MOC :</b>									
	COMPLIED WITH									
SL CIL-26-01 R01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING	KCHA		MANDATORY	MTH 20-Sep-2018 HRS 3490.9 LDG 2902		-			N/A
	<b>MOC :</b>									
	NOT APPLICABLE - NOTE TO ANALYST: CARTRIDGES WERE REPLACED AND THIS SL IS NO LONGER APPLICABLE BY DATE RANGE. CARTRIDGE MFG DATE 7/30/18.									
SL CIL-26-01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING			MANDATORY	MTH		-			
	<b>MOC :</b>									
COM MC 525-009	HYDRAULIC FIREWALL SHUTOFF VALVES			INFORMATIONAL			-			
	<b>MOC :</b>									
SB 525-27-11 R02 27SB-11 : 525R2	STEEP APPROACH CERTIFICATION-SPEED BRAKE SWITCH ADJUSTMENT	*CF		OPTIONAL	MTH		-			
	<b>MOC :</b>									
SB 525-27-15 R01 27SB-15 : 525R1	FLAP OVERRIDE SWITCH INSTALLATION	GSO		RECOMMENDED	MTH 02-Nov-2003 HRS 1539		-			Complete
	<b>MOC :</b>									
	COMPLIED WITH									



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 525-27-17 27SB-17	ELECTRIC ELEVATOR TRIM PRINTED CIRCUIT BOARD REPLACEMENT			MANDATORY	MTH 21-Apr-2004 HRS 1705		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 525-27-18 27SB-18	ELEVATOR TRIM POINTER IMPROVEMENT			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 525-27-19 R02 27SB-19	ELEVATOR TRIM CABLE THICKNESS CHANGE AND VERTICAL STABILIZER CABLE FAIRLEAD INSTALLATION	KCHA		MANDATORY	MTH 24-Aug-2017 HRS 3403.3 LDG 2815 ACH 2023.8		A/R			
<b>MOC : DECLINED - CUSTOMER DOES NOT WISH TO COMPLY WITH AT THIS TIME.</b>										
SB 525-27-20 27SB-20	ELEVATOR TRIM POINTER ASSEMBLY IMPROVEMENT			OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SB 525-27-26 R01 27SB-26	FLIGHT CONTROLS - TAILCONE STRINGER FAIRLEAD INSTALLATION			RECOMMENDED	MTH		-			
<b>MOC :</b>										
SB 525-27-28 27SB-28	FLIGHT CONTROLS - ELEVATOR TRIM WHEEL INSPECTION			RECOMMENDED	MTH		-			
<b>MOC :</b>										
ASL 525-27-02 27SLA02	ELECTRIC ELEVATOR TRIM RUNAWAY PROCEDURE	GSO		MANDATORY	MTH 02-Nov-2003 HRS 1539		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB CAS1480 ISSUE A	TAMARACK ATLAS ENHANCEMENTS IMPLEMENTATION	KSZT		MANDATORY	MTH 11-May-2021 HRS 3664.5 LDG 3139		-			Complete
<b>MOC : COMPLIED WITH - THIS AIRCRAFT HAS COMPLIED WITH SERVICE BULLETIN SB1480 BY COMPLYING WITH SBATLAS-57-03 AND SBATLAS-57-05 (REFERENCE ITEMS 7, 8, 12, &amp; 13 OF THIS MTR FOR MORE DETAILS).</b>										
SL 525-27-01 27SL-01	ELEVATOR ELECTRIC TRIM TAB ACTUATOR MOUNT INSPECTION	GSO		RECOMMENDED	MTH 07-Mar-2003 HRS 1377		-			Complete
<b>MOC : COMPLIED WITH</b>										
SL 525-27-04 R01 27SL-04 : 525R1	FLAP PUSHROD SAFETY WIRE INSPECTION	CHA		RECOMMENDED	MTH 02-Dec-2010 HRS 2773.2 LDG 2197		300			Complete
<b>MOC : COMPLIED WITH</b>										
SL 525-27-09 27SL-09	FLIGHT CONTROLS - SPEED BRAKE ACTUATOR SCREW REPLACEMENT			OPTIONAL			-			
<b>MOC :</b>										
SB 525-28-10 28SB-10	FUEL CROSSFEED TO FUEL TRANSFER MODIFICATION			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 525-28-11 R01 28SB-11 : 525R1	WING FUEL BOOST PUMP WIRE ROUTING IMPROVEMENT	CHA		MANDATORY	MTH 02-Oct-2006 HRS 2284		A/R			N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE</b>										
SB 525-28-12 R01 28SB-12 : 525R1	WING FUEL BOOST PUMP WIRING IMPROVEMENT	MCO		MANDATORY	MTH 28-Jan-2006 HRS 2138		-			Complete
<b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH.</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-28-01	FUEL - MICROBIOLOGICAL CONTAMINATION IN AIRCRAFT FUEL TANKS AND FUEL SYSTEMS									
	<b>MOC :</b>									
SB 525-29-09 29SB-09	HYDRAULIC LINE IMPROVEMENT	GSO		MANDATORY	MTH 13-Dec-2000 HRS 741					Complete
	<b>MOC :</b> COMPLIED WITH									
SB 525-29-10 29SB-10	SOLENOID LOADING VALVE REPLACEMENT	GSO		RECOMMENDED	MTH 07-Mar-2003 HRS 1377					Complete
	<b>MOC :</b> COMPLIED WITH									
SB 525-29-11 R02 29SB-11 : 525R2	HYDRAULIC RELIEF VALVE INSPECTION			CANCELLED	MTH HRS		36 1200			
	SERVICE BULLETIN CANCELLED.									
	<b>MOC :</b>									
SB 525-29-14 R01	HYDRAULIC POWER - HYDRAULIC RELIEF VALVE STAKING IMPROVEMENT	KCHA		MANDATORY	MTH 06-Jun-2014 HRS 3106.3 LDG 2519		A/R			Complete
	<b>MOC :</b> COMPLIED WITH - C/W SB 525-29-14 R1 BY INSPECTION. REMOVED AND REPLACED THE RELIEF VALVE WITH NEW VALVE P/N 9912423-46 S/N 1472A WAS INSTALLED. P/N 9912423-12 S/N 306 WAS REMOVED. OPERATION AND LEAK CHECK WAS SATISFACTORY. NO FURTHER ACTION REQUIRED.									
SB 525-29-15	HYDRAULIC POWER - STAINLESS STEEL TUBE ASSEMBLY INSTALLATION			OPTIONAL			A/R			
	<b>MOC :</b>									
SB 525-30-06 30SB-06	WING ANTI-ICE OVER TEMPERATURE SWITCH WIRING IMPROVEMENT	GSO		RECOMMENDED	MTH 18-Jan-2000 HRS 460					Complete
	<b>MOC :</b> COMPLIED WITH									
SB 525-30-07 R02 30SB-07 : 525R2	WING ANTI-ICE OVERTEMPERATURE SWITCH RELOCATION			OPTIONAL	MTH		A/R			
	<b>MOC :</b>									
SL CIL-30-01 R01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES									
	<b>MOC :</b>									
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION									
	<b>MOC :</b>									
SB 525-32-17 R01 32SB-17 : 525R1	BRAKE LINE REPLACEMENT	SAT		RECOMMENDED	MTH 22-Aug-2002 HRS 1220					Complete
	<b>MOC :</b> COMPLIED WITH									
SB 525-32-20 R01 32SB-20 : 525R1	BRAKE LINE REPLACEMENT & RELOCATION	GSO		RECOMMENDED	MTH 13-Dec-2000 HRS 741					Complete
	<b>MOC :</b> COMPLIED WITH									
SB 525-32-22 32SB-22	EMERGENCY GEAR RELEASE BRACKET CLEARANCE IMPROVEMENT	GSO		RECOMMENDED	MTH 28-Sep-2001 HRS 951		A/R			Complete
	<b>MOC :</b> COMPLIED WITH									
SB 525-32-25 32SB-25	BEARING REPLACEMENT	GSO		MANDATORY	MTH 27-Jul-2005 HRS 2036		A/R			N/A
	<b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE									



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
ASL 525-32-21 32SLA21	TRANSMITTAL OF GOODRICH SERVICE BULLETIN 2-1559-32-4, MAIN LANDING GEAR - BRAKE ASSEMBLY - P/N 2-1559-1 AND 2-1559-2 - CESSNA CITATION AIRCRAFT - INTRODUCTION OF A NEW BRAKE ASSEMBLY P/N 2-1559-3	CHA		MANDATORY	MTH 15-Jun-2010 HRS 2752.6 LDG 2175		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SL CIL-32-01	LANDING GEAR - IMPROVED NOSE WHEEL GREASE SEAL			INFORMATIONAL			-			
	<b>MOC :</b>									
SL CIL-32-03	NLG UPLOCK ROLLER BRACKET INSPECTION	KCHA		RECOMMENDED	MTH 09-Jan-2015 HRS 3179.7 LDG 2584		-			Complete
	<b>MOC : COMPLIED WITH - C/W CITATION SERVICE LETTER CIL-32-03, INSPECTION FOUND THE UP-LOCK ROLLER BRACKET INSTALLED CORRECTLY. NO FURTHER ACTION NEED AT THIS TIME.</b>									
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION			INFORMATIONAL			-			
	<b>MOC :</b>									
SL CIL-32-06	LANDING GEAR - WIRELESS TIRE PRESSURE SENSOR FILL VALVE TORQUE VERIFICATION			INFORMATIONAL			-			
	<b>MOC :</b>									
SL 525-32-15 32SL-15	NOSE LANDING GEAR TIRE INSPECTION	GSO		MANDATORY	MTH 03-Jun-2002 HRS 1141 LDG 779		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 525-32-17 R01 32SL-17 : 525R1	NOSE LANDING GEAR ICE PROTECTION BOOT INSTALLATION			OPTIONAL	MTH		-			
	<b>MOC :</b>									
SL 525-32-19 32SL-19	TRANSMITTAL OF GOODRICH SERVICE LETTER 2056	CHA		RECOMMENDED	MTH 01-Oct-2010 HRS 2768 LDG 2190		150			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 525-32-20 32SL-20	MAIN LANDING GEAR DOOR PUSHROD SAFETY WIRE INSPECTION	CHA		RECOMMENDED	MTH 02-Dec-2010 HRS 2773.2 LDG 2197		300			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 525-32-23 R02	EMERGENCY GEAR RELEASE INSPECTION	CHA		MANDATORY	MTH 02-Dec-2010 HRS 2773.2 LDG 2197		-			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 525-32-23 32SL-23	EMERGENCY GEAR RELEASE INSPECTION			MANDATORY	MTH		A/R			
	<b>MUST BE ACCOMPLISHED IN CONJUNCTION WITH INSPECTION DOCUMENT 10.</b>									
	<b>MOC :</b>									
SL 525-32-27	LANDING GEAR - MAIN LANDING GEAR REPAIR			INFORMATIONAL			-			
	<b>MOC :</b>									
SB 525-33-07 33SB-07	CHART LIGHT MODIFICATION			OPTIONAL	MTH		-			
	<b>MOC :</b>									
SB 525-33-10	LIGHTS - WING TIP LED LIGHT MODIFICATION			OPTIONAL			-			
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-33-01	TRANSMITTAL OF RADIANT POWER CORP. SB-RPC-001, PROCEDURE TO REPLACE OBSOLETE CONNECTOR ASSEMBLY FOR CBS28 EMERGENCY BATTERY	INFORMATIONAL			-			
<b>MOC :</b>								
SB 525-34-30 34SB-30	ART-2000-6 RADAR MODIFICATION GSO	RECOMMENDED	MTH 26-Jun-1999 HRS 301		A/R			Complete
<b>MOC :</b> COMPLIED WITH								
SB 525-34-35 34SB-35	BRNAV INCORPORATION	OPTIONAL	MTH		-			
<b>MOC :</b>								
SB 525-34-36 34SB-36	UNS-1K W/604.0 SOFTWARE UPGRADE GSO	RECOMMENDED	MTH 13-Dec-2000 HRS 741		-			Complete
<b>MOC :</b> COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED								
SB 525-34-38 R01 34SB-38 : 525R1	SHADIN ADC-200 FUEL/AIR DATA COMPUTER GSO	RECOMMENDED	MTH 28-Sep-2001 HRS 951		-			Complete
<b>MOC :</b> COMPLIED WITH								
SB 525-34-39 34SB-39	GNS-XLS SOFTWARE MOD 4 UPGRADE GSO	RECOMMENDED	MTH 26-Jun-1999 HRS 301		A/R			Complete
<b>MOC :</b> COMPLIED WITH								
SB 525-34-41 R01 34SB-41 : 525R1	REDUCED VERTICAL SEPARATION (RVSM) OPERATION MODIFICATION BTL	OPTIONAL	MTH 23-Jan-2003 HRS 1347		A/R			Complete
<b>MOC :</b> COMPLIED WITH								
SB 525-34-46 34SB-46	UNIVERSAL AVIONICS FLAT PANEL CONTROL DISPLAY UNIT UPGRADE TO MOD 8 GSO	MANDATORY	MTH 07-Mar-2003 HRS 1377		-			Complete
<b>MOC :</b> COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED								
SB 525-34-61 34SB-61	MST-67A TRANSPONDER INSTALLATION	OPTIONAL	MTH		-			
<b>MOC :</b>								
SB 525-34-62 R01 34SB-62 : 525R1	GARMIN RADIO INSTALLATION	OPTIONAL	MTH		A/R			
<b>MOC :</b>								
SB 525-34-84 R03	NAVIGATION - COLLINS FMS-3000 WIDE AREA AUGMENTATION SYSTEM (WAAS) WITH FMS 4.0 SOFTWARE UPDATES OPTIONAL				-			
<b>MOC :</b>								
ASL 525-34-13 34SLA13	FLAT PANEL CONTROL DISPLAY UNIT INVERTER CIRCUITRY INTEGRITY TEST GSO	MANDATORY	MTH 28-Sep-2001 HRS 951		-			Complete
<b>MOC :</b> COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED								
SL 525-34-08 34SL-08	TRANSMITTAL OF BFGOODRICH ALERT SERVICE BULLETIN 78A GSO	MANDATORY	MTH 05-Feb-1999 HRS 153		A/R			Complete
<b>MOC :</b> COMPLIED WITH - NOT APPLICABLE								
SL 525-34-09 34SL-09	TRANSMITTAL OF BF GOODRICH ALERT SERVICE BULLETIN #79 GSO	MANDATORY	MTH 18-Jan-2000 HRS 460		A/R			Complete
<b>MOC :</b> COMPLIED WITH								



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 525-34-10 <i>34SL-10</i>	GNS-XLS FMS MOD 7 SFTWRE UPGR	GSO		RECOMMENDED	MTH 07-Mar-2003 HRS 1377		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL 525-34-14 R01 <i>34SL-14 : 525R1</i>	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN IN 182A-16 RADAR INDICATOR	GSO		RECOMMENDED	MTH 02-Nov-2003 HRS 1539		-			Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>										
SL 525-34-40	NAVIGATION - TRANSMITTAL OF UNIVERSAL AVIONICS SERVICE BULLETIN NUMBER 3116.(.)-34-3771 INSTALLATION OF MOD 9 IN THE UNS-1LW FMS			RECOMMENDED	MTH		-			
<b>MOC :</b>										
SLA 525-34-04 <i>34SLA04</i>	KLN89B,KLN90B & KLN900 GPS INSTRUMENT LANDING SYSTEM APPROACH RESTRICTIONS	GSO		MANDATORY	MTH 05-Feb-1999 HRS 153		-			Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE</b>										
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001	KCHA		MANDATORY	MTH 30-Mar-2016 DAYS 3310.5 HRS 2715 LDG		-			N/A
<b>MOC : NOT APPLICABLE - INSPECTED BOTH OXYGEN MASK AND FOUND THEM TO BE NOT APPLICABLE PER THERE P/N &amp; S/N.</b>										
SL 525-35-02 <i>35SL-02</i>	PORTABLE OXYGEN CYLINDER MASK INSPECTION/REPLACEMENT	GSO		RECOMMENDED	MTH 18-Jul-2001 HRS 903		-			Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>										
SL 525-35-05	OXYGEN - OXYGEN BOTTLE INSPECTION				MTH		A/R			
<b>MOC :</b>										
SL 525-35-06 R01	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240			MANDATORY			-			
<b>MOC :</b>										
SL 525-35-06 R02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240	KCHA		MANDATORY	MTH 06-Jun-2014 HRS 3106.3 LDG 2519		-			N/A
<b>MOC : NOT APPLICABLE - C/W SL 525-35-06 R2 I/A/W INTERCHANGE SB MXH-35-240. FOUND N/A BY DATE CODE. PILOTS DATE CODE 0017-SAND CO-PILOTS DATE CODE 0642S. NO FURTHER ACTION REQUIRED.</b>										
SB 525-36-04 R01 <i>36SB-04 : 525R1</i>	PRECOOLER IMPROVEMENT			DISCRETIONARY	MTH		A/R			
<b>MOC :</b>										
SB 525-36-04 R02	PRECOOLER IMPROVEMENT			DISCRETIONARY			-			
<b>MOC :</b>										
SB 525-36-04 R03	PNEUMATIC - PRECOOLER IMPROVEMENT			DISCRETIONARY			-			
<b>MOC :</b>										
COM MC 525-008	LIFE LIMITED PRECOOLERS						-			
<b>MOC :</b>										
SL 525-36-01 R01 LEFT <i>36SL-01 : L</i>	PRECOOLER INSPECTION MODEL 525	CHA		RECOMMENDED	MTH 01-Oct-2010 HRS 2768 LDG 2190		300			Complete
<b>MOC : COMPLIED WITH</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 525-36-01 R01 RIGHT 36SL-01 : R	PRECOOLER INSPECTION CHA			RECOMMENDED	MTH 01-Oct-2010 HRS 2768 LDG 2190		300			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 525-52-05 R01 52SB-05 : 525R1	DOOR SEAL VALVE REPLACEMENT *CF			OPTIONAL	MTH		-			
	<b>MOC :</b>									
SB 525-52-07 52SB-07	TAILCONE BAGGAGE DOOR UPPER DOOR LATCH DRAIN OPTIONAL				MTH		-			
	<b>MOC :</b>									
SB 525-52-08 R01 52SB-08 : 525R1	IMPROVEMENT FOR THE CABIN ENTRY STEPS OPTIONAL				MTH		A/R			
	<b>MOC :</b>									
SB 525-52-09 R01	CABIN ENTRY DOOR HANDLE POSITION SWITCH INSTALLATION OPTIONAL						A/R			
	<b>MOC :</b>									
ASL 525-52-01 52SLA01	EMERGENCY DOOR INSPECTION CHA			MANDATORY	MTH 11-May-2008 HRS 2555		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SL CIL-52-01	DOORS - EMERGENCY DOOR INSPECTION KCHA			MANDATORY	MTH 06-Jun-2014 HRS 3106.3 LDG 2519		-			Complete
	<b>MOC : COMPLIED WITH - C/W SL CIL -52-01 BY INSPECTION AND LUBRICATION OF THE EMERGENCY EXIT DOOR SEAL. OPERATION OF DOOR WAS NORMAL.</b>									
SL CIL-52-02	DOORS - EMERGENCY EXIT DOOR INSPECTION INFORMATIONAL						-			
	<b>MOC :</b>									
SL CIL-52-03	DOORS - EMERGENCY ESCAPE HATCH INSPECTION UNK			MANDATORY	MTH 09-Nov-2021 HRS 3722.1 LDG 3186		-			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 525-53-07 R02 53SB-07 : 525R2	AFT BAGGAGE SECTION SKI OPTION INSTALLATION OPTIONAL				MTH		-			
	<b>MOC :</b>									
SB 525-53-17 R01 53SB-17 : 525R1	NOSE WHEEL STEER BRACKET REPLACEMENT GSO			MANDATORY	MTH 18-Jul-2001 HRS 903		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 525-53-17 53SB-17	NOSE WHEEL STEERING BRACKET REPLACEMENT GSO			MANDATORY	MTH 18-Jan-2000 HRS 460		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 525-53-18 53SB-18	RIVET INSPECTION/INSTALLATION GSO			RECOMMENDED	MTH 28-Sep-2001 HRS 951		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 525-53-20 R01 53SB-20 : 525R1	DISABLE THE COCKPIT MOUNTED RELIEF TUBE(S) CHA			MANDATORY	MTH 11-May-2008 HRS 2555		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
ASL 525-53-03 R01 53SLA03 : 525R1	RELIEF TUBE CORROSION STOP ALL USE OF THE COCKPIT MOUNTED RELIEF TUBE.			MANDATORY	MTH		BF/F BF/F			
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl Part Serial No		C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
ASL 525-53-04 <i>53SLA04</i>	RELIEF TUBE CORROSION INSPECTION MCO MANDATORY		MTH 02-May-2007 HRS 2391		A/R			Complete
<b>MOC :</b> COMPLIED WITH								
SL 525-53-05 <i>53SL-05</i>	INTERCOSTAL DRAINAGE PATH INSPECTION KCHA RECOMMENDED		MTH 06-Jun-2014 HRS 3106.3 LDG 2519		300			Complete
<b>MOC :</b> COMPLIED WITH - C/W SL525-52-05 BY INSPECTION, NO RIVET IN TOOLING HOLE.								
SL 525-53-06	UPPER TAILCONE SKIN INSPECTION CHA MANDATORY		MTH 02-Dec-2010 HRS 2773.2 LDG 2197		A/R			Complete
<b>MOC :</b> COMPLIED WITH								
SL 525-53-07	ACCESS PANEL DRAIN HOLE INSTALLATION KCHA RECOMMENDED		MTH 04-Aug-2016 HRS 3349.2 LDG 2758 ACH 1974.2		-			Complete
<b>MOC :</b> COMPLIED WITH - C/W CITATION SERVICE LETTER SL 525-53-07 ACCESS PANEL DRAIN HOLE INSTALLATION I/A/W SERVICE LETTER INSTRUCTIONS. NEW DRAIN HOLES DRILL INACCESS PANEL.								
SB 525-54-04 R01 <i>54SB-04 : 525R1</i>	FIREWALL BOX REPAIR MCO RECOMMENDED		MTH 28-Jan-2006 HRS 2138		-			Complete
<b>MOC :</b> COMPLIED WITH - -								
SB 525-54-04 R02	NACELLES/PYLONS - FIREWALL BOX REPAIR RECOMMENDED				A/R			
<b>MOC :</b>								
SB 525-54-05	NACELLES/PYLONS - MID FIREWALL FASTENER INSPECTION MCO MANDATORY		MTH 20-Oct-2011 HRS 2841.1 LDG 2255		A/R			Complete
<b>MOC :</b> COMPLIED WITH								
SB 525-57-10 R01 <i>57SB-10 : 525R1</i>	SKID PLATE CAP ADDITION ICT RECOMMENDED		MTH 24-Nov-1999 HRS 427		-			Complete
<b>MOC :</b> COMPLIED WITH								
SB 525-57-12 <i>57SB-12</i>	LEADING EDGE TUBE REPLACEMENT SAT RECOMMENDED		MTH 22-Aug-2002 HRS 1220		-			Complete
<b>MOC :</b> COMPLIED WITH								
SB ATLAS-57-06 ISS A	AFMS UPDATE - PRE-FLIGHT CHECK AND ADDITION OF LEFT-HAND TACS VISIBILITY PLACARDS DAB MANDATORY		MTH 13-Dec-2023 HRS 3957.5 LDG 3335		-			Complete
<b>MOC :</b> COMPLIED WITH - C/W ATLAS SERVICE BULLETIN SBATLAS-57-06 INSTRUCTIONS BY INSTALLING DECALS PROVIDED IN KIT A/C OK FOR SERVICE FLIGHT MANUAL AMENDMENT C/W								
SL 525-57-02 <i>57SL-02</i>	ACCESS DOOR DRAINAGE IMPROVEMENT CHA RECOMMENDED		MTH 26-Jan-2007 HRS 2356		-			Complete
<b>MOC :</b> COMPLIED WITH								
SL WI-70-1008-CN E1	CANCELLED - STANDARD PRACTICES - CONSUMABLE MATERIALS LIST - REVISION TO LINE MAINTENANCE MANUAL CANCELLED				-			
<b>MOC :</b>								
SL WI-70-1008-CN E2	CANCELLED - STANDARD PRACTICES - CONSUMABLE MATERIALS LIST - REVISION TO LINE MAINTENANCE MANUAL CANCELLED				-			
<b>MOC :</b>								



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL WI-70-1008 E1	STANDARD PRACTICES - CONSUMABLE MATERIALS LIST - REVISION TO LINE MAINTENANCE MANUAL									-
	<b>MOC :</b>									
SL WI-70-1008 E2	STANDARD PRACTICES - CONSUMABLE MATERIALS LIST - REVISION TO LINE MAINTENANCE MANUAL									-
	<b>MOC :</b>									
SL WI-70-1010-CN E1	CANCELLED - STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED						-
	<b>MOC :</b>									
SL WI-70-1010-CN E2	CANCELLED - STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED						-
	<b>MOC :</b>									
SL WI-70-1010 E1	STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL									-
	<b>MOC :</b>									
SL WI-70-1010 E2	STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL									-
	<b>MOC :</b>									
SL WI-70-1011-CN E1	CANCELLED - STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED						-
	<b>MOC :</b>									
SL WI-70-1011-CN E2	CANCELLED - STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED						-
	<b>MOC :</b>									
SL WI-70-1011 E1	STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL									-
	<b>MOC :</b>									
SL WI-70-1011 E2	STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL									-
	<b>MOC :</b>									
SB FJ44-71-006-CN E1	CANCELLED - ENGINE - COMPRESSOR SECTION INSPECTION (CSI) - NOTIFICATION			CANCELLED						-
	<b>MOC :</b>									
SB FJ44-71-006-CN E2	CANCELLED - ENGINE - COMPRESSOR SECTION INSPECTION (CSI) - NOTIFICATION			CANCELLED						-
	<b>MOC :</b>									
SL 44-71-153 E1	ENGINE - VOLCANIC ASH - CONTAMINATION / TROUBLESHOOTING									-
	<b>MOC :</b>									
SL 44-71-153 E2	ENGINE - VOLCANIC ASH - CONTAMINATION / TROUBLESHOOTING									-
	<b>MOC :</b>									
SL WI-71-1064-CN E1	CANCELED - POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL			CANCELLED						-
	<b>MOC :</b>									
SL WI-71-1064-CN E2	CANCELED - POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL			CANCELLED						-
	<b>MOC :</b>									
SL WI-71-1064 E1	POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL									-
	<b>MOC :</b>									
SL WI-71-1064 E2	POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL									-
	<b>MOC :</b>									
SL WI-71-1129 E1	CANCELED - POWER PLANT - BIT NO. 50 FAULT TROUBLESHOOTING - REVISION TO MAINTENANCE MANUAL			CANCELLED						-
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL WI-71-1129 E2	CANCELED - POWER PLANT - BIT NO. 50 FAULT TROUBLESHOOTING - REVISION TO MAINTENANCE MANUAL			CANCELLED			-			
	<b>MOC :</b>									
SL WI-71-1606 E1	POWER PLANT - IDLE SPEED AND LEAK CHECK RUN - REVISION TO LINE MAINTENANCE MANUAL						-			
	<b>MOC :</b>									
SL WI-71-1606 E2	POWER PLANT - IDLE SPEED AND LEAK CHECK RUN - REVISION TO LINE MAINTENANCE MANUAL						-			
	<b>MOC :</b>									
SL 525-72-06 72SL-06	TRANSMITTAL OF WILLIAMS ROLLS SERVICE LETTER SL44-72-72 GEARBOX CARBON SEALS-MAINTENANCE REQUIREMENTS	GSO		MANDATORY	MTH 26-Jun-1999 HRS 301		-			Complete
	<b>MOC :</b> COMPLIED WITH									
SL 525-72-09 72SL-09	TRANSMITTAL OF WILLIAMS ROLLS SERVICE BULLETIN FJ44-72-052, ENGINE-IP COMPRESSOR ROTOR-REPLACE	BTL		MANDATORY	MTH 23-Jan-2003 HRS 1347		-			Complete
	<b>MOC :</b> COMPLIED WITH									
SB FJ44-05-002 R02 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	<b>MOC :</b>									
SB FJ44-05-002 R02 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	<b>MOC :</b>									
SB FJ44-05-002 R03 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	<b>MOC :</b>									
SB FJ44-05-002 R03 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	<b>MOC :</b>									
SB FJ44-72-014 R01-CN E1	COMPLETED - FCW - ENGINE - FRONT INNER BYPASS DUCT FAIRING - INSPECTION AND REPLACEMENT			RECOMMENDED			-			
	<b>MOC :</b>									
SB FJ44-72-014 R01-CN E2	COMPLETED - FCW - ENGINE - FRONT INNER BYPASS DUCT FAIRING - INSPECTION AND REPLACEMENT			RECOMMENDED			-			
	<b>MOC :</b>									
SB FJ44-72-022 R01 E1	REPAIR RIGHT-HAND SERVICE ADAPTER INSERT OF FRONT BYPASS DUCT			RECOMMENDED			-			
	<b>MOC :</b>									
SB FJ44-72-022 R01 E2	REPAIR RIGHT-HAND SERVICE ADAPTER INSERT OF FRONT BYPASS DUCT			RECOMMENDED			-			
	<b>MOC :</b>									
SB FJ44-72-022 R02-CN E1	CANCELED - ENGINE - FRONT BYPASS DUCT - REPAIR RIGHT HAND SERVICE ADAPTER INSERT			CANCELLED			-			
	<b>MOC :</b>									
SB FJ44-72-022 R02-CN E2	CANCELED - ENGINE - FRONT BYPASS DUCT - REPAIR RIGHT HAND SERVICE ADAPTER INSERT			CANCELLED			-			
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-022 R02 E1	FRONT BYPASS DUCT - REPAIR RIGHT-HAND SERVICE ADAPTER INSERT			RECOMMENDED			-			
<b>MOC :</b>										
SB FJ44-72-022 R02 E2	FRONT BYPASS DUCT - REPAIR RIGHT-HAND SERVICE ADAPTER INSERT			RECOMMENDED			-			
<b>MOC :</b>										
SB FJ44-72-027-CNFCW E1	ENGINE - GEARBOX ASSY - INSPECT OF BREATHER PORT MAGNETIC CARBON SEAL & REWORK OF BREATHER TUBE			RECOMMENDED			-			
<b>MOC :</b>										
SB FJ44-72-027-CNFCW E2	ENGINE - GEARBOX ASSY - INSPECT OF BREATHER PORT MAGNETIC CARBON SEAL & REWORK OF BREATHER TUBE			RECOMMENDED			-			
<b>MOC :</b>										
SB FJ44-72-039 R03 E1	ENGINE HP COMPRESSOR ROTOR REWORK BACKWALL (SUPERSEDED BY FJ44-72-039 R04)			RECOMMENDED			-			
<b>MOC :</b>										
SB FJ44-72-039 R03 E2	ENGINE HP COMPRESSOR ROTOR REWORK BACKWALL (SUPERSEDED BY FJ44-72-039 R04)			RECOMMENDED			-			
<b>MOC :</b>										
SB FJ44-72-039 R04 E1	HP COMPRESSOR ROTOR - REWORK BACKWALL (SUPERSEDED BY FJ44-72-039 R05)			RECOMMENDED			-			
<b>MOC :</b>										
SB FJ44-72-039 R04 E2	HP COMPRESSOR ROTOR - REWORK BACKWALL (SUPERSEDED BY FJ44-72-039 R05)			RECOMMENDED			-			
<b>MOC :</b>										
SB FJ44-72-039 R05 E1	HP COMPRESSOR ROTOR - REWORK BACKWALL	UNK		RECOMMENDED	MTH 09-May-2019 HRS 3537.4 LDG 2951		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB FJ44-72-039 R05 E2	HP COMPRESSOR ROTOR - REWORK BACKWALL	UNK		RECOMMENDED	MTH 07-May-2019 HRS 3537.4 LDG 2951		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB FJ44-72-051 R03 E1	REWORK NAMEPLATE (SUPERSEDED BY FJ44-72-051 R04)			RECOMMENDED			-			
<b>MOC :</b>										
SB FJ44-72-051 R03 E2	REWORK NAMEPLATE (SUPERSEDED BY FJ44-72-051 R04)			RECOMMENDED			-			
<b>MOC :</b>										
SB FJ44-72-051 R04 E1	REWORK NAMEPLATE	UNK		RECOMMENDED	MTH 09-May-2019 HRS 3537.4 LDG 2951		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB FJ44-72-051 R04 E2	REWORK NAMEPLATE			RECOMMENDED			-			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-051 R05 E1	NAMEPLATE - REWORK			RECOMMENDED			-			
<b>MOC :</b>										
SB FJ44-72-051 R05 E2	NAMEPLATE - REWORK			RECOMMENDED	MTH HRS		MPI MPI MPI		5537.4	1397.7
<b>MOC :</b>										
SB FJ44-72-054 R04 E1	ENGINE - GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER (SUPERSEDED BY FJ44-72-054 R05)			RECOMMENDED			-			
<b>MOC :</b>										
SB FJ44-72-054 R04 E2	ENGINE - GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER (SUPERSEDED BY FJ44-72-054 R05)			RECOMMENDED			-			
<b>MOC :</b>										
SB FJ44-72-054 R05 E1	ENGINE - GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER (SUPERSEDED BY FJ44-72-054 R06)			RECOMMENDED			-			
<b>MOC :</b>										
SB FJ44-72-054 R05 E2	ENGINE - GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER (SUPERSEDED BY FJ44-72-054 R06)			RECOMMENDED			-			
<b>MOC :</b>										
SB FJ44-72-054 R06 E1	GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER	UNK		RECOMMENDED	MTH HRS LDG	09-May-2019 3537.4 2946	-			Complete
<b>MOC : COMPLIED WITH</b>										
SB FJ44-72-054 R06 E2	GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER	UNK		RECOMMENDED	MTH HRS LDG	07-May-2019 3537.4 2946	-			Complete
<b>MOC : COMPLIED WITH - PREVIOUSLY</b>										
SB FJ44-72-054 R07 E1	GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER			RECOMMENDED			-			
<b>MOC :</b>										
SB FJ44-72-054 R07 E2	GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER			RECOMMENDED			-			
<b>MOC :</b>										
SB FJ44-72-076 R01 E1	IP COMPRESSOR STATOR - REWORK	UNK		OPTIONAL	MTH HRS LDG	09-May-2019 3537.4 2951	-			Complete
<b>MOC : COMPLIED WITH</b>										
SB FJ44-72-076 R01 E2	IP COMPRESSOR STATOR - REWORK	UNK		OPTIONAL	MTH HRS LDG	07-May-2019 3537.4 2951	-			Complete
<b>MOC : COMPLIED WITH</b>										
SB FJ44-72-076 R02 E1	IP COMPRESSOR STATOR - REWORK			OPTIONAL			-			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-076 R02 E2	IP COMPRESSOR STATOR - REWORK			OPTIONAL			-			
<b>MOC :</b>										
SB FJ44-72-076 E1	REWORK - ENGINE- COMPRESSOR STATOR (SUPERSEDED BY FJ44-72-076 R01)			OPTIONAL			-			
<b>MOC :</b>										
SB FJ44-72-076 E2	REWORK - ENGINE- COMPRESSOR STATOR (SUPERSEDED BY FJ44-72-076 R01)			OPTIONAL			-			
<b>MOC :</b>										
SB FJ44-72-079 R02 E1	CANCELLED - ENGINE - MPI - TIME EXTENSION FOR TAP ENGINES			CANCELLED			-			
<b>MOC :</b>										
SB FJ44-72-079 R02 E2	CANCELLED - ENGINE - MPI - TIME EXTENSION FOR TAP ENGINES			CANCELLED			-			
<b>MOC :</b>										
SB FJ44-72-083 R04 E1	ENGINE- UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-083 R05)	KCHA		OPTIONAL	MTH 15-Aug-2016 HRS 3361.5 LDG 2766		-			Complete
<b>MOC :</b> COMPLIED WITH - C/W SB FJ44-72-083 AT REV 5 BY REPLACING THE GEAR BOX ASSY. WORK PERFORMED BY DUNCAN AVIATION CRS# JGVR194F UNDER DUNCAN W/O YY1E. GROUNDOPERATION AND LEAK CHECK WAS NORMAL. P/N OFF 60178 S/N OFF WL01956 INSTALLED MODIFIED GEAR BOX P/N 115283 INSTALLED S/N WL01502 WITH TOTAL HRS 6568.6TOTAL CYC 5846.										
SB FJ44-72-083 R04 E2	ENGINE- UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-083 R05)	KCHA		OPTIONAL	MTH 15-Aug-2016 HRS 3361.5 LDG 2766		-			Complete
<b>MOC :</b> COMPLIED WITH - C/W SB FJ44-72-083 AT REV 5 BY INSTALLATION OF A MODIFIED GEAR BOX. REMOVED P/N 69110 S/N WL01938 AND INSTALLED P/N 115283 S/N WL01935 MODIFIED BYWILLIAMS INT. CRS # W15R335J UNDER THEIR W/O 400213199 FORM TRACKING # 400213199 DATED 02 MARCH 2016. GEAR BOX REPLACEMENT PERFORMED BY DUNCANAVIATION CRS# JGVR194F UNDER THEIR W/O# YY1E. INSTALLED GEAR BOX TOTAL HRS. 2477.2 TOTAL CYCLES 1792. GROUND OPERATION AND LEAK CHECK WAS NORMAL.										
SB FJ44-72-083 R05 E1	UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-083 R06)	KCHA		OPTIONAL	MTH 15-Aug-2016 HRS 3361.5 LDG 2766		-			Complete
<b>MOC :</b> COMPLIED WITH - C/W SB FJ44-72-083 R5 C/W BY REPLACEMENT OF THE GEARBOX ASSY. WORK PERFORMED BY DUNCAN AVIATION CRS#JGVR194F. REMOVED GEAR BOX ASSY P/N69110 S/N WL01956 INSTALLED MODIFIED GEAR BOX P/N 115283 S/N WL01502 GEAR BOX TOTAL HRS. 6568.6 TOTAL CYCLES 5846. GROUND OPERATION AND LEAK CHECK WASNORMAL.										
SB FJ44-72-083 R05 E2	UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-083 R06)	KCHA		OPTIONAL	MTH 15-Aug-2016 HRS 3361.5 LDG 2766		-			Complete
<b>MOC :</b> COMPLIED WITH - C/W SB FJ44-72-083 R5 BY INSTALLATION OF A MODIFIED GEAR BOX ASSY. GEAR BOX MODIFIED BY WILLIAMS INT. CRS# W15R335J UNDER THEIR W/O 400213199FORM TRACKING # 400213199 DATED 02 MAR 2016. REMOVED GEAR BOX P/N 69110 S/N WL01938 AND INSTALLED MODIFIED GEAR BOX P/N 115283 S/N WL01935. GEAR BOXREPLACEMENT PERFORMED BY DUNCAN AVIATION CRS# JGVR194F UNDER THEIR W/O YY1E. GROUND OPERATION AND LEAK CHECK WAS NORMAL.										
SB FJ44-72-083 R06 E1	UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION	UNK		OPTIONAL	MTH 09-May-2019 HRS 3537.4 LDG 2946		-			Complete
<b>MOC :</b> COMPLIED WITH										



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-083 R06 E2	UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION	UNK		OPTIONAL	MTH 07-May-2019 HRS 3537.4 LDG 2946		-			Complete
<b>MOC : COMPLIED WITH - PREVIOUSLY</b>										
SB FJ44-72-087 R04 E1	ENGINE - BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-087 R05)			OPTIONAL			-			
<b>MOC :</b>										
SB FJ44-72-087 R04 E2	ENGINE - BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-087 R05)			OPTIONAL			-			
<b>MOC :</b>										
SB FJ44-72-087 R05 E1	BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY SB WISB-72-1011 R01)			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB FJ44-72-087 R05 E2	BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY SB WISB-72-1011 R01)			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB FJ44-72-099 R01 E1	ENGINE - 6 BOLT SPINNER - REPLACE (SUPERSEDED BY FJ44-72-099 R02)			RECOMMENDED			-			
<b>MOC :</b>										
SB FJ44-72-099 R01 E2	ENGINE - 6 BOLT SPINNER - REPLACE (SUPERSEDED BY FJ44-72-099 R02)			RECOMMENDED			-			
<b>MOC :</b>										
SB FJ44-72-099 R02 E1	6 BOLT SPINNER - REPLACE (SUPERSEDED BY FJ44-72-099 R03)			RECOMMENDED			-			
<b>MOC :</b>										
SB FJ44-72-099 R02 E2	6 BOLT SPINNER - REPLACE (SUPERSEDED BY FJ44-72-099 R03)			RECOMMENDED			-			
<b>MOC :</b>										
SB FJ44-72-099 R03 E1	6 BOLT SPINNER - REPLACE (SUPERSEDED BY FJ44-72-099 R04)			RECOMMENDED			-			
<b>MOC :</b>										
SB FJ44-72-099 R03 E2	6 BOLT SPINNER - REPLACE (SUPERSEDED BY FJ44-72-099 R04)			RECOMMENDED			-			
<b>MOC :</b>										
SB FJ44-72-099 R04 E1	6 BOLT SPINNER - REPLACE	UNK		RECOMMENDED	MTH 09-May-2019 HRS 3537.4 LDG 2946		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB FJ44-72-099 R04 E2	6 BOLT SPINNER - REPLACE	UNK		RECOMMENDED	MTH 07-May-2019 HRS 3537.4 LDG 2946		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB FJ44-72-108 R01-CN E1	SUPERSEDED - ACCESSORY DRIVE SHAFT - REPLACE (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE)			CANCELLED			-			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-108 R01-CN E2	SUPERSEDED - ACCESSORY DRIVE SHAFT - REPLACE (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE) CANCELLED									
<b>MOC :</b>										
SB FJ44-72-108 R01 E1	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY SB WISB-72-1037 R01)	UNK		RECOMMENDED	MTH 09-May-2019 HRS 3537.4 LDG 2951					Complete
<b>MOC : COMPLIED WITH</b>										
SB FJ44-72-108 R01 E2	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY SB WISB-72-1037 R01)	UNK		RECOMMENDED	MTH 07-May-2019 HRS 3537.4 LDG 2951					Complete
<b>MOC : COMPLIED WITH</b>										
SB FJ44-72-108 E1	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-108 R01)			RECOMMENDED						
<b>MOC :</b>										
SB FJ44-72-108 E2	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-108 R01)			RECOMMENDED						
<b>MOC :</b>										
SB FJ44-72-109 E1	ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE	UNK		RECOMMENDED	MTH 09-May-2019 HRS 3537.4 LDG 2951					Complete
<b>MOC : COMPLIED WITH</b>										
SB FJ44-72-109 E2	ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE	UNK		RECOMMENDED	MTH 07-May-2019 HRS 3537.4 LDG 2951					Complete
<b>MOC : COMPLIED WITH</b>										
SB FJ44-72-111 R01 E1	ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION (SUPERSEDED BY FJ44-72-111 R02)			RECOMMENDED						
<b>MOC :</b>										
SB FJ44-72-111 R01 E2	ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION (SUPERSEDED BY FJ44-72-111 R02)			RECOMMENDED						
<b>MOC :</b>										
SB FJ44-72-111 R02 E1	ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION	UNK		RECOMMENDED	MTH 09-May-2019 HRS 3537.4 LDG 2946					Complete
<b>MOC : COMPLIED WITH</b>										
SB FJ44-72-111 R02 E2	ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION	UNK		RECOMMENDED	MTH 07-May-2019 HRS 3537.4 LDG 2946					Complete
<b>MOC : COMPLIED WITH - PREVIOUSLY</b>										
SB FJ44-72-111 E1	ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION (SUPERSEDED BY FJ44-72-111 R01)			RECOMMENDED						
<b>MOC :</b>										
SB FJ44-72-111 E2	ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION (SUPERSEDED BY FJ44-72-111 R01)			RECOMMENDED						
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-112 E1	CANCELLED - ENGINE - ROUTINE PERIODIC INSPECTION - TIME EXTENSION			CANCELLED			-			
	<b>MOC :</b>									
SB FJ44-72-112 E2	CANCELLED - ENGINE - ROUTINE PERIODIC INSPECTION - TIME EXTENSION			CANCELLED			-			
	<b>MOC :</b>									
SB FJ44-72-123 R01 E1	CANCELLED - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE			CANCELLED			-			
	<b>MOC :</b>									
SB FJ44-72-123 R01 E2	CANCELLED - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE			CANCELLED			-			
	<b>MOC :</b>									
SB FJ44-72-129 R01-CN E1	CANCELLED - ENGINE - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE			CANCELLED			-			
	<b>MOC :</b>									
SB FJ44-72-129 R01-CN E2	CANCELLED - ENGINE - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE			CANCELLED			-			
	<b>MOC :</b>									
SB FJ44-72-130 R01 E1	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R02)			RECOMMENDED			-			
	<b>MOC :</b>									
SB FJ44-72-130 R01 E2	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R02)			RECOMMENDED			-			
	<b>MOC :</b>									
SB FJ44-72-130 R02 E1	HP COMPRESSOR ROTOR - INSPECTION	UNK		RECOMMENDED	MTH 09-May-2019 HRS 3537.4 LDG 2951		-			Complete
	<b>MOC :</b>									
SB FJ44-72-130 R02 E2	HP COMPRESSOR ROTOR - INSPECTION	UNK		RECOMMENDED	MTH 07-May-2019 HRS 3537.4 LDG 2951		-			Complete
	<b>MOC :</b>									
SB FJ44-72-130 E1	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R01)			RECOMMENDED			-			
	<b>MOC :</b>									
SB FJ44-72-130 E2	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R01)			RECOMMENDED			-			
	<b>MOC :</b>									
SB FJ44-72-145 R03 E1	GEARBOX ASSEMBLY - INSTALL WASHER & SPRING CARTRIDGE ASSEMBLY				MTH		-			
	<b>MOC :</b>									
SB FJ44-72-145 R03 E2	GEARBOX ASSEMBLY - INSTALL WASHER & SPRING CARTRIDGE ASSEMBLY				MTH		-			
	<b>MOC :</b>									
SB FJ44-72-147 R01 E1	DIFFUSER CASE ASSEMBLY - INSPECTION			RECOMMENDED			-			
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
SB FJ44-72-147 R01 E2	DIFFUSER CASE ASSEMBLY - INSPECTION				-			
		RECOMMENDED						
	<b>MOC :</b>							
SB FJ44-72-147 R02 E1	DIFFUSER CASE ASSEMBLY - INSPECTION				-			
		RECOMMENDED						
	<b>MOC :</b>							
SB FJ44-72-147 R02 E2	DIFFUSER CASE ASSEMBLY - INSPECTION				-			
		RECOMMENDED						
	<b>MOC :</b>							
SB FJ44-72-147 E1	DIFFUSER CASE ASSEMBLY - INSPECTION UNK	RECOMMENDED	MTH 09-May-2019 HRS 3537.4 LDG 2951		-			Complete
	<b>MOC :</b> COMPLIED WITH							
SB FJ44-72-147 E2	DIFFUSER CASE ASSEMBLY - INSPECTION UNK	RECOMMENDED	MTH 07-May-2019 HRS 3537.4 LDG 2951		-			Complete
	<b>MOC :</b> COMPLIED WITH							
SB FJ44-72-149 R01 E1	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE	RECOMMENDED			-			
	<b>MOC :</b>							
SB FJ44-72-149 R01 E2	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE	RECOMMENDED			-			
	<b>MOC :</b>							
SB FJ44-72-149 R02 E1	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE	RECOMMENDED	MTH		-			
	<b>MOC :</b>							
SB FJ44-72-149 R02 E2	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE	RECOMMENDED	MTH		-			
	<b>MOC :</b>							
SB FJ44-72-149 R03 E1	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE	RECOMMENDED	HRS		MPI		5537.4	1397.7
	<b>MOC :</b>							
SB FJ44-72-149 R03 E2	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE	RECOMMENDED	HRS		MPI		5537.4	1397.7
	<b>MOC :</b>							
SB FJ44-72-149 E1	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE UNK	RECOMMENDED	MTH 09-May-2019 HRS 3537.4 LDG 2946		-			Complete
	<b>MOC :</b> COMPLIED WITH							
SB FJ44-72-149 E2	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE UNK	RECOMMENDED	MTH 07-May-2019 HRS 3537.4 LDG 2946		-			Complete
	<b>MOC :</b> COMPLIED WITH							
SB FJ44-72-16-CN E1	CANCELLED-REAR BYPASS DUCT AND TAILPIPE-APPLY CANCELLED				-			
	<b>MOC :</b>							



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-16-CN E2	CANCELLED-REAR BYPASS DUCT AND TAILPIPE-APPLY CANCELLED				-			
	<b>MOC :</b>							
SL 44-72-325 R06 E1	ENGINE - 1ST LP TURBINE DISK - INSPECTION				-			
	<b>MOC :</b>							
SL 44-72-325 R06 E2	ENGINE - 1ST LP TURBINE DISK - INSPECTION				-			
	<b>MOC :</b>							
SL 44-72-325 R07 E1	1ST LP TURBINE DISK - INSPECTION				-			
	<b>MOC :</b>							
SL 44-72-325 R07 E2	1ST LP TURBINE DISK - INSPECTION				-			
	<b>MOC :</b>							
PSID WI-05-1000 R02 E1	UNSERVICEABLE PARTS - NOTIFICATION	INFORMATIONAL			-			
	<b>MOC :</b>							
PSID WI-05-1000 R02 E2	UNSERVICEABLE PARTS - NOTIFICATION	INFORMATIONAL			-			
	<b>MOC :</b>							
PSID WI-05-1000 R03 E1	UNSERVICEABLE PARTS - NOTIFICATION	INFORMATIONAL			-			
	<b>MOC :</b>							
PSID WI-05-1000 R03 E2	UNSERVICEABLE PARTS - NOTIFICATION	INFORMATIONAL			-			
	<b>MOC :</b>							
PSID WI-72-1022 R01 E1	OPERATING IN AREAS OF SMOKE				-			
	<b>MOC :</b>							
PSID WI-72-1022 R01 E2	OPERATING IN AREAS OF SMOKE				-			
	<b>MOC :</b>							
PSID WI-72-1026 E1	FAN CASE - RUB INDICATIONS				-			
	<b>MOC :</b>							
PSID WI-72-1026 E2	FAN CASE - RUB INDICATIONS				-			
	<b>MOC :</b>							
SB WI-72-1011 R01 E1	BLEED VALVE ASSEMBLY - UPGRADE	OPTIONAL			-			
	<b>MOC :</b>							
SB WI-72-1011 R01 E2	BLEED VALVE ASSEMBLY - UPGRADE	OPTIONAL			-			
	<b>MOC :</b>							
SB WI-72-1011 E1	BLEED VALVE ASSEMBLY - UPGRADE UNK	OPTIONAL	MTH 09-May-2019 HRS 3537.4 LDG 2946		-			Complete
	<b>MOC :</b> COMPLIED WITH							



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB WI-72-1011 E2	BLEED VALVE ASSEMBLY - UPGRADE UNK			OPTIONAL MTH	07-May-2019 HRS 3537.4 LDG 2946		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB WI-72-1037 R01 E1	ACCESSORY DRIVE TOWERSHAFT - REPLACE			RECOMMENDED			-			
<b>MOC :</b>										
SB WI-72-1037 R01 E2	ACCESSORY DRIVE TOWERSHAFT - REPLACE			RECOMMENDED			-			
<b>MOC :</b>										
SB WI-72-1037 R02 E1	ACCESSORY DRIVE TOWERSHAFT - REPLACE			MTH			-			
<b>MOC :</b>										
SB WI-72-1037 R02 E2	ACCESSORY DRIVE TOWERSHAFT - REPLACE			MTH			-			
<b>MOC :</b>										
SB WI-72-1037 R03 E1	ACCESSORY DRIVE TOWERSHAFT - REPLACE						-			
<b>MOC :</b>										
SB WI-72-1037 R03 E2	ACCESSORY DRIVE TOWERSHAFT - REPLACE						-			
<b>MOC :</b>										
SB WI-72-1037 R04 E1	ACCESSORY DRIVE TOWERSHAFT - REPLACE						-			
<b>MOC :</b>										
SB WI-72-1037 R04 E2	ACCESSORY DRIVE TOWERSHAFT - REPLACE						-			
<b>MOC :</b>										
SB WI-72-1037 R05 E1	ACCESSORY DRIVE TOWERSHAFT - REPLACE			RECOMMENDED	MTH		CSI	CSI		
<b>MOC :</b>										
SB WI-72-1037 R05 E2	ACCESSORY DRIVE TOWERSHAFT - REPLACE			RECOMMENDED	MTH		CSI	CSI		
<b>MOC :</b>										
SB WI-72-1041 R01 E1	HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE			RECOMMENDED			-			
<b>MOC :</b>										
SB WI-72-1041 R01 E2	HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE			RECOMMENDED			-			
<b>MOC :</b>										
SB WI-72-1041 R02 E1	HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE			MTH			-			
<b>MOC :</b>										
SB WI-72-1041 R02 E2	HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE			MTH			-			
<b>MOC :</b>										
SB WI-72-1041 R03 E1	HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE						-			
<b>MOC :</b>										
SB WI-72-1041 R03 E2	HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE						-			
<b>MOC :</b>										
SB WI-72-1041 R04 E1	HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE			RECOMMENDED			MPI			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
SB WI-72-1041 E2	R04 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE						MPI			
	<b>MOC :</b>			RECOMMENDED						
SB WI-72-1041 E1	HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE						-			
	<b>MOC :</b>			RECOMMENDED						
SB WI-72-1041 E2	HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE						-			
	<b>MOC :</b>			RECOMMENDED						
SB WI-72-1044 E1	R01 BALANCE PISTON - REPLACE						-			
	<b>MOC :</b>									
SB WI-72-1044 E2	R01 BALANCE PISTON - REPLACE						-			
	<b>MOC :</b>									
SB WI-72-1044 E1	R02 BALANCE PISTON - REPLACE						-			
	<b>MOC :</b>									
SB WI-72-1044 E2	R02 BALANCE PISTON - REPLACE						-			
	<b>MOC :</b>									
SB WI-72-1044 E1	R03 BALANCE PISTON - REPLACE						CSI			
	<b>MOC :</b>			RECOMMENDED						
SB WI-72-1044 E2	R03 BALANCE PISTON - REPLACE						CSI			
	<b>MOC :</b>			RECOMMENDED						
SB WI-72-1044 E1	ENGINE - BALANCE PISTON - REPLACE				MTH		-			
	<b>MOC :</b>									
SB WI-72-1044 E2	ENGINE - BALANCE PISTON - REPLACE				MTH		-			
	<b>MOC :</b>									
SB WI-72-1068 E1	R01 6 BOLT SPINNER - REPLACE				RECOMMENDED	MTH	-			
	<b>MOC :</b>				RECOMMENDED					
SB WI-72-1068 E2	R01 6 BOLT SPINNER - REPLACE				RECOMMENDED	MTH	-			
	<b>MOC :</b>				RECOMMENDED					
SB WI-72-1068 E1	6 BOLT SPINNER - REPLACE				RECOMMENDED	MTH	-			
	<b>MOC :</b>				RECOMMENDED					
SB WI-72-1068 E2	6 BOLT SPINNER - REPLACE				RECOMMENDED	MTH	-			
	<b>MOC :</b>				RECOMMENDED					
SL WI-72-1080 E1	VISUALLY INSPECT THE 2ND LP TURBINE NOZZLE ASSEMBLY - REVISION TO ENGINE MANUAL						-			
	<b>MOC :</b>									
SL WI-72-1080 E2	VISUALLY INSPECT THE 2ND LP TURBINE NOZZLE ASSEMBLY - REVISION TO ENGINE MANUAL						-			
	<b>MOC :</b>									
SL WI-72-1128 E1	FAN ROTOR - REVISION TO LINE MAINTENANCE MANUAL						-			
	<b>MOC :</b>									
SL WI-72-1128 E2	FAN ROTOR - REVISION TO LINE MAINTENANCE MANUAL						-			
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL WI-72-1132-CN E1	CANCELED - ENGINE - APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	<b>MOC :</b>									
SL WI-72-1132-CN E2	CANCELED - ENGINE - APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	<b>MOC :</b>									
SL WI-72-1132 E1	APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL						-			
	<b>MOC :</b>									
SL WI-72-1132 E2	APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL						-			
	<b>MOC :</b>									
SL WI-72-1140 E1	INDUCTION HEATING - REVISION TO ENGINE MANUAL						-			
	<b>MOC :</b>									
SL WI-72-1140 E2	INDUCTION HEATING - REVISION TO ENGINE MANUAL						-			
	<b>MOC :</b>									
SL WI-72-1262-CN E1	CANCELED - ENGINE - APPROVED ENGINE FUEL - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	<b>MOC :</b>									
SL WI-72-1262-CN E2	CANCELED - ENGINE - APPROVED ENGINE FUEL - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	<b>MOC :</b>									
SL WI-72-1262 E1	APPROVED ENGINE FUEL - REVISION TO LINE MAINTENANCE MANUAL						-			
	<b>MOC :</b>									
SL WI-72-1262 E2	APPROVED ENGINE FUEL - REVISION TO LINE MAINTENANCE MANUAL						-			
	<b>MOC :</b>									
SL WI-72-1332-CN E1	CANCELED - FAN ROTOR - INSPECTION/CHECK - REVISION TO LINE MAINTENANCE MANUALS			CANCELLED			-			
	<b>MOC :</b>									
SL WI-72-1332-CN E2	CANCELED - FAN ROTOR - INSPECTION/CHECK - REVISION TO LINE MAINTENANCE MANUALS			CANCELLED			-			
	<b>MOC :</b>									
SL WI-72-1418 E1	REAR HOUSING ASSEMBLY - REVISION TO ENGINE MANUAL						-			
	<b>MOC :</b>									
SL WI-72-1418 E2	REAR HOUSING ASSEMBLY - REVISION TO ENGINE MANUAL						-			
	<b>MOC :</b>									
ASL 525-73-06 RT ENG 73ASL06 : E2**R	TRANSMITTAL OF WILLIAMS-ROLLS ALERT SERVICE BULLETIN FJ44-A73-12 ENGINE FUEL CONTROL UNION-TO-OIL COOLER FUEL TUBE ASSEMBLY - REPLACE	GSO		RECOMMENDED	MTH 18-Jan-2000 HRS 460		A/R			Complete
	<b>MOC :</b> COMPLIED WITH									
ASL 525-73-06L 73ASL06 : E1**L	TRANSMITTAL OF WILLIAMS-ROLLS ALERT SERVICE BULLETIN FJ44-A73-12 ENGINE FUEL CONTROL UNION-TO-OIL COOLER FUEL TUBE ASSEMBLY - REPLACE	GSO		RECOMMENDED	MTH 18-Jan-2000 HRS 460		-			Complete
	<b>MOC :</b> COMPLIED WITH									
SB FJ44-73-062 R01 E1	ENGINE FUEL AND CONTROL - FUEL FLOW TO OIL COOLER TUBE ASSEMBLY - REPLACE	UNK		RECOMMENDED	MTH 09-May-2019 HRS 3537.4 LDG 2946		-			Complete
	<b>MOC :</b> COMPLIED WITH									



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-73-062 R01 E2	ENGINE FUEL AND CONTROL - FUEL FLOW TO OIL COOLER TUBE ASSEMBLY - REPLACE	UNK		RECOMMENDED	MTH 07-May-2019 HRS 3537.4 LDG 2946		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB FJ44-73-062 E1	ENGINE FUEL AND CONTROL - FUEL FLOW TO OIL COOLER TUBE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-73-062 R01)			RECOMMENDED			-			
<b>MOC :</b>										
SB FJ44-73-062 E2	ENGINE FUEL AND CONTROL - FUEL FLOW TO OIL COOLER TUBE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-73-062 R01)			RECOMMENDED			-			
<b>MOC :</b>										
SB FJ44-73-9-CN E1	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE)						-			
<b>MOC :</b>										
SB FJ44-73-9-CN E2	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE)						-			
<b>MOC :</b>										
SB WI-73-1000 R01 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE	UNK		RECOMMENDED	MTH 09-May-2019 HRS 3537.4 LDG 2946		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB WI-73-1000 R01 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE	UNK		RECOMMENDED	MTH 07-May-2019 HRS 3537.4 LDG 2946		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB WI-73-1000 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			RECOMMENDED			-			
<b>MOC :</b>										
SB WI-73-1000 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			RECOMMENDED			-			
<b>MOC :</b>										
SB WI-74-1001 E1	IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT	UNK		MANDATORY	MTH 09-May-2019 HRS 3537.4 LDG 2951		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB WI-74-1001 E2	IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT	UNK		MANDATORY	MTH 07-May-2019 HRS 3537.4 LDG 2951		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB WI-75-1002 R01 E1	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE	UNK		RECOMMENDED	MTH 09-May-2019 HRS 3537.4 LDG 2951		-			Complete
<b>MOC : COMPLIED WITH</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB WI-75-1002 R01 E2	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE	UNK		RECOMMENDED	MTH 07-May-2019 HRS 3537.4 LDG 2951		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB WI-75-1002 R02 E1	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED			-			
<b>MOC :</b>										
SB WI-75-1002 R02 E2	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED			-			
<b>MOC :</b>										
SB WI-75-1002 E1	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED			-			
<b>MOC :</b>										
SB WI-75-1002 E2	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED			-			
<b>MOC :</b>										
SB 525-76-04 R01 76SB-04 : 525R1	FORWARD THROTTLE CABLE REPLACEMENT *CF			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 525-76-05 R01 76SB-05 : 525R1	ENGINE POWER CONTROL CABLE REPLACEMENT			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 525-76-06 76SB-06	SAFE FLIGHT N1 COMPUTER INSTALLATION			OPTIONAL	MTH		-			
<b>MOC :</b>										
SL WI-76-1001-CN E1	CANCELED - ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL			CANCELLED			-			
<b>MOC :</b>										
SL WI-76-1001-CN E2	CANCELED - ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL			CANCELLED			-			
<b>MOC :</b>										
SL WI-76-1001 E1	ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL						-			
<b>MOC :</b>										
SL WI-76-1001 E2	ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL						-			
<b>MOC :</b>										
SB FJ44-77-008 R03 E1	ENGINE INDICATING - REPLACE ITT PROBES WITH MID-LENGTH PROBE HARNESS	UNK		RECOMMENDED	MTH 09-May-2019 HRS 3537.4 LDG 2946		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB FJ44-77-008 R03 E2	ENGINE INDICATING - REPLACE ITT PROBES WITH MID-LENGTH PROBE HARNESS	UNK		RECOMMENDED	MTH 07-May-2019 HRS 3537.4 LDG 2946		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB FJ44-79-011 R01 E1	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R02)			MANDATORY			-			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-79-011 R01 E2	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R02)			MANDATORY			-			
<b>MOC :</b>										
SB FJ44-79-011 R02 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R03)			MANDATORY			-			
<b>MOC :</b>										
SB FJ44-79-011 R02 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R03)			MANDATORY			-			
<b>MOC :</b>										
SB FJ44-79-011 R03 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R04)			MANDATORY			-			
<b>MOC :</b>										
SB FJ44-79-011 R03 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R04)			MANDATORY			-			
<b>MOC :</b>										
SB FJ44-79-011 R04 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE	UNK		MANDATORY	MTH 09-May-2019 HRS 3537.4 LDG 2946		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB FJ44-79-011 R04 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE	UNK		MANDATORY	MTH 07-May-2019 HRS 3537.4 LDG 2946		-			Complete
<b>MOC : COMPLIED WITH - PREVIOUSLY</b>										
SB FJ44-79-011 R05 E1	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE						-			
<b>MOC :</b>										
SB FJ44-79-011 R05 E2	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE						-			
<b>MOC :</b>										
SB FJ44-79-011 R06 E1	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE			MANDATORY			-			
<b>MOC :</b>										
SB FJ44-79-011 R06 E2	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE			MANDATORY			-			
<b>MOC :</b>										
SB FJ44-79-011 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R01)			MANDATORY			-			
<b>MOC :</b>										
SB FJ44-79-011 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R01)			MANDATORY			-			
<b>MOC :</b>										
SB FJ44-79-015 E1	CANCELLED - OIL - LUBE AND SCAVENGE PUMP ASSEMBLY - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO) FOR TOTAL ASSURANCE PROGRAM (TAP)			RECOMMENDED			-			
<b>MOC :</b>										
SB FJ44-79-015 E2	CANCELLED - OIL - LUBE AND SCAVENGE PUMP ASSEMBLY - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO) FOR TOTAL ASSURANCE PROGRAM (TAP)			RECOMMENDED			-			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS									
				CANCELLED			-			
	<b>MOC :</b>									
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS									
				CANCELLED			-			
	<b>MOC :</b>									
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)									
				CANCELLED			-			
	<b>MOC :</b>									
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW									
				CANCELLED			-			
	<b>MOC :</b>									
SL CIL-99-05	MISCELLANEOUS - INSTALLATION OF CESSNA VARIANT PART NUMBERS									
				INFORMATIONAL			-			
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 1998-25-02 34AD-02	APPLIANCE AD - BFGOODRICH SKYWATCH GSO	SKY497 MANDATORY	MTH 05-Feb-1999 HRS 153		A/R			Complete
<b>MOC :</b> COMPLIED WITH - NOT APPLICABLE								
FAA 2013-08-05 PARA (G)	INSPECTION AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON CERTAIN P/N A/C COMPRESSOR MOTORS OR DEACTIVATION OF THE A/C SYSTEM A/C COMPRESSOR HOUR METER KCRG	MANDATORY	DAYS 18-Feb-2020 HRS 3567.1 LDG 2967		-			Complete
<b>MOC :</b> COMPLIED WITH - C/W AD 2013-08-05 (PARA G) BY REPLACING THE AIR CONDITIONING COMPRESSOR CONDENSER MODULE. THE REPLACEMENT MODULE INCLUDES NEW COMPRESSOR MOTOR BRUSHES. NEXT INSPECTION DUE AT 2607.9 HOURS.								
FAA 2013-08-05 PARA (H)	REPLACE AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON CERTAIN P/N A/C COMPRESSOR MOTORS OR DEACTIVATION OF THE A/C SYSTEM THE AIR CONDITIONING COMPRESSOR MOTOR BRUSHES WITH NEW BRUSHES KCRG	MANDATORY	MTH 18-Feb-2020 HRS 3567.1 LDG 2967 ACH 2107.9				2607.9	Complete 367.1
<b>MOC :</b> COMPLIED WITH								
FAA 2013-08-05 PARA (I)	DEACTIVATION AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON CERTAIN P/N A/C COMPRESSOR MOTORS OR DEACTIVATION OF THE A/C SYSTEM OF THE AIR CONDITIONING MANDATORY				A/R			
<b>MOC :</b>								
FAA 2013-08-05 PARA (J)	RETURN AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON CERTAIN P/N A/C COMPRESSOR MOTORS OR DEACTIVATION OF THE A/C SYSTEM OF REPLACED PARTS AND REPORTING REQUIREMENT MANDATORY		DAYS		30			
<b>MOC :</b>								
FAA 2013-08-05	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON CERTAIN P/N A/C COMPRESSOR MOTORS OR DEACTIVATION OF THE A/C SYSTEM KCHA	MANDATORY	MTH 22-Jul-2016 HRS 3347.7 LDG 2756 ACH 1971.5		-			Complete
<b>MOC :</b> COMPLIED WITH - INSTALLED A OVERHAULED MOTOR ASSY P/N 1134104-5 S/N 691 DUE TO MOTOR FAILURE. MOTOR OVERHAULED BY THE MANUFACTURE (ENVIRO SYSTEMS). NEW BRUSHES INSTALLED AT OVERHAUL P/N1251171. OPERATIONAL CHECK WAS SATISFACTORY.								
FAA 1998-25-10 25AD-01	APPLIANCE AD - AIRCRAFT BELTS INC GSO	MANDATORY	MTH 05-Feb-1999 HRS 153		A/R			Complete
<b>MOC :</b> COMPLIED WITH - NOT APPLICABLE								
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2 MANDATORY				-			
<b>MOC :</b>								
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK MANDATORY				-			
<b>MOC :</b>								
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS MANDATORY				-			
<b>MOC :</b>								
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT MANDATORY		MTH		-			
<b>MOC :</b>								



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	KCHA		MTH HRS LDG	20-Sep-2018 3490.9 2902		-			N/A
<b>MOC :</b> NOT APPLICABLE - THIS AD 2017-16-01 IS NOT APPLICABLE, EQUIPMENT (AMERIKING ELT) NOT INSTALLED THIS AIRCRAFT.										
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT	KCHA		MANDATORY MTH HRS LDG	20-Sep-2018 3490.9 2902		-			N/A
<b>MOC :</b> NOT APPLICABLE										
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS	KCHA		MANDATORY MTH HRS LDG	20-Sep-2018 3490.9 2902		-			N/A
<b>MOC :</b> NOT APPLICABLE										
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE	UNK		MANDATORY MTH HRS LDG	09-Nov-2021 3722.1 3186		-			Complete
<b>MOC :</b> COMPLIED WITH										
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE	UNK		MANDATORY MTH HRS LDG	09-Nov-2021 3722.1 3186		-			Complete
<b>MOC :</b> COMPLIED WITH										
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER	UNK		MANDATORY MTH HRS LDG	09-Nov-2021 3722.1 3186		-			Complete
<b>MOC :</b> COMPLIED WITH										
FAA 2021-07-13	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT	UNK		MANDATORY MTH HRS LDG	09-Nov-2021 3722.1 3186		-			Complete
<b>MOC :</b> COMPLIED WITH - BOTH PILOT & CO-PILOT BUCKLE HANDLES HAVE THE BLUE LOGO BUTTON										
FAA 2024-26-02 PARA (G)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE			MANDATORY MTH			6		07-Sep-2025	2 m 28 d
<b>MOC :</b>										
FAA 2024-26-02 PARA (G)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE			MANDATORY MTH			12		07-Mar-2026	8 m 25 d
<b>MOC :</b>										
FAA 2024-26-02 PARA (G)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER			MANDATORY			-			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2024-26-02	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT MANDATORY				-			
<b>MOC :</b>								
FAA 2005-17-11 26AD-01	PREVENT INCORRECT INSTALLATION OF WIRES MCO	MANDATORY	MTH 28-Jan-2006 HRS 2138		A/R			Complete
<b>MOC :</b> COMPLIED WITH - PREVIOUSLY COMPLIED WITH.								
FAA 2003-21-07 27AD-01	ELECTRIC PITCH TRIM FAILURE CAUSING RUN AWAY PITCH TRIM CONDITION, LARGE PITCH MISTRIM AND EXCESSIVE CONTROL FORCES (SUPERSEDED BY FAA AD 2004-14-20) GSO	SUPERSEDED	MTH 02-Nov-2003 HRS 1539		N/A			Complete
<b>MOC :</b> COMPLIED WITH								
FAA 2004-14-20 27AD-02	CORRECT SINGLE POINT FAILURE IN THE ELECTRIC PITCH TRIM SYSTEM GSO	MANDATORY	MTH 08-Oct-2004 HRS 1818		A/R			Complete
<b>MOC :</b> COMPLIED WITH								
FAA 2019-08-13	FLIGHT CONTROLS - MODELS 525, 525A, AND 525B AIRPLANES WITH TAMARACK ACTIVE LOAD ALLEVIATION SYSTEM (ATLAS) WINGLETS INSTALLED IN ACCORDANCE WITH SUPPLEMENTAL TYPE CERTIFICATE (STC) SA03842NY - REVISE THE OPERATING LIMITATIONS SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) TO PROHIBIT FURTHER FLIGHT (SUPERSEDED BY 2020-24-06) MANDATORY				-			
<b>MOC :</b>								
FAA 2020-24-06	FLIGHT CONTROLS - ACTIVE TECHNOLOGY LOAD ALLEVIATING SYSTEM - DEACTIVATION / MODIFICATION - AIRPLANE FLIGHT MANUAL SUPPLEMENT - AMENDMENT KSZT	MANDATORY	MTH 11-May-2021 HRS 3664.5 LDG 3139		-			Complete
<b>MOC :</b> COMPLIED WITH - COMPLIED WITH AD 2020-24-06. REFERENCE ITEM 19 OF THIS MTR FOR MORE DETAILS. NOTE: THIS AD SUPERSEDES AD2019-08-13								
FAA 2024-15-09	GUST LOCK/DAMPER SYSTEM - INSTALL PLACARDS ON THE LEFT-HAND INBOARD EDGE OF THE TAMARACK ACTIVE CAMBER SURFACE (TACS) AND REVISING THE EXISTING AIRPLANE FLIGHT MANUAL (AFM) FOR YOUR AIRPLANE MANDATORY		MTH		6 60		22-Apr-2025 4100.37	-1 m 19 d -39.33 <b>Over Due</b>
<b>MOC :</b>								
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS KEAU	MANDATORY	MTH 20-Jan-2022 HRS 3750.6 LDG 3202		-			N/A
<b>MOC :</b> NOT APPLICABLE - AD 2021-23-12 IS NOT APPLICABLE TO THIS AIRCRAFT.								
FAA 1997-05-03 34AD-01	APPLIANCE AD - ALLIEDSIGNAL GNS-XLS & GNS-XL ICT	SUPERSEDED	MTH 01-Sep-1998 HRS 11		A/R			Complete
<b>MOC :</b> COMPLIED WITH								
FAA 2001-23-17 34AD-04	APPLIANCE AD - GARMIN GNS 430 GSO	MANDATORY	MTH 13-Feb-2002 HRS 1074		A/R			Complete
<b>MOC :</b> COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED								
FAA 2002-20-09 31AD-01	APPLIANCE AD - COLLINS AFD-3010 AFD UNITS GSO	MANDATORY	MTH 07-Mar-2003 HRS 1377		A/R			Complete
<b>MOC :</b> COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED								
FAA 2003-13-08 34AD-05	APPLIANCE AD - TAWS 8000 TERRAIN AWARENESS GSO	MANDATORY	MTH 02-Nov-2003 HRS 1539		A/R			Complete
<b>MOC :</b> COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED								



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2004-08-15 <i>34AD-06</i>	APPLIANCE AD - TAWS 8000 TERRAIN AWARENESS GSO		MANDATORY	MTH 08-Oct-2004 HRS 1818		A/R			Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>									
FAA 2006-16-18 <i>34AD-12</i>	APPLIANCE AD - SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR (TAWS/RMI)	CHA	MANDATORY	MTH 28-Oct-2006 HRS 2297		A/R			N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>									
FAA 2012-02-08	APPLIANCE AD - AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFICALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS	KCHA	MANDATORY	MTH 03-Oct-2012 HRS 2923.6 LDG 2330		-			N/A
<b>MOC : NOT APPLICABLE - THIS AD2012-02-08 WAS RESEARCHED AND FOUND TO BE NOT APPLICABLE TO THIS AIRCRAFT DUE TO EQUIPMENT NOT INSTALLED.</b>									
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION	KCHA	MANDATORY	MTH 01-Oct-2014 HRS 3144.4 LDG 2558		-			N/A
<b>MOC : NOT APPLICABLE - THIS AD 2014-18-01 NOT APPLICABLE TO THIS AIRCRAFT, EQUIPMENT NOT INSTALLED.NO FURTHER ACTION REQUIRED.</b>									
FAA 2015-10-51-E	APPLIANCE/EMERGENCY AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.	KCHA	MANDATORY	MTH 30-Mar-2016 HRS 3310.5 LDG 2715		-			N/A
<b>MOC : NOT APPLICABLE - THIS AIRCRAFT IS NOT EQUIPPED WITH A AVIDYNE IFD. NOT APPLICABLE.</b>									
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS	KCHA	MANDATORY	MTH 30-Mar-2016 HRS 3310.5 LDG 2715		-			N/A
<b>MOC : NOT APPLICABLE - THIS AIRCRAFT NOT EQUIPPED WITH AVIDYNE IFD. NOT APPLICABLE.</b>									
FAA 1999-08-21 <i>35AD-01</i>	APPLIANCE AD - PURITAN-BENNETT AERO SYSTEM	GSO	MANDATORY	MTH 26-Jun-1999 HRS 301		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011	KCHA	MANDATORY	MTH 30-Mar-2016 HRS 3310.5 LDG 2715		-			N/A
<b>MOC : NOT APPLICABLE - INSPECTED BOTH MASK AND FOUND BOTH NOT APPLICABLE PER THERE P/N'S AND S/N'S. NO FURTHER ACTION REQUIRED.</b>									
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPERGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES	KCHA	MANDATORY	MTH 30-Mar-2016 HRS 3310.5 LDG 2715		-			N/A
<b>MOC : NOT APPLICABLE - INSPECTED BOTH MASK AND FOUND THEM TO BE NOT APPLICABLE PER THERE P/N'S AND S/N'S. NO FURTHER ACTION REQUIRED.</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSSES	KCHA		MANDATORY	MTH 30-Mar-2016 HRS 3310.5 LDG 2715		-			N/A
<b>MOC :</b> NOT APPLICABLE - INSPECTED BOTH MASK AND FOUND THEM TO BE NOT APPLICABLE PER THERE P/N'S AND S/N'S. NO FURTHER ACTION REQUIRED.										
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER	KCHA		MANDATORY	MTH 30-Mar-2016 DAYS 3310.5 HRS 2715 LDG		-			N/A
<b>MOC :</b> NOT APPLICABLE - INSPECTED BOTH MASK AND FOUND BOTH TO BE NOT APPLICABLE PER THERE P/N'S AND S/N'S.										
FAA 2015-23-09 PARA (H.1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).	KCHA		MANDATORY	MTH 30-Mar-2016 DAYS 3310.5 HRS 2715 LDG		-			N/A
<b>MOC :</b> NOT APPLICABLE - INSPECTED BOTH OXYGEN MASK FOUND BOTH TO BE NOT APPLICABLE PER THERE P/N'S AND S/N'S. NO FURTHER ACTION REQUIRED.										
FAA 2015-23-09 PARA (H.2.I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1	KCHA		MANDATORY	MTH 30-Mar-2016 DAYS 3310.5 HRS 2715 LDG		-			N/A
<b>MOC :</b> NOT APPLICABLE - INSPECTED BOTH OXYGEN MASK AND FOUND TO BE NOT APPLICABLE PER THERE P/N'S AND S/N'S. NO FURTHER ACTION REQUIRED.										
FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	KCHA		MANDATORY	MTH 30-Mar-2016 DAYS 3310.5 HRS 2715 LDG		-			N/A
<b>MOC :</b> NOT APPLICABLE - INSPECTED BOTH OXYGEN MASK AND FOUND THEM TO BE NOT APPLICABLE PER THERE P/N'S AND S/N'S. NO FURTHER ACTION REQUIRED.										
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT	KCHA		MANDATORY	MTH 30-Mar-2016 HRS 3310.5 LDG 2715		-			N/A
<b>MOC :</b> NOT APPLICABLE - INSPECTED BOTH OXYGEN MASK AND FOUND THEM TO BE NOT APPLICABLE PER THERE P/N'S AND S/N'S. NO FURTHER ACTION REQUIRED.										
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	KCHA		MANDATORY	MTH 30-Mar-2016 HRS 3310.5 LDG 2715		-			N/A
<b>MOC :</b> NOT APPLICABLE - INSPECTED BOTH OXYGEN MASK AND FOUND THEM TO BE NOT APPLICABLE PER THERE P/N'S AND S/N'S. NO FURTHER ACTION REQUIRED.										
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12	KCHA		MANDATORY	MTH 04-Aug-2016 HRS 3349.2 LDG 2758 ACH 1974.2		-			N/A
<b>MOC :</b> NOT APPLICABLE - THIS AD WAS FOUND TO BE NOT APPLICABLE, NO P/N 119003-11 PBE INSTALLED THIS AIRCRAFT AT THIS TIME.										



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12	KCHA		MANDATORY	MTH 04-Aug-2016 HRS 3349.2 LDG 2758		-			N/A
<b>MOC :</b> NOT APPLICABLE - FOUND THIS AD NOT APPLICABLE, NO P/N 119003-11 PBE IN THIS AIRCRAFT AT THIS TIME.										
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12	KCHA		MANDATORY	MTH 04-Aug-2016 HRS 3349.2 LDG 2758 ACH 1974.2		-			N/A
<b>MOC :</b> NOT APPLICABLE - THIS AD NOT APPLICABLE TO THIS AIRCRAFT, NO P/N 119003-11 PBE IN THIS AIRCRAFT AT THIS TIME.										
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12	KCHA		MANDATORY	MTH 04-Aug-2016 HRS 3349.2 LDG 2758 ACH 1974.2		-			N/A
<b>MOC :</b> NOT APPLICABLE - FOUND THIS AD NOT APPLICABLE, NO P/N 119003-11 PBE IN THIS AIRCRAFT AT THIS TIME.										
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	KCHA		MANDATORY	MTH 24-Jan-2018 HRS 3443.5 LDG 2854		-			N/A
<b>MOC :</b> NOT APPLICABLE										
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	KCHA		MANDATORY	MTH 24-Jan-2018 HRS 3443.5 LDG 2854		-			N/A
<b>MOC :</b> NOT APPLICABLE										
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	KCHA		MANDATORY	MTH 24-Jan-2018 HRS 3443.5 LDG 2854 ACH 2047.8		-			N/A
<b>MOC :</b> NOT APPLICABLE - THIS AD WAS DETERMIND TO BE NOT APPLICABLE, NO PBE P/N 119003-21 INSTALLED IN THIS AIRCRAFT. NO FURTHER ACTION REQUIRED.										
FAA 2017-18-12	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES	KCHA		MANDATORY	MTH 24-Jan-2018 HRS 3443.5 LDG 2854		-			N/A
<b>MOC :</b> NOT APPLICABLE										
FAA 2008-03-10 53AD-01	INSPECT THE LOWER WING SKIN STRUCTURE, FORWARD WING SPAR, LOWER FUSELAGE SKIN, FAIRINGS, AND THE EXTERNAL FAIRING FRAMES FOR CORROSION; REPAIR ANY DAMAGE FOUND; APPLY A CORROSION INHIBITIVE SEALANT TO THE FUSELAGE FAIRINGS BEFORE REINSTALLING; AND DISABLE THE COCKPIT MOUNTED PILOT RELIEF TUBE	CHA		MANDATORY	DAYS 15-Jul-2010 HRS 2752.6 LDG 2175		-			Complete
<b>MOC :</b> COMPLIED WITH - FOUND THAT THIS AD HAS BEEN COMPLIED WITH PER CESSNA ASL525-53-04 ON 5-2-2007 AND ASL525-53-20 DISABLING THE RELIEF TUB ASSEMBLE. NO FURTHER ACTION IS REQUIRED.										



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
FAA 1999-07-04	TO PREVENT HIGH PRESSURE TURBINE (HPT) DISK RIM FAILURE (P/N 55291)									
E1		GSO					A/R			Complete
					MTH 26-Jun-1999					
					HRS 301					
					LDG 221					
<b>MOC : COMPLIED WITH</b>										
FAA 1999-07-04	TO PREVENT HIGH PRESSURE TURBINE (HPT) DISK RIM FAILURE (P/N 55291)									
E2		GSO					A/R			Complete
					MTH 26-Jun-1999					
					HRS 301					
					LDG 221					
<b>MOC : COMPLIED WITH</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **RONALD L ANDERSON LLC**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0272**  
 Unit: **0272** Reg No: **N48DR**  
 Airworthiness: **01-Sep-1998**  
 Print Date: **10-Jun-2025 3:36PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 1</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>ENG 2</b>	<b>4139.7</b>	<b>3486</b>	<b>07-Jun-2025</b>	<b>.07</b>
<b>AIR COND</b>	<b>2240.8</b>		<b>07-Jun-2025</b>	<b>0</b>

## Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
24FO-01 525/K <i>24FO-01 : 525/K</i>	44 AMP/HOUR BATTERY FACTORY OPTION	*CF		186K FO	MTH 01-Sep-1998		-			
25FO-01 525/D <i>25FO-01 : 525/D</i>	REFRESH CTR-LH FWD DELUXE(EXCH) FACTORY OPTION	*CF		128D FO	MTH 01-Sep-1998		-			
25FO-06 525 <i>25FO-06 : 525</i>	STANDARD SEATING FACTORY OPTION	*CF		109 FO	MTH 01-Sep-1998		-			
25FO-08 525 <i>25FO-08 : 525</i>	NAVIGATION CHART CASE, LH FACTORY OPTION	*CF		103 FO	MTH 01-Sep-1998		-			
25FO-10 525/Y <i>25FO-10 : 525/Y</i>	DIVIDER, RH AFT W/MIRROR(EXCH) FACTORY OPTION	*CF		120Y FO	MTH 01-Sep-1998		-			
25FO-13 525/F <i>25FO-13 : 525/F</i>	CURTAIN, AFT REMOVABLE(EXCH) FACTORY OPTION	*CF		121F FO	MTH 01-Sep-1998		-			
25FO-18 525/C <i>25FO-18 : 525/C</i>	MONORAIL SUNVISOR(EXCH) FACTORY OPTION	*CF		122C FO	MTH 01-Sep-1998		-			
25FO-37 525/Q <i>25FO-37 : 525/Q</i>	OVERBOARD DRAIN, LH FWD RELIEF TUBE FACTORY OPTION	*CF		131Q FO	MTH 01-Sep-1998		-			
25FO-45 K <i>25FO-45 : K</i>	HEADLINGER-IZIT LEATHER BISQUE FACTORY OPTION	*CF		725K FO	MTH 01-Sep-1998		-			
25FO-59 525/L <i>25FO-59 : 525/L</i>	PILLOWS- HEADREST SLIP COVER FACTORY OPTION	*CF		118L FO	MTH 01-Sep-1998		-			
33FO-03 525/J <i>33FO-03 : 525/J</i>	INDIRECT LIGHTING W/DELUXE REFRESHMENT CENTER FACTORY OPTION	*CF		50J FO	MTH 01-Sep-1998		-			
34FO-03 525/R <i>34FO-03 : 525/R</i>	RADIO ALTIMETER FACTORY OPTION	*CF		672R FO	MTH 01-Sep-1998		-			
34FO-06 525 <i>34FO-06 : 525</i>	ALLIED SIGNAL FMS WITH GPS FACTORY OPTION	*CF		697 FO	MTH 01-Sep-1998		-			
34FO-09 525 <i>34FO-09 : 525</i>	INDEXER-PILOTS AOA FACTORY OPTION	*CF		11A FO	MTH 01-Sep-1998		-			
34FO-11 525/B <i>34FO-11 : 525/B</i>	SHADIN AIR DATA COMPUTER FACTORY OPTION	*CF		698B FO	MTH 01-Sep-1998		-			
34FO-13 <i>34FO-13</i>	VOICE ANNUNCIATOR FACTORY OPTION	*CF		650 FO	MTH 01-Sep-1998		-			
35FO-01 525/F <i>35FO-01 : 525/F</i>	OXY-50 CU FT BOTTLE (EXCH) FACTORY OPTION	*CF		66F FO	MTH 01-Sep-1998		-			
35FO-02 G <i>35FO-02 : G</i>	EROS OXYGEN MASK & GOGGLE INST (EXCH) FACTORY OPTION	*CF		58G FO	MTH 01-Sep-1998		-			
38FO-01 525/C <i>38FO-01 : 525/C</i>	TOILET-FLUSH RH AFT NON-BELT(EXCH) FACTORY OPTION	*CF		130C FO	MTH 01-Sep-1998		-			
73FO-01 525 <i>73FO-01 : 525</i>	ENGINE SYNCHRONIZER FACTORY OPTION	*CF		76 FO	MTH 01-Sep-1998		-			